

序号	报告编号	发布日期	结论	影像资料
1	GX-B1322/21-1-25279~25281	2025. 11. 3	本次共检验电力电缆3条，3条所检项目合格	
2	GX-B1451/20-1-25518	2025. 11. 3	所检项目合格	

3	GX-B1329/21-1-25114~25115	2025. 11. 3	本次共检氧化锌避雷器2组，2组氧化锌避雷器所检项目合格	
4	GX-B1598/24-1-25090	2025. 11. 4	实测钢丝绳有效截面积损失百分比最大为1.89%，小于5%为正常	

5	GX-B1598/24-1-25091	2025. 11. 4	实测钢丝绳有效截面积损失百分比最大为1.58%，小于5%为正常	
6	GX-B1598/24-1-25092	2025. 11. 4	实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常	


7	GX-B1598/24-1-25093	2025. 11. 4	实测钢丝绳有效截面积损失百分比最大为1.30%，小于5%为正常	
8	GX-B1313/21-1-25197~25198	2025. 11. 6	本次共检电力变压器2台，2台电力变压器所检项目合格。	

9	GX-B1621/24-1-25005	2025. 11. 6	所检项目合格。	
10	GX-B1621/24-1-25006	2025. 11. 6	所检项目合格。	

11	GX-B1350/21-1-25037	2025. 11. 6	本次共检接地装置 2处，2处接地装置所 检项目合格。	
12	GX-B1427/21-1-25246	2025. 11. 3	符合标准要求	

13	GX-B1427/21-1-25250	2025. 11. 3	符合标准要求	
14	GX-B1427/21-1-25254	2025. 11. 3	符合标准要求	

15	GX-B1427/21-1-25258	2025. 11. 3	符合标准要求	
16	GX-B1310/21-1-25244	2025. 11. 4	符合标准要求	

17	GX-B1310/21-1-25247	2025. 11. 4	符合标准要求	
18	GX-B1310/21-1-25251	2025. 11. 4	符合标准要求	

19	GX-B1310/21-1-25255	2025. 11. 4	符合标准要求	
20	GX-B1310/21-1-25259	2025. 11. 4	符合标准要求	

21	GX-B1310/21-1-25262	2025. 11. 4	符合标准要求	
22	GX-B1310/21-1-25265	2025. 11. 4	符合标准要求	

23	GX-B1310/21-1-25245	2025. 11. 4	符合标准要求	
24	GX-B1310/21-1-25248	2025. 11. 4	符合标准要求	

25	GX-B1310/21-1-25249	2025. 11. 4	符合标准要求	
26	GX-B1310/21-1-25252	2025. 11. 4	符合标准要求	

27	GX-B1310/21-1-25253	2025. 11. 4	符合标准要求	
28	GX-B1310/21-1-25256	2025. 11. 4	符合标准要求	

29	GX-B1310/21-1-25257	2025. 11. 4	符合标准要求		
30	GX-B1310/21-1-25260	2025. 11. 4	符合标准要求		

31	GX-B1310/21-1-25261	2025. 11. 4	符合标准要求	
32	GX-B1310/21-1-25263	2025. 11. 4	符合标准要求	

33	GX-B1310/21-1-25264	2025. 11. 4	符合标准要求	
34	GX-B1310/21-1-25266	2025. 11. 4	符合标准要求	

35	GX-B1310/21-1-25267	2025. 11. 4	符合标准要求		
----	---------------------	-------------	--------	--	---