

序号	报告编号	发布日期	结论	影像资料
1	GX-B1309/21-2-25021	2025. 11. 3	所检项目合格。	
2	GX-B1500/21-2-25085	2025. 11. 3	综合判定：合格。	

3	GX-B1416/22-2-25013	2025. 11. 3	综合判定：合格。	 A photograph of two workers in a dark tunnel. They are wearing dark blue uniforms with reflective silver stripes and red hard hats. The worker on the right is holding a flashlight, illuminating the scene. The date '2025/10/27' is printed in the bottom right corner of the image.
4	GX-B1416/22-2-25014	2025. 11. 3	综合判定：合格。	 A photograph of two workers in a tunnel. They are wearing blue uniforms and red hard hats. The tunnel is illuminated by overhead lights, and there are various pipes and equipment visible in the background. The date '2025/10/28' is printed in the bottom right corner of the image.

5	GX-B1418/23-2-25018	2025. 11. 7	综合判定：合格		
---	---------------------	-------------	---------	--	---