


序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-6-25402	2025/11/4	符合标准要求	 2025 09 25
2	GX-B1310/21-6-25403	2025/11/4	符合标准要求	 2025 09 25


3	GX-B1310/21-6-25404	2025/11/4	符合标准要求	 A worker wearing a blue uniform, yellow helmet, and safety glasses is kneeling in an industrial environment, holding a handheld electronic device. The background shows various pipes and machinery. A timestamp '2025 09 25' is visible in the bottom right corner of the image.
4	GX-B1310/21-6-25405	2025/11/4	符合标准要求	 A worker wearing a blue uniform, yellow helmet, and safety glasses is operating a red industrial machine. A control panel with a screen is visible above the machine. The background shows a concrete wall and other industrial equipment. A timestamp '2025 09 25' is visible in the bottom right corner of the image.

5	GX-B1310/21-6-25406	2025/11/4	符合标准要求	
6	GX-B1310/21-6-25407	2025/11/4	符合标准要求	

7	GX-B1310/21-6-25408	2025/11/4	符合标准要求		 2025 09 26	
8	GX-B1310/21-6-25409	2025/11/4	符合标准要求		 2025 09 26	

9	GX-B1310/21-6-25410	2025/11/4	符合标准要求	
10	GX-B1310/21-6-25411	2025/11/4	符合标准要求	

11	GX-B1310/21-6-25412	2025/11/4	符合标准要求		 2025 09 27	
12	GX-B1310/21-6-25413	2025/11/4	符合标准要求		 2025 09 27	

13	GX-B1310/21-6-25414	2025/11/4	符合标准要求	
14	GX-B1310/21-6-25415	2025/11/4	符合标准要求	

15	GX-B1310/21-6-25416	2025/11/4	符合标准要求	
16	GX-B1310/21-6-25417	2025/11/4	符合标准要求	

17	GX-B1310/21-6-25418	2025/11/4	符合标准要求	 2025 09 28
18	GX-B1310/21-6-25419	2025/11/4	符合标准要求	 2025 09 28

19	GX-B1310/21-6-25420	2025/11/4	符合标准要求	
20	GX-B1310/21-6-25421	2025/11/4	符合标准要求	


21	GX-B1310/21-6-25422	2025/11/4	符合标准要求	 A worker wearing a yellow hard hat and a blue uniform is working on a rusty metal structure. The worker is using a tool to work on the metal. The date 2025 09 26 is visible in the bottom right corner of the image.
22	GX-B1427/21-6-25103	2025/11/4	符合标准要求	 A worker wearing a yellow hard hat and a blue uniform is working on a rusty metal structure. The worker is using a tool to work on the metal. The date 2025 09 26 is visible in the bottom right corner of the image.

23	GX-B1305/21-6-25019	2025/11/7	综合判定：合格。		
24	GX-B1305/21-6-25020	2025/11/7	综合判定：合格。		

25	GX-B1305/21-6-25021	2025/11/7	综合判定：合格。	 A worker in a blue uniform and yellow hard hat is operating a red and blue industrial machine in a tunnel. The machine has a large red cylindrical component and a blue rectangular component. The worker is holding a small device. The background shows the rough rock walls of the tunnel. A date stamp '2025 09 25' is visible in the bottom right corner of the image.
26	GX-B1305/21-6-25022	2025/11/7	综合判定：合格。	 A worker in a blue uniform and yellow hard hat is operating a control panel in a tunnel. The worker is holding a red tool or device. The background shows the rough rock walls of the tunnel. A date stamp '2025 09 26' is visible in the bottom right corner of the image.

27	GX-B1303/21-6-25020	2025/11/7	综合判定：合格。	 2025.09.25
28	GX-B1303/21-6-25021	2025/11/7	综合判定：合格。	 2025.09.26

29	GX-B1303/21-6-25022	2025/11/7	综合判定：合格。	
30	GX-B1304/21-6-25036	2025/11/7	综合判定：合格。	

31	GX-B1305/21-6-25023	2025/11/7	综合判定：合格。		 2025 09 27
32	GX-B1305/21-6-25024	2025/11/7	综合判定：合格。		 2025 09 24

33	GX-B1305/21-6-25025	2025/11/7	综合判定：合格。	
34	GX-B1305/21-6-25026	2025/11/7	综合判定：合格。	

35	GX-B1305/21-6-25027	2025/11/7	综合判定：合格。	 A worker wearing a red hard hat and a blue uniform with orange safety harness is operating a large green industrial machine in a tunnel. The machine has a large green flywheel. The worker is holding a tablet or clipboard. The background shows the rough rock walls of a tunnel. A timestamp '2025 09 24' is visible in the bottom right corner of the photo.
36	GX-B1305/21-6-25028	2025/11/7	综合判定：合格。	 A worker wearing a red hard hat and a blue uniform is standing next to a large blue industrial machine in a tunnel. The worker is holding a tablet or clipboard. The machine has a large blue flywheel. The background shows the rough rock walls of a tunnel. A timestamp '2025 09 28' is visible in the bottom right corner of the photo.

37	GX-B1305/21-6-25029	2025/11/7	综合判定：合格。	 A worker wearing a blue uniform, a red helmet, and safety glasses is operating a blue and orange tool. The worker is standing in an industrial setting with various equipment and a control panel visible in the background. The date 2025.09.27 is visible in the bottom right corner of the image.
38	GX-B1305/21-6-25030	2025/11/7	综合判定：合格。	 A worker wearing a blue uniform, a red helmet, and safety glasses is standing next to a large green machine. The worker is holding a tool and appears to be inspecting or working on the machine. The background shows an industrial setting with a control panel and other equipment. The date 2025.09.27 is visible in the bottom right corner of the image.

39	GX-B1305/21-6-25031	2025/11/7	综合判定：合格。	
40	GX-B1305/21-6-25037	2025/11/7	综合判定：合格。	

41	GX-B1305/21-6-25038	2025/11/7	综合判定：合格。	
42	GX-B1305/21-6-25039	2025/11/7	综合判定：合格。	

43	GX-B1305/21-6-25040	2025/11/7	综合判定：合格。	 A worker wearing a red hard hat and a blue uniform with orange reflective stripes is operating a green industrial machine in a tunnel. The machine has a large black wheel. The date stamp '2025 9 25' is visible in the bottom right corner of the photo.
44	GX-B1305/21-6-25041	2025/11/7	综合判定：合格。	 A worker wearing a red hard hat and a blue uniform with orange reflective stripes is operating a green industrial machine in a tunnel. The machine has a large black wheel. The date stamp '2025 9 25' is visible in the bottom right corner of the photo.

45	GX-B1328/25-6-25213	2025/11/6	本次共检绝缘手套80只，80只绝缘手套合格。	
46	GX-B1328/25-6-25214	2025/11/6	本次共检全橡胶绝缘胶靴70只，70只全橡胶绝缘胶靴合格。	

47	GX-B1304/21-6-25039	2025. 11. 7	综合判定：合格。	
48	GX-B1304/21-6-25040	2025. 11. 7	综合判定：合格。	