





序号	报告编号	发布日期	结论	影像资料	
36	GX-B1598/24-1-25085	2025. 11. 10	实测钢丝绳有效截面积损失百分比最大为1.90%，小于5%为正常。 。		
37	GX-B1598/24-1-25086	2025. 11. 10	实测钢丝绳有效截面积损失百分比最大为1.74%，小于5%为正常。 。		

38	GX-B1598/24-1-25087	2025. 11. 10	实测钢丝绳有效截面积损失百分比最大为2.40%，小于5%为正常。 。		
39	GX-B1598/24-1-25088	2025. 11. 10	实测钢丝绳有效截面积损失百分比最大为1.73%，小于5%为正常。 。		

40	GX-B1598/24-1-25089	2025. 11. 10	实测钢丝绳有效截面积损失百分比最大为1.80%，小于5%为正常。 。	
41	GX-B1310/21-1-25271	2025. 11. 10	符合标准要求	

42	GX-B1418/23-1-25005	2025. 11. 11	综合判定：合格。	
43	GX-B1310/21-1-25270	2025. 11. 10	符合标准要求	



44	GX-B1451/20-1-25531~2554	2025. 11. 13	本次共检高压开关柜14台，14台高压开关柜所检项目合格	
45	GX-B1451/20-1-25545~25552	2025. 11. 13	本次共检高压开关柜8台，8台高压开关柜所检项目合格	

46	GX-B1310/21-1-25327	2025. 11. 14	符合标准要求		
47	GX-B1310/21-1-25328	2025. 11. 14	符合标准要求		

48	GX-B1310/21-1-25329	2025. 11. 14	符合标准要求	
49	GX-B1310/21-1-25330	2025. 11. 14	符合标准要求	

50	GX-B1310/21-1-25331	2025. 11. 14	符合标准要求	 2025/11/07
51	GX-B1310/21-1-25332	2025. 11. 14	符合标准要求	 2025/11/07

52	GX-B1310/21-1-25333	2025. 11. 14	符合标准要求	
53	GX-B1310/21-1-25334	2025. 11. 14	符合标准要求	



54	GX-B1310/21-1-25292	2025. 11. 13	符合标准要求			
55	GX-B1310/21-1-25293	2025. 11. 13	符合标准要求			





56	GX-B1310/21-1-25294	2025. 11. 13	符合标准要求	
57	GX-B1427/21-1-25295	2025. 11. 13	符合标准要求	

58	GX-B1310/21-1-25296	2025. 11. 13	符合标准要求	
59	GX-B1310/21-1-25297	2025. 11. 13	符合标准要求	

60	GX-B1310/21-1-25298	2025. 11. 13	符合标准要求	
61	GX-B1310/21-1-25299	2025. 11. 13	符合标准要求	

62	GX-B1310/21-1-25300	2025. 11. 13	符合标准要求			
63	GX-B1310/21-1-25301	2025. 11. 13	符合标准要求			

64	GX-B1451/20-1-25553~25573	2025. 11. 14	本次共检高压开关柜21台，21台高压开关柜所检项目合格。	
65	GX-B1322/21-1-25282~25290	2025. 11. 14	本次共检验电力电缆9条，9条所检项目合格	



66	GX-B1322/21-1-25291~25296	2025. 11. 14	本次共检验电力电缆6条，6条所检项目合格	
67	GX-B1328/25-1-25107	2025. 11. 14	本次共检验电器9支，9支验电器合格	





68	GX-B1328/25-1-25108	2025. 11. 14	本次共检绝缘杆6套， 6套绝缘杆合格	 <p>2025. 11. 04</p>
69	GX-B1328/25-1-25109	2025. 11. 14	本次共检携带式接地 和接地短路装置6套， 6套携带式接地和接地 短路装置所检项目合 格	 <p>2025. 11. 04</p>

70	GX-B1329/21-1-25116~25117	2025/11/17	所检项目合格	
71	GX-B1329/21-1-25118~25123	2025/11/17	所检项目合格	

72	GX-B1329/21-1-25124~25125	2025/11/17	所检项目合格	
73	GX-B1451/20-1-25519~25530	2025/11/17	所检项目合格	

74	GX-B1309/21-1-25033	2025/11/17	所检项目合格	
75	GX-B1500/21-1-25121	2025/11/17	综合判定：合格。	




76	GX-B1500/21-1-25122	2025/11/17	综合判定：合格。	
77	GX-B1500/21-1-25123	2025/11/17	综合判定：合格。	

78	GX-B1322/21-1-25297~25304	2025/11/17	所检项目合格	
79	GX-B1322/21-1-25305~25316	2025/11/17	所检项目合格	



80	GX-B1322/21-1-25317~25323	2025/11/17	所检项目合格	
81	GX-B1332/21-1-25073~25090	2025/11/17	所检项目合格	

82	GX-B1350/21-1-25039	2025/11/17	所检项目合格	
83	GX-B1350/21-1-25038	2025. 11. 14	本次共检接地装置10处，10处接地装置所检项目合格	

84	GX-B1328/25-1-25110	2025/11/17	合格	
85	GX-B1328/25-1-25111	2025/11/17	合格	