

序号	报告编号	发布日期	结论	影像资料
48	GX-B1528/20-F-25380~25399	2025.11.4	所检项目合格	 2025年10月02日
49	GX-B1540/20-F-252852~252871	2025.11.10	所检项目合格	 2025年10月02日

50	GX-B1528/20-F-25440~25459	2025.11.4	所检项目合格	
51	GX-B1540/20-F-252412~252431	2025.11.10	所检项目合格	

52	GX-B1528/20-F-25460~25479	2025.11.4	所检项目合格	
53	GX-B1540/20-F-252432~252451	2025.11.10	所检项目合格	

54	GX-B1529/20-F-25418~25447	2025.11.3	所检项目合格	
55	GX-B1528/20-F-25480~25499	2025.11.4	所检项目合格	

56	GX-B1528/20-F-25520~25539	2025.11.4	所检项目合格	
57	GX-B1528/20-F-25500~25519	2025.11.3	所检项目合格	

58	GX-B1528/20-F-25540~25564	2025.11.3	所检项目合格	
59	GX-B1540/20-F-252512~252536	2025.11.5	所检项目合格	

60	GX-B1540/20-F-252492~252511	2025.11.5	所检项目合格	
61	GX-B1540/20-F-252472~252491	2025.11.5	所检项目合格	

62	GX-B1540/20-F-252452~252471	2025.11.5	所检项目合格	
63	GX-B1465/22-F-25147~25148	2025.11.7	所检项目合格	

64	GX-B1466/22-F-25095~25096	2025.11.7	所检项目合格	
65	GX-B1372/22-F-250872	2025.11.11	所检项目合格	

66	GX-B1372/22-F-250894~250902	2025.11.11	所检项目合格	
67	GX-B1475/22-F-25454~25455	2025.11.11	所检项目合格	

68	GX-B1373/21-F-25526	2025.11.11	所检项目合格	
69	GX-B1374/22-F-250929~250931	2025.11.11	所检项目合格	

70	GX-B1540/20-F-253266~253290	2025.11.11	所检项目合格	
71	GX-B1540/20-F-253291~253315	2025.11.11	所检项目合格	

72	GX-B1372/22-F-250915~250916	2025.11.11	所检项目合格	
73	GX-B1601/22-F-250992~250993	2025.11.11	所检项目合格	


74	GX-B1374/22-F-250970~250974	2025.11.11	所检项目合格	
75	GX-B1601/22-F-250995~250997	2025.11.12	所检项目合格	

76	GX-B1528/20-F-25929~25933	2025.11.12	所检项目合格	
77	GX-B1529/20-F-25648~25652	2025.11.12	所检项目合格	

78	GX-B1543/25-F-25256~25260	2025.11.12	所检项目合格	
79	GX-B1592/21-F-25178	2025.11.12	所检项目合格	

80	GX-B1475/22-F-25467~25479	2025.11.12	所检项目合格	
81	GX-B1603/22-F-250365~250367	2025.11.12	所检项目合格	

82	GX-B1373/21-F-25534~25536	2025.11.12	所检项目合格	
83	GX-B1373/21-F-25537~25540	2025.11.12	所检项目合格	

84	GX-B1593/21-F-25487~25493	2025.11.12	所检项目合格	
85	GX-B1465/22-F-25151~25154	2025.11.12	所检项目合格	

86	GX-B1374/22-F-250962~250969	2025.11.12	所检项目合格	
87	GX-B1374/22-F-250903~250906	2025.11.11	所检项目合格	

88	GX-B1528/20-F-25908~25917	2025.11.11	所检项目合格	
89	GX-B1601/22-F-250953~250964	2025.11.11	所检项目合格	

90	GX-B1412/22-F-25044~25045	2025.11.11	所检项目合格	
91	GX-B1409/22-F-25124	2025.11.11	所检项目合格	

92	GX-B1409/22-F-25114~25123	2025.11.11	所检项目合格	
93	GX-B1605/23-F-25419~25421	2025.11.11	所检项目合格	

94	GX-B1606/23-F-25422~25424	2025.11.12	所检项目合格	 2025/10/17
95	GX-B1410/22-F-25725~25726	2025.11.11	所检项目合格	 2025/10/17

96	GX-B1601/22-F-250935~250937	2025.11.11	所检项目合格	
97	GX-B1592/21-F-25169~25170	2025.11.11	所检项目合格	

98	GX-B1372/22-F-250892	2025.11.11	所检项目合格	
99	GX-B1372/22-F-250893	2025.11.11	所检项目合格	

100	GX-B1372/22-F-250882~250891	2025.11.11	所检项目合格	 2025.10.27
101	GX-B1568/22-F-25622~25635	2025.11.11	所检项目合格	 2025年10月22日

102	GX-B1568/22-F-25655~25657	2025.11.11	所检项目合格	 2025.10.24
103	GX-B1374/22-F-250920~250927	2025.11.11	所检项目合格	 2025.10.27

104	GX-B1374/22-F-250928	2025.11.11	所检项目合格	 A photograph showing a technician in a white lab coat with a blue logo on the back, working inside a laboratory fume hood. Several gas cylinders are visible on a rack inside the hood. A digital display on the left shows '100.00'. The date '2025.10.27' is printed in the bottom right corner of the image.
105	GX-B1605/23-F-25424~25433	2025.11.11	所检项目合格	 A photograph showing two technicians in white lab coats with blue logos on their backs, working in a laboratory fume hood. They are positioned behind the hood, which contains various equipment and gas cylinders. The date '2025.10.27' is printed in the bottom right corner of the image.

106	GX-B1593/21-F-25486	2025.11.11	所检项目合格	
107	GX-B1606/23-F-25427~25436	2025.11.11	所检项目合格	

108	GX-B1568/22-F-25693~25694	2025.11.12	所检项目合格	
109	GX-B1529/20-F-25637~25647	2025.11.12	所检项目合格	

110	GX-B1542/21-F-25614~25619	2025.11.12	所检项目合格	 2025.11.5
111	GX-B1568/22-F-25679~25682	2025.11.13	所检项目合格	 2025.11.6

112	GX-B1568/22-F-25683~25692	2025.11.13	所检项目合格	
113	GX-B1528/20-F-25934	2025.11.12	所检项目合格	

114	GX-B1528/20-F-25928	2025.11.12	所检项目合格	
115	GX-B1529/20-F-25636	2025.11.12	所检项目合格	

116	GX-B1543/25-F-25255	2025.11.12	所检项目合格	 A photograph showing two technicians in white lab coats with the '中检公信' (Zhongjian Gongxin) logo working inside a blue fume hood. The hood has 'FUME HOOD' written on its upper panel. A date stamp '2025.11.6' is visible in the bottom right corner of the image.
117	GX-B1540/20-F-253366	2025.11.13	所检项目合格	 A photograph showing two technicians in white lab coats with the '中检公信' (Zhongjian Gongxin) logo working inside a blue fume hood. The hood has 'FUME HOOD' written on its upper panel. A date stamp '2025.11.6' is visible in the bottom right corner of the image.


118	GX-B1373/21-F-25525	2025.11.11	所检项目合格	
119	GX-B1373/21-F-25522~25524	2025.11.11	所检项目合格	

120	GX-B1603/22-F-250352	2025.11.11	所检项目合格	 2025.10.27
121	GX-B1466/22-F-25100~25101	2025.11.11	所检项目合格	 2025.10.28

122	GX-B1373/21-F-25521	2025.11.11	所检项目合格	
123	GX-B1603/22-F-250340	2025.11.7	所检项目合格	

124	GX-B1373/21-F-25512~25515	2025.11.11	所检项目合格	
125	GX-B1601/22-F-250941~250942	2025.11.12	所检项目合格	

126	GX-B1372/22-F-250863~250871	2025.11.12	所检项目合格	
127	GX-B1601/22-F-250990~250991	2025.11.12	本次共检验矿用风速传感器2台，2台所检项目合格。	

128	GX-B1601/22-F-250965~250989		本次共检验矿用风速传感器25台，25台所检项目合格	
129	GX-B1372/22-F-250903~250914	2025.11.12	本次共检验煤矿用低浓度载体催化式甲烷传感器12台，12台所检项目合格	

130	GX-B1604/23-F-25050~25060	2025.11.11	本次共检验传感器11台，11台所检项目合格。	
131	GX-B1592/21-F-25171~25177	2025.11.11	本次共检测传感器7台，7台所检项目合格。	

132	GX-B1466/22-F-25103~25106	2025.11.12	本次共检验煤矿用二氧化碳传感器4台，4台所检项目合格。	
133	GX-B1373/21-F-25529~25533		本次共检验温度传感器5台，5台所检项目合格。	

134	GX-B1373/21-F-25527~25528	2025.11.12	本次共检验温度传感器5台，5台所检项目合格。	
135	GX-B1465/22-F- 25149~25150	2025.11.12	本次共检验氧气传感器2台，2台所检项目合格。	

136	GX-B1540/20-F-252900~252914	2025.11.5	所检项目合格	
137	GX-B1475/22-F-25437~25442	2025.11.5	所检项目合格	

138	GX-B1372/22-F-250838~250839	2025.11.5	所检项目合格	
139	GX-B1475/22-F-25436	2025.11.5	所检项目合格	

140	GX-B1372/22-F-250872	2025.11.5	所检项目合格	
141	GX-B1374/22-F-250907	2025.11.4	所检项目合格	

142	GX-B1374/22-F-250908~250913	2025.11.4	所检项目合格	
-----	-----------------------------	-----------	--------	---