




序号	报告编号	发布日期	结论	影像资料
1	GX-B1495/25-1-251937~251947	2025. 12. 1	本次共检高压防爆开关设备11台，11台高压防爆开关设备所检项目合格。	
2	GX-B1495/25-1-251948~251952	2025. 12. 1	本次共检高压防爆开关设备5台，5台高压防爆开关设备所检项目合格。	

3	GX-B1350/21-1-25041	2025. 12. 1	本次共检接地装置 2处，2处接地装置所 检项目合格。	 
4	GX-B1321/20-1-251096~251108	2025. 12. 1	本次共检电力电缆13 条，13条电力电缆所 检项目合格。	 

5	GX-B1312/20-1-25514~25516	2025. 12. 1	本次共检电力变压器3台, 3台电力变压器所检项目合格。	
6	GX-B1310/21-1-25345	2025. 12. 2	符合标准要求。	



7	GX-B1329/21-1-25126~25142	2025. 12. 3	本次共检氧化锌避雷器17组，17组所检项目合格。	
8	GX-B1495/25-1-251953~251960	2025. 12. 4	本次共检高压开关设备8台，8台高压开关设备所检项目合格。	



9	GX-B1322/21-1-25324	2025. 12. 5	所检项目合格。	
10	GX-B1313/21-1-25220	2025. 12. 5	所检项目合格。	


11	GX-B1350/21-1-25042	2025. 12. 5	所检项目合格。	 A worker wearing a red hard hat and a grey work jacket is standing next to a green metal structure. He is holding a handheld electronic device. A black toolbox with yellow and red cables is on the ground. The date '2025.12.4' is visible in the bottom right corner of the photo.
12	GX-B1316/23-1-25124	2025. 12. 5	所检项目合格。	 A worker wearing a yellow hard hat is crouching next to a large black pipe in a rocky, outdoor environment. The date '2025.12.4' is visible in the bottom right corner of the photo.

13	GX-B1316/23-1-25125	2025. 12. 5	所检项目合格。			
14	GX-B1316/23-1-25126	2025. 12. 5	所检项目合格。			

15	GX-B1451/20-1-25575	2025. 12. 5	所检项目合格。	
16	GX-B1329/21-1-25143	2025. 12. 5	所检项目合格。	

17	GX-B1328/25-1-25128	2025. 12. 5	本次共检绝缘手套80只，80只绝缘手套合格。	
18	GX-B1328/25-1-25129	2025. 12. 5	本次共检绝缘靴72只，72只绝缘靴合格。	

19	GX-B1328/25-1-25130	2025. 12. 5	本次共检验电器 30支，30支验电器合格。 。	
20	GX-B1328/25-1-25131	2025. 12. 5	本次共检便携式接地 和接地短路装置 12套，12套便携式接地 和接地短路装置 合格。	

21	GX-B1328/25-1-25132	2025. 12. 5	本次共检绝缘胶垫152个，152个绝缘胶垫合格。	
----	---------------------	-------------	--------------------------	---