

序号	报告编号	发布日期	结论	影像资料
1	GX-B1361/22-A-251227	2025/12/1	所检项目合格	
2	GX-B1361/22-A-251229	2025/12/1	所检项目合格	

3	GX-B1361/22-A-251230	2025/12/1	所检项目合格	
4	GX-B1361/22-A-251231	2025/12/1	所检项目合格	

5	GX-B1361/22-A-251232	2025/12/1	所检项目合格	
6	GX-B1361/22-A-251233	2025/12/1	所检项目合格	

7	GX-B1361/22-A-251234	2025/12/1	合格	
8	GX-B1361/22-A-251273	2025/12/3	所检项目合格	

9	GX-B1361/22-A-251274	2025/12/3	所检项目合格	
10	GX-B1361/22-A-251275	2025/12/3	所检项目合格	

11	GX-B1361/22-A-251276	2025/12/3	所检项目合格	
12	GX-B1361/22-A-251277	2025/12/3	所检项目合格	

13	GX-B1361/22-A-251278	2025/12/3	所检项目合格	 A photograph showing a worker in a workshop. The worker is wearing a light-colored jacket and gloves, and is using a tool to work on a metal part. The date 2025/11/30 is visible in the bottom right corner of the image.
14	GX-B1361/22-A-251279	2025/12/3	所检项目合格	 A photograph showing two workers in a workshop. One worker is operating a machine, and the other is standing next to it. The date 2025/12/1 is visible in the bottom right corner of the image.

15	GX-B1361/22-A-251280	2025/12/3	所检项目合格	
16	GX-B1361/22-A-251235	2025/12/3	所检项目合格	

17	GX-B1361/22-A-251236	2025/12/3	所检项目合格	
18	GX-B1361/22-A-251237	2025/12/3	所检项目合格	

19	GX-B1361/22-A-251238	2025/12/3	所检项目合格	
20	GX-B1362/23-A-25567	2025/12/5	所检项目合格	

21	GX-B1362/23-A-25568	2025/12/5	所检项目合格	
22	GX-B1362/23-A-25569	2025/12/5	所检项目合格	

23	GX-B1362/23-A-25570	2025/12/5	所检项目合格	
----	---------------------	-----------	--------	---