

序号	报告编号	发布日期	结论	影像资料
24	GX-B1363/25-A-25592	2025/12/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
25	GX-B1367/22-A-25077	2025/12/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1363/25-A-25580	2025/12/2	所检项目合格。	 2025.11.19

序号	报告编号	发布日期	结论	影像资料
27	GX-B1363/25-A-25581	2025/12/2	所检项目合格。	 2025.11.19

序号	报告编号	发布日期	结论	影像资料
28	GX-B1363/25-A-25583	2025/12/2	所检项目合格。	 2025.11.21

序号	报告编号	发布日期	结论	影像资料
29	GX-B1363/25-A-25584	2025/12/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1363/25-A-25585	2025/12/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1363/25-A-25590	2025/12/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1363/25-A-25591	2025/12/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1363/25-A-25578	2025/12/3	所检项目合格。	 A photograph showing two men in grey short-sleeved shirts and dark trousers. They are wearing white face masks and are looking into the open door of a large, industrial-grade oven or kiln. The oven is made of metal and has a prominent chimney pipe extending from the top. The men are positioned on either side of the oven's entrance. The background shows a plain wall and a window with a red frame. The date '2025.11.20' is visible in the bottom right corner of the image. The logo '中检公信' (China Inspection and Certification) is printed on the back of both men's shirts.

序号	报告编号	发布日期	结论	影像资料
34	GX-B1363/25-A-25579	2025/12/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1363/25-A-25596	2025/12/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1363/25-A-25597	2025/12/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
37	GX-B1367/22-A-25079	2025/12/3	阻燃性不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1367/22-A-25078	2025/12/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1462/22-A-25005	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1462/22-A-25006	2025/12/4	所检项目合格。	 A photograph showing two men in grey work uniforms with "CIC" and "中检公信" logos on the back. They are standing in front of a piece of industrial equipment with glass panels, possibly a sterilizer or oven. The man on the right is looking at a screen or control panel. The date "2025.11.29" is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
41	GX-B1364/25-A-251092	2025/12/4	所检项目合格。	 A photograph showing two men in light-colored work uniforms standing in a laboratory or industrial setting. One man is facing a large black machine with a computer monitor, while the other stands beside him. A warning sign on the wall to the right of the machine features a triangle with a wavy line and the text '注意高温' (Caution: High Temperature). The date '2025.11.28' is visible on the back of the man on the right's uniform. The machine has a 'ULUX' brand label.

序号	报告编号	发布日期	结论	影像资料
42	GX-B1364/25-A-251080	2025/12/4	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1364/25-A-251081	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1364/25-A-251082	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
45	GX-B1364/25-A-251088	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1364/25-A-251089	2025/12/4	所检项目合格。	 <p>2025.11.28</p>

序号	报告编号	发布日期	结论	影像资料
47	GX-B1364/25-A-251090	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
48	GX-B1364/25-A-251091	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
49	GX-B1364/25-A-251083	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
50	GX-B1364/25-A-251084	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
51	GX-B1364/25-A-251085	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
52	GX-B1364/25-A-251086	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
53	GX-B1364/25-A-251087	2025/12/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
54	GX-B1365/25-A-25098	2025/12/4	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
55	GX-B1366/25-A-25124	2025/12/4	所检项目全部合格。	