





序号	报告编号	发布日期	结论	影像资料
86	GX-B1310/21-1-25335	2025. 11. 17	符合标准要求	
87	GX-B1310/21-1-25336	2025. 11. 17	符合标准要求	

88	GX-B1310/21-1-25337	2025. 11. 17	符合标准要求	
89	GX-B1310/21-1-25338	2025. 11. 17	符合标准要求	

90	GX-B1310/21-1-25339	2025. 11. 17	符合标准要求	
91	GX-B1310/21-1-25340	2025. 11. 17	符合标准要求	

92	GX-B1310/21-1-25341	2025. 11. 17	符合标准要求	
93	GX-B1310/21-1-25302	2025. 11. 14	符合标准要求	

94	GX-B1310/21-1-25303	2025. 11. 14	符合标准要求	
95	GX-B1310/21-1-25304	2025. 11. 14	符合标准要求	

96	GX-B1310/21-1-25305	2025. 11. 14	符合标准要求			
97	GX-B1310/21-1-25306	2025. 11. 14	符合标准要求			

98	GX-B1310/21-1-25307	2025. 11. 14	符合标准要求	
99	GX-B1310/21-1-25308	2025. 11. 14	符合标准要求	

100	GX-B1310/21-1-25309	2025. 11. 14	符合标准要求			
101	GX-B1310/21-1-25310	2025. 11. 14	符合标准要求			


102	GX-B1310/21-1-25311	2025. 11. 14	符合标准要求			
103	GX-B1310/21-1-25312	2025. 11. 14	符合标准要求			

104	GX-B1310/21-1-25313	2025. 11. 14	符合标准要求	
105	GX-B1310/21-1-25314	2025. 11. 14	符合标准要求	


106	GX-B1310/21-1-25342	2025. 11. 18	符合标准要求	
107	GX-B1310/21-1-25343	2025. 11. 18	符合标准要求	

108	GX-B1310/21-1-25344	2025. 11. 18	符合标准要求	
109	GX-B1310/21-1-25345	2025. 11. 18	符合标准要求	

110	GX-B1310/21-1-25346	2025. 11. 18	符合标准要求		
111	GX-B1310/21-1-25347	2025. 11. 18	符合标准要求		

112	GX-B1303/21-1-25007	2025. 11. 19	综合判定：合格	
113	GX-B1303/21-1-25008	2025. 11. 19	综合判定：合格	

114	GX-B1304/21-1-25017	2025. 11. 19	综合判定：合格	
115	GX-B1328/25-1-25112	2025. 11. 19	本次共检绝缘手套 8只，8只绝缘手套合格	

116	GX-B1328/25-1-25113	2025. 11. 19	本次共检绝缘靴8只， 8只绝缘靴合格	
117	GX-B1328/25-1-25114	2025. 11. 19	本次共检绝缘杆1套， 1套绝缘杆合格	

118	GX-B1328/25-1-25115	2025. 11. 19	本次共检验电器1支， 1支验电器合格		
119	GX-B1310/21-1-25315	2025. 11. 18	符合标准要求		

120	GX-B1310/21-1-25316	2025. 11. 18	符合标准要求	
121	GX-B1310/21-1-25317	2025. 11. 18	符合标准要求	

122	GX-B1310/21-1-25318	2025. 11. 18	符合标准要求	
123	GX-B1310/21-1-25319	2025. 11. 18	符合标准要求	

124	GX-B1310/21-1-25320	2025. 11. 18	符合标准要求	
125	GX-B1310/21-1-25321	2025. 11. 18	符合标准要求	

126	GX-B1310/21-1-25322	2025. 11. 18	符合标准要求		
127	GX-B1310/21-1-25323	2025. 11. 18	符合标准要求		



128	GX-B1310/21-1-25324	2025. 11. 18	符合标准要求	
129	GX-B1310/21-1-25325	2025. 11. 18	符合标准要求	

130	GX-B1310/21-1-25326	2025. 11. 18	符合标准要求	
131	GX-B1328/25-1-25118	2025. 11. 21	本次共检绝缘手套 2只，2只绝缘手套合格	


132	GX-B1328/25-1-25119	2025. 11. 21	本次共检绝缘靴2只， 2只绝缘靴合格	
133	GX-B1328/25-1-25120	2025. 11. 21	本次共检绝缘杆1套， 1套绝缘杆合格	

134	GX-B1328/25-1-25121	2025. 11. 21	本次共检验电器1支， 1支验电器合格	
135	GX-B1328/25-1-25116	2025. 11. 26	本次共检绝缘手套120只， 120只绝缘手套合格。	

136	GX-B1328/25-1-25117	2025. 11. 26	本次共检绝缘靴 120只，120只绝缘靴合格。	
137	GX-B1304/21-1-25018	2025. 11. 26	综合判定：合格。	


138	GX-B1350/21-1-25040	2025. 11. 26	所检项目合格。	
139	GX-B1313/21-1-25219	2025. 11. 26	所检项目合格。	

140	GX-B1350/21-1-25040	2025. 11. 26	所检项目合格。	 2025.11.17
141	GX-B1313/21-1-25203~25205	2025. 11. 26	本次共检电力变压器3台，3台电力变压器所检项目合格。	 2025/11/03



142	GX-B1313/21-1-25206~25207	2025. 11. 26	本次共检电力变压器2台，2台电力变压器所检项目合格。		
143	GX-B1313/21-1-25208~25211	2025. 11. 26	本次共检电力变压器4台，4台电力变压器所检项目合格。		

144	GX-B1313/21-1-25212~25214	2025. 11. 26	本次共检电力变压器3台，3台电力变压器所检项目合格。	
145	GX-B1313/21-1-25215~25218	2025. 11. 26	本次共检电力变压器4台，4台电力变压器所检项目合格。	

146	GX-B1328/25-1-25122	2025. 11. 27	本次共检绝缘手套14只，14只绝缘手套合格。	
147	GX-B1328/25-1-25123	2025. 11. 27	本次共检绝缘靴4只，4只绝缘靴合格。	

148	GX-B1328/25-1-25124	2025. 11. 27	本次共检验电器6支， 6支验电器合格。	
149	GX-B1328/25-1-25125	2025. 11. 27	本次共检便携式接 地和接地短路装置 1套，1套便携式接地 和接地短路装置合格 。	



150	GX-B1313/21-1-25199~25202	2025. 11. 26	本次共检电力变压器4台，4台电力变压器所检项目合格。	 <p>2025. 11. 04</p>
151	GX-B1328/25-1-25126	2025. 11. 27	本次共检绝缘手套20只，20只绝缘手套合格。	 <p>2025.11.20</p>



152	GX-B1328/25-1-25127	2025. 11. 27	本次共检绝缘靴 20只，20只绝缘靴合格。 。	
153	GX-B1598/24-1-25094	2025. 11. 28	实测钢丝绳有效截面 积损失百分比最大为 1.15%，小于5%为正常。 。	

154	GX-B1598/24-1-25095	2025. 11. 28	实测钢丝绳有效截面积损失百分比最大为1.30%，小于5%为正常。 。			
155	GX-B1598/24-1-25096	2025. 11. 28	实测钢丝绳有效截面积损失百分比最大为1.17%，小于5%为正常。 。			

156	GX-B1598/24-1-25097	2025. 11. 28	实测钢丝绳有效截面积损失百分比最大为1.21%，小于5%为正常。 。		
157	GX-B1598/24-1-25098	2025. 11. 28	实测钢丝绳有效截面积损失百分比最大为1.51%，小于5%为正常。 。		

158	GX-B1598/24-1-25099	2025. 11. 28	实测钢丝绳有效截面 积损失百分比最大为 1.27%，小于5%为正常 。	
159	GX-B1310/21-1-25339	2025. 11. 27	符合标准要求	

160	GX-B1310/21-1-25340	2025. 11. 27	符合标准要求	
161	GX-B1310/21-1-25341	2025. 11. 27	符合标准要求	

162	GX-B1427/21-1-25342	2025. 11. 27	符合标准要求	
163	GX-B1310/21-1-25343	2025. 11. 27	符合标准要求	

164	GX-B1427/21-1-25344	2025. 11. 27	符合标准要求	
-----	---------------------	--------------	--------	-------------------------------------------------------------------------------------