

序号	报告编号	发布日期	结论	影像资料
143	GX-B1540/20-F-253047~253066	2025.11.13	所检项目合格	
144	GX-B1540/20-F-253087~253106	2025.11.13	所检项目合格	

145	GX-B1528/20-F-25769~25788	2025.11.13	所检项目合格	
146	GX-B1528/20-F-25749~25768	2025.11.13	所检项目合格	

147	GX-B1374/22-F-250975~250979	2025.11.12	所检项目合格	
148	GX-B1605/23-F-25434~25440	2025.11.13	所检项目合格	

149	GX-B1606/23-F-25438~25444	2025.11.13	所检项目合格	
150	GX-B1373/21-F-25529~25533	2025.11.14	本次共检验温度传感器5台，5台所检项目合格。	

151	GX-B1593/21-F-25497~25498	2025.11.13	所检项目合格	
152	GX-B1528/20-F-25807~25825	2025.11.13	所检项目合格	

153	GX-B1528/20-F-25789~25806	2025.11.13	所检项目合格	
154	GX-B1540/20-F-253107~253124	2025.11.13	所检项目合格	

155	GX-B1540/20-F-253125~253143	2025.11.13	所检项目合格	
156	GX-B1542/21-F-25555~25558	2025.11.14	本次共检验光干涉式 甲烷测定器4台，4台 所检项目合格。	

157	GX-B1543/25-F-25233~25234	2025.11.14	本次共检验硫化氢报警仪2台，2台所检项目合格。	
158	GX-B1529/20-F-25554~25580	2025.11.14	本次共检验一氧化碳测定器27台，27台所检项目合格	

159	GX-B1529/20-F-25544~25553	2025.11.14	本次共检验一氧化碳测定器10台，10台所检项目合格”	
160	GX-B1529/20-F-25581~25599	2025.11.14	本次共检验一氧化碳测定器19台，19台所检项目合格”	
161	GX-B1502/24-F-25046	2025. 11. 11	I 类，容易自燃。	
162	GX-B1501/24-F-25046	2025. 11. 11	煤尘具有爆炸性。	

163	GX-B1542/21-F-25589~25599	2025.11.11	所检项目合格	
164	GX-B1529/20-F-25616~25625	2025.11.11	所检项目合格	
165	GX-B1501/24-F-25045	2025. 11. 14	煤尘具有爆炸性	
166	GX-B1502/24-F-25045	2025. 11. 14	II类, 自燃	

167	GX-B1602/22-F-25086~25087	2025.11.14	所检项目合格	
168	GX-B1595/22-F-25170~25177	2025.11.14	所检项目合格	


169	GX-B1529/20-F-25520~25539	2025.11.14	所检项目合格	
170	GX-B1543/25-F-25229~25232	2025.11.14	所检项目合格	

171	GX-B1542/21-F-25550~25554	2025.11.14	所检项目合格	
172	GX-B1529/20-F-25540~25543	2025.11.14	所检项目合格	

173	GX-B1528/20-F-25705~25708	2025.11.14	所检项目合格	
174	GX-B1568/22-F-25658~25663	2025.11.14	所检项目合格	

175	GX-B1540/20-F-252921~252927	2025.11.14	所检项目合格	
176	GX-B1540/20-F-252928~252952	2025.11.14	所检项目合格	

177	GX-B1540/20-F-252953~252977	2025.11.14	所检项目合格	
178	GX-B1540/20-F-252978~253002	2025.11.14	所检项目合格	

179	GX-B1540/20-F-253003~253006	2025.11.14	所检项目合格	
180	GX-B1602/22-F-25080~25082	2025.11.14	所检项目合格	

181	GX-B1528/20-F-25705~25708	2025.11.14	所检项目合格	
182	GX-B1410/22-F-25743~25746	2025.11.14	所检项目合格	

183	GX-B1372/22-F-250917~250918	2025.11.14	所检项目合格	
184	GX-B1540/20-F-253356~253360	2025.11.14	所检项目合格	

185	GX-B1540/20-F-253361~253365	2025.11.14	所检项目合格	
186	GX-B1529/20-F-25626~25630	2025.11.13	所检项目合格	


187	GX-B1529/20-F-25631~25635	2025.11.13	所检项目合格	
188	GX-B1543/25-F-25245~25249	2025.11.13	所检项目合格	

189	GX-B1543/25-F-25250~25254	2025.11.14	所检项目合格	
190	GX-B1528/20-F-25918~25922	2025.11.13	所检项目合格	

191	GX-B1528/20-F-25923~25927	2025.11.14	所检项目合格	 25.11.7
192	GX-B1540/20-F-253316~253335	2025.11.17	所检项目合格	 2025.11.4

193	GX-B1540/20-F-253336~253355	2025.11.17	所检项目合格	
194	GX-B1540/20-F-253356~253360	2025.11.17	所检项目合格	

195	GX-B1540/20-F-253361~253365	2025.11.17	所检项目合格	
196	GX-B1529/20-F-25514~25519	2025.11.17	所检项目合格	

197	GX-B1542/21-F-25543~25549	2025.11.17	所检项目合格	
198	GX-B1568/22-F-25693~25694	2025.11.18	所检项目合格	

199	GX-B1475/22-F-25480~25485	2025.11.17	所检项目合格	
200	GX-B1465/22-F-25155	2025.11.17	所检项目合格	

201	GX-B1373/21-F-25541	2025.11.17	所检项目合格	
202	GX-B1372/22-F-250873~250874	2025.11.17	所检项目合格	

203	GX-B1372/22-F-250917~250918	2025.11.17	所检项目合格	
204	GX-B1606/23-F-25445-25453	2025.11.19	所检项目合格	

205	GX-B1605/23-F-25441-25449	2025.11.18	所检项目合格	
206	GX-B1568/22-F-25704~25709	2025.11.20	所检项目合格	

207	GX-B1568/22-F-25710~25711	2025.11.20	所检项目合格	 2025年11月12日
208	GX-B1602/22-F-25088	2025.11.20	所检项目合格	 2025年11月13日

209	GX-B1542/21-F-25602~25613	2025.11.19	所检项目合格	
210	GX-B1542/21-F-25559~25574	2025.11.19	所检项目合格	


211	GX-B1528/20-F-25901~25905	2025.11.19	所检项目合格	 A photograph showing two laboratory technicians, a man and a woman, wearing grey lab coats with a logo on the back, working inside a blue fume hood. They are using various pieces of laboratory equipment. The date '2025.11.4' is visible in the bottom right corner of the image.
212	GX-B1528/20-F-25896~25900	2025.11.19	所检项目合格	 A photograph showing the same two laboratory technicians working in a similar fume hood setup. The date '2025.11.3' is visible in the bottom right corner of the image.

213	GX-B1543/25-F-25240~25244	2025.11.19	所检项目合格	
214	GX-B1543/25-F-25235~25239	2025.11.19	所检项目合格	

215	GX-B1529/20-F-25609~25613	2025.11.19	所检项目合格	 A photograph showing two laboratory technicians in white lab coats with the '中检公信' (Zhongjian Gongxin) logo on the back, working inside a blue fume hood. The hood has 'FUME HOOD' written on the top. A date stamp '2025.11.4' is visible in the bottom right corner of the image.
216	GX-B1529/20-F-25600~25603	2025.11.19	所检项目合格	 A photograph showing two laboratory technicians in white lab coats with the '中检公信' (Zhongjian Gongxin) logo on the back, working inside a blue fume hood. The hood has 'FUME HOOD' written on the top. A date stamp '2025.10.28' is visible in the bottom right corner of the image.

217	GX-B1528/20-F-25886~25895	2025.11.19	所检项目合格	 A photograph showing two female students in a laboratory. They are wearing grey lab coats. One student is holding a clipboard and looking at it, while the other is using a pipette to transfer liquid into small vials on a lab bench. The lab bench has various equipment and containers. A timestamp '2025.10.25' is visible in the bottom right corner of the photo.
218	GX-B1528/20-F-25729~25748	2025.11.19	所检项目合格	 A photograph showing two female students in a laboratory, similar to the one above. They are wearing grey lab coats. One student is holding a clipboard and looking at it, while the other is using a pipette to transfer liquid into small vials on a lab bench. The lab bench has various equipment and containers. A timestamp '2025.10.29' is visible in the bottom right corner of the photo.

219	GX-B1528/20-F-25866~25885	2025.11.20	所检项目合格	
220	GX-B1528/20-F-25709~25728	2025.11.20	所检项目合格	

221	GX-B1529/20-F-25604~25608	2025.11.20	所检项目合格	
222	GX-B1542/21-F-25575~25588	2025.11.20	所检项目合格	

223	GX-B1544/21-F-25082~25083	2025.11.20	所检项目合格	
224	GX-B1529/20-F-25614~25615	2025.11.19	所检项目合格	

225	GX-B1528/20-F-25906~25907	2025.11.19	所检项目合格	
226	GX-B1502/24-F-25044	2025. 11. 20	I 类，容易自燃。	

227	GX-B1501/24-F-25044	2025. 11. 20	煤尘具有爆炸性。	
228	GX-B1374/22-F-250932~250951	2025.11.18	所检项目合格	

229	GX-B1374/22-F-250952~250961	2025.11.18	所检项目合格	
230	GX-B1475/22-F-25456~25466	2025.11.20	所检项目合格	

231	GX-B1603/22-F-250359~250364	2025.11.20	所检项目合格	 A person in a grey lab coat is operating a large industrial machine with a control panel. The machine is white and blue. The date 2025/10/30 is visible in the bottom right corner of the image.
232	GX-B1601/22-F-250965~250989	2025.11.20	所检项目合格	 A person in a grey lab coat is operating a large industrial machine with a control panel. The machine is white and blue. The date 2025.11.3 is visible in the bottom right corner of the image.

233	GX-B1540/20-F-253144~253163	2025.11.20	所检项目合格	 A technician in a grey lab coat with the '中检公信' logo is working inside a laboratory fume hood. They are using a yellow handheld device. The hood contains various glassware and equipment. A date stamp '2025/11/1' is visible in the bottom right corner of the photo.
234	GX-B1528/20-F-25826~25845	2025.11.18	所检项目合格	 A technician in a grey lab coat with the '中检公信' logo is working inside a laboratory fume hood. They are using a yellow handheld device. The hood contains various glassware and equipment. A date stamp '2025/11/1' is visible in the bottom right corner of the photo.

235	GX-B1540/20-F-253164~253183	2025.11.20	所检项目合格	 A technician in a grey uniform is working on a piece of equipment with multiple ports and cables. Another person is standing nearby, looking at a document. The date 2025/10/23 is visible in the bottom right corner of the image.
236	GX-B1528/20-F-25846~25865	2025.11.19	所检项目合格	 Two technicians in grey uniforms are working on a piece of equipment. One is standing and looking at a document, while the other is leaning over the equipment. The date 2025/10/23 is visible in the bottom right corner of the image.