

序号	报告编号	发布日期	结论	影像资料
60	GX-B1321/20-2-25467~25472	2025/12/18	所检项目合格	
61	GX-B1321/20-2-25473~25476	2025/12/18	所检项目合格	

62	GX-B1321/20-2-25487~25489	2025/12/18	所检项目合格		
63	GX-B1321/20-2-25490~25492	2025/12/18	所检项目合格		


64	GX-B1312/20-2-25298~25299	2025/12/18	所检项目合格	 <p>2025/12/03</p>
65	GX-B1312/20-2-25319~25320	2025/12/18	所检项目合格	 <p>2025/12/03</p>

66	GX-B1312/20-2-25321~25322	2025/12/18	所检项目合格		 <p>2025/12/04</p>	
67	GX-B1312/20-2-25323~25325	2025/12/18	所检项目合格		 <p>2025/12/05</p>	

68	GX-B1323/21-2-25108~25109	2025. 12. 17	所检项目合格。		 <p>2025/12/04</p>	
69	GX-B1495/25-2-251039~251042	2025. 12. 18	所检项目合格		 <p>2025/12/04</p>	

70	GX-B1495/25-2-251043~251047	2025. 12. 18	所检项目合格		 <p>2025/12/05</p>
71	GX-B1611/23-2-25035	2025/12/18	所检项目合格。		 <p>2025/11/12</p>

72	GX-B1611/23-2-25036	2025/12/18	所检项目合格。	 <p>2025/11/12</p>
73	GX-B1611/23-2-25037	2025/12/18	所检项目合格。	 <p>2025/11/13</p>

74	GX-B1611/23-2-25038	2025/12/18	所检项目合格。	
75	GX-B1328/25-2-25142	2025. 12. 18	本次共检绝缘手套40只，40只绝缘手套合格。	


76	GX-B1328/25-2-25143	2025. 12. 18	本次共检绝缘靴 40只，40只绝缘靴合格。 。	
77	GX-B1328/25-2-25144	2025. 12. 18	本次共检验电器 16支，16支验电器合格。 。	



78	GX-B1328/25-2-25145	2025. 12. 18	本次共检便携式接地和接地短路装置10组，10组便携式接地和接地短路装置合格。	
79	GX-B1328/25-2-25146	2025. 12. 18	本次共检绝缘杆2组，2组绝缘杆所检项目合格。	

80	GX-B1574/20-2-25064	2025/12/19	所检项目合格。	 <p>2025/11/12</p>
81	GX-B1574/20-2-25066	2025. 12. 22	所检项目合格	 <p>2025/12/15</p>

82	GX-B1612/23-2-25156	2025. 12. 22	所检项目合格	
83	GX-B1416/22-2-25015	2025. 12. 19	综合判定：合格。	

84	GX-B1515/22-2-25016	2025. 12. 23	滚筒绳衬直径与钢丝绳直径之比小于50倍。除上述问题外，其余所检项目合格。		
85	GX-B1515/22-2-25017	2025. 12. 23	滚筒绳衬直径与钢丝绳直径之比小于50倍。除上述问题外，其余所检项目合格。		

86	GX-B1328/25-2-25148	2025. 12. 19	所检项目合格	
87	GX-B1328/25-2-25149	2025. 12. 19	所检项目合格	

88	GX-B1328/25-2-25150	2025. 12. 19	所检项目合格	
89	GX-B1328/25-2-25151	2025. 12. 19	所检项目合格	

90	GX-B1328/25-2-25152	2025. 12. 19	所检项目合格	 A photograph showing two workers in a room. They are wearing red hard hats and light-colored jackets. In the foreground, there is a blue electrical control panel with various wires connected to it. To the right, there is a large white electrical cabinet. The floor is concrete and has some tools and equipment scattered on it. A date stamp '2025/12/09' is visible in the bottom right corner of the photo.
91	GX-B1328/25-2-25153	2025. 12. 19	所检项目合格	 A photograph showing two workers in a room, similar to the one above. They are wearing red hard hats and light-colored jackets. In the foreground, there is a blue electrical control panel with various wires connected to it. To the right, there is a large white electrical cabinet. The floor is concrete and has some tools and equipment scattered on it. A date stamp '2025/12/09' is visible in the bottom right corner of the photo.

92	GX-B1612/23-2-25142	2025. 12. 22	所检项目合格。	
93	GX-B1612/23-2-25143	2025. 12. 22	所检项目合格。	

94	GX-B1612/23-2-25144	2025. 12. 22	所检项目合格。	 <p>2025/11/12</p>
95	GX-B1612/23-2-25145	2025. 12. 22	所检项目合格。	 <p>2025/11/12</p>

96	GX-B1612/23-2-25146	2025. 12. 22	所检项目合格。			
97	GX-B1612/23-2-25147	2025. 12. 22	所检项目合格。			

98	GX-B1612/23-2-25148	2025. 12. 22	所检项目合格。			
99	GX-B1612/23-2-25149	2025. 12. 22	所检项目合格。			

100	GX-B1612/23-2-25150	2025. 12. 22	所检项目合格。	
101	GX-B1612/23-2-25151	2025. 12. 22	所检项目合格。	

102	GX-B1612/23-2-25152	2025. 12. 22	所检项目合格。	
103	GX-B1612/23-2-25153	2025. 12. 22	所检项目合格。	