

序号	报告编号	发布日期	结论	影像资料
101	GX-B1313/21-6-25344~25345	2025/12/17	本次共检测电力变压器2台，2台电力变压器所检项目合格。	 A photograph showing a worker in a white protective uniform and a red hard hat standing in a room. The worker is positioned next to a piece of electrical equipment, possibly a transformer or control panel. The room has a white wall and a ceiling with some wiring. A timestamp '2025 12 13' is visible in the bottom right corner of the image.
102	GX-B1350/21-6-25069	2025/12/18	本次共检测接地装置2处，2处接地装置所检项目合格。	 A photograph showing a worker in a white protective uniform and a red hard hat standing behind a safety fence. The worker is holding a tool or device. The room has a white wall and a wooden door or partition. A timestamp '2025 12 13' is visible in the bottom right corner of the image.


103	GX-B1304/21-6-25051	2025/12/18	综合判定：合格。	
104	GX-B1304/21-6-25052	2025/12/18	综合判定：合格。	

105	GX-B1310/21-6-25454	2025/12/16	符合标准要求	
106	GX-B1310/21-6-25455	2025/12/16	符合标准要求	

107	GX-B1310/21-6-25450	2025/12/16	符合标准要求	 <p>2025 11 28</p>
108	GX-B1310/21-6-25451	2025/12/16	符合标准要求	 <p>2025 11 28</p>

109	GX-B1310/21-6-25452	2025/12/16	符合标准要求		 <p>2025 11 28</p>
110	GX-B1310/21-6-25453	2025/12/16	符合标准要求		 <p>2025 11 28</p>

111	GX-B1310/21-6-25454	2025/12/16	符合标准要求	
112	GX-B1310/21-6-25455	2025/12/16	符合标准要求	

113	GX-B1310/21-6-25456	2025/12/16	符合标准要求		 <p>2025 11 18</p>	
114	GX-B1310/21-6-25457	2025/12/16	符合标准要求		 <p>2025 11 18</p>	

115	GX-B1310/21-6-25458	2025/12/16	符合标准要求	
116	GX-B1310/21-6-25459	2025/12/16	符合标准要求	

117	GX-B1310/21-6-25460	2025/12/16	符合标准要求		 <p>2025 11 18</p>	
118	GX-B1310/21-6-25461	2025/12/16	符合标准要求		 <p>2025 11 18</p>	

119	GX-B1310/21-6-25463	2025/12/16	符合标准要求	 <p>2025 12 11</p>
120	GX-B1328/25-6-25265	2025年12月19日	本次共检绝缘手套 8只，8只绝缘手套合格。	 <p>2025 12 18</p>

121	GX-B1328/25-6-25266	2025年12月19日	本次共检全橡胶绝缘胶靴8只，8只全橡胶绝缘胶靴合格。	 A worker in a blue jacket is kneeling on a wet concrete surface, inspecting several pairs of black rubber boots. A red fire extinguisher and other equipment are nearby. The background shows a blue car and some trees under a clear sky. A timestamp '2025-12-16' is visible in the bottom right corner of the photo.
122	GX-B1313/21-6-25346~25347	2025年12月19日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 A worker in a black long-sleeved shirt and black pants is standing on a small platform, inspecting a green electrical transformer cabinet. He is wearing red safety gloves and holding a red tool. The cabinet is open, revealing internal components. A timestamp '2025-12-16' is visible in the bottom right corner of the photo.

123	GX-B1350/21-6-25070	2025年12月19日	本次共检验接地装置2处，2处接地装置所检项目合格。	 <p>2025 12 16</p>
124	GX-B1300/23-6-25005	2025年12月22日	综合判定：合格。	 <p>2025 12 08</p>