

序号	报告编号	发布日期	结论	影像资料
60	GX-B1559/22-7-25009	2025/12/16	所检项目合格。	
61	GX-B1328/25-7-25132	2025/12/18	本次共检绝缘手套96只，96只绝缘手套合格。	

62	GX-B1328/25-7-25133	2025/12/18	本次共检绝缘靴 56只，56只绝缘靴合格。 。	
63	GX-B1328/25-7-25134	2025/12/18	本次共检便携式接地 和接地短路装置 16套，16套便携式接地 和接地短路装置合格。 。	

64	GX-B1328/25-7-25135	2025/12/18	本次共检验电器 19只，19只验电器合格。 。	
65	GX-B1328/25-7-25136	2025/12/18	本次共检绝缘杆2组， 2组绝缘杆合格。	

66	GX-B1306/23-7-25032	2025/12/18	综合判定：合格。	
67	GX-B1306/23-7-25033	2025/12/18	综合判定：合格。	

68	GX-B1574/20-7-25001	2025/12/19	所检项目合格。	
69	GX-B1574/20-7-25002	2025/12/19	所检项目合格。	

70	GX-B1574/20-7-25003	2025/12/19	所检项目合格。		 A photograph showing a worker in a red protective suit and helmet inspecting a large, treaded tire in a dimly lit tunnel. The worker is holding a flashlight. A toolbox is on the ground nearby. A yellow timestamp '2025/11/20' is visible in the bottom right corner of the photo.	
71	GX-B1574/20-7-25004	2025/12/19	所检项目合格。		 A photograph showing a worker in a red protective suit and helmet inspecting a large, treaded tire in a dimly lit tunnel. The worker is holding a flashlight. A yellow timestamp '2025/11/20' is visible in the bottom right corner of the photo.	

72	GX-B1574/20-7-25005	2025/12/19	所检项目合格。	
73	GX-B1574/20-7-25006	2025/12/19	所检项目合格。	

74	GX-B1574/20-7-25007	2025/12/19	所检项目合格。	
75	GX-B1574/20-7-25008	2025/12/19	所检项目合格。	

76	GX-B1574/20-7-25009	2025/12/19	所检项目合格。		
77	GX-B1574/20-7-25010	2025/12/19	所检项目合格。		

78	GX-B1574/20-7-25011	2025/12/19	所检项目合格。		 <p>2025/11/21</p>	
79	GX-B1574/20-7-25012	2025/12/19	所检项目合格。		 <p>2025/11/21</p>	

80	GX-B1574/20-7-25013	2025/12/19	所检项目合格。	 A photograph showing a red motor vehicle, possibly a loader or hauler, in a dark tunnel. A worker wearing a red helmet and high-visibility vest stands next to the vehicle. A bright blue light beam is visible. A yellow timestamp '2025/11/22' is in the bottom right corner.
81	GX-B1574/20-7-25014	2025/12/19	所检项目合格。	 A photograph showing a motor vehicle, possibly a hauler, in a dark tunnel. A worker is visible near the vehicle. A bright blue light beam is visible. A yellow timestamp '2025/11/22' is in the bottom right corner.

82	GX-B1574/20-7-25015	2025/12/19	所检项目合格。	 A photograph showing a red wheel loader in a tunnel. Two workers in blue uniforms and red hard hats are standing near the loader. The date '2025/11/22' is visible in the bottom right corner of the image.
83	GX-B1574/20-7-25016	2025/12/19	所检项目合格。	 A photograph showing a red wheel loader in a tunnel. Two workers in blue uniforms and red hard hats are standing near the loader. The date '2025/11/22' is visible in the bottom right corner of the image.

84	GX-B1574/20-7-25017	2025/12/19	所检项目合格。		 A photograph showing a worker in a dark environment, likely an underground tunnel or mine. The worker is wearing a red hard hat and a dark jacket. The scene is illuminated by bright overhead lights, creating a high-contrast environment. The walls are rocky and uneven. A yellow timestamp '2025/11/22' is visible in the bottom right corner of the image.	
85	GX-B1574/20-7-25018	2025/12/19	所检项目合格。		 A photograph showing a worker in a dark environment, likely an underground tunnel or mine. The worker is wearing a red hard hat and a dark jacket. The scene is illuminated by bright overhead lights, creating a high-contrast environment. The walls are rocky and uneven. A yellow timestamp '2025/11/22' is visible in the bottom right corner of the image.	

86	GX-B1328/25-7-25137	2025/12/22	本次共检绝缘手套14只，14只绝缘手套合格。	
87	GX-B1328/25-7-25138	2025/12/22	本次共检绝缘靴14只，14只绝缘靴合格。	