

序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-5-25344	2025. 1. 4	符合标准要求。	 A photograph showing a worker in a red hard hat and safety harness working on a complex metal structure, possibly a bridge or industrial equipment. The worker is holding a red rope or cable. A yellow timestamp '2025/12/27' is visible in the bottom right corner of the image.
2	GX-B1427/21-5-25039	2025. 1. 4	符合标准要求。	 A photograph showing a worker in a red hard hat and safety harness standing on a metal structure, possibly a bridge or industrial equipment. The worker is holding a tool or device. A yellow timestamp '2025/12/27' is visible in the bottom right corner of the image.

3	GX-B1321/20-5-25994~25998	2026. 1. 4	本次共检电力电缆 5条，5条电力电缆所 检项目合格。		 <p>2025.12.3</p>
4	GX-B1495/25-5-251547~251548	2026. 1. 5	本次共检防爆型高压 配电装置2台，2台防 爆型高压配电装置所 检项目合格。		 <p>2025.12.3</p>

5	GX-B1495/25-5-251527~251528	2026. 1. 5	本次共检高压开关柜2台, 2台高压开关柜所检项目合格。	
6	GX-B1451/20-5-26001~26004	2026. 1. 5	本次共检高压开关柜4台, 4台高压开关柜所检项目合格。	

7	GX-B1451/20-5-26005~26011	2026. 1. 5	本次共检高压开关柜7台, 7台高压开关柜所检项目合格。		
8	GX-B1313/21-5-26001~26002	2026. 1. 5	本次共检电力变压器2台, 2台电力变压器所检项目合格。		

9	GX-B1313/21-5-26003~26004	2026. 1. 5	本次共检电力变压器2台，2台电力变压器所检项目合格。		
10	GX-B1322/21-5-26001~26003	2026. 1. 5	本次共检电力电缆3条，3条电力电缆所检项目合格。		

11	GX-B1322/21-5-26004~26006	2026. 1. 5	本次共检电力电缆 3条，3条电力电缆所 检项目合格。	
12	GX-B1350/21-5-26001	2026. 1. 5	所检项目合格。	

13	GX-B1323/21-5-25167~25168	2026. 1. 6	所检项目合格。	
14	GX-B1321/20-5-25923~25925	2026. 1. 6	本次共检电力电缆 3条，3条电力电缆所 检项目合格。	

15	GX-B1304/21-5-25006	2026. 1. 7	综合判定：合格。	
16	GX-B1495/25-5-251470~251473	2026. 1. 7	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	