

序号	报告编号	发布日期	结论	影像资料
112	GX-B1312/20-1-26001~26002	2026. 1. 16	本次共检电力变压器2台，2台电力变压器所检项目合格。	
113	GX-B1495/25-1-251965~251986	2026. 1. 19	本次共检高压开关设备22台，22台高压开关设备所检项目合格	

114	GX-B1495/25-1-251987~252014	2026. 1. 19	本次共检高压开关设备28台，28台高压开关设备所检项目合格		
115	GX-B1500/21-1-26001	2026. 1. 20	综合判定：合格。		

116	GX-B1500/21-1-26002	2026. 1. 20	综合判定：合格。	
117	GX-B1323/21-1-25360~25369	2026. 1. 20	所检项目合格。	

118	GX-B1328/25-1-26018	2026. 1. 22	本次共检绝缘胶垫10个，10个绝缘胶垫合格。	
119	GX-B1321/20-1-251130~251140	2026. 1. 21	本次共检电力电缆11条，11条电力电缆所检项目合格。	

120	GX-B1321/20-1-251141~251152	2026. 1. 21	本次共检电力电缆12条，12条电力电缆所检项目合格。	
121	GX-B1312/20-1-25518~25522	2026. 1. 21	本次共检电力变压器5台，5台电力变压器所检项目合格。	

122	GX-B1312/20-1-25523~25525	2026. 1. 21	本次共检电力变压器3台，3台电力变压器所检项目合格。	
123	GX-B1500/21-1-26001	2026. 1. 20	综合判定：合格。	

124	GX-B1500/21-1-26002	2026. 1. 20	综合判定：合格。	
125	GX-B1500/21-1-26003	2026. 1. 20	综合判定：合格。	

126	GX-B1328/25-1-26014	2026. 1. 26	本次共检绝缘手套10只，10只绝缘手套合格。	
127	GX-B1328/25-1-26015	2026. 1. 26	本次共检绝缘靴10只，10只绝缘靴合格。	

128	GX-B1328/25-1-26016	2026. 1. 26	本次共检验电器1支， 1支验电器合格。	 <p>2026.1.19</p>
129	GX-B1328/25-1-26017	2026. 1. 26	本次共检绝缘杆1套， 1套合格。	 <p>2026.1.19</p>

130	GX-B1313/21-1-25300~25310	2026. 1. 26	本次共检电力变压器 11台，11台电力变压器 所检项目合格。	
131	GX-B1313/21-1-26009~26020	2026. 1. 26	本次共检电力变压器 12台，12台电力变压器 所检项目合格。	

132	GX-B1612/23-1-25012	2026. 1. 26	所检项目合格。	
133	GX-B1313/21-1-25311~25313	2026. 1. 26	本次共检电力变压器3台，3台电力变压器所检项目合格。	

134	GX-B1322/21-1-25405~25423	2026. 1. 26	本次共检验电力电缆 19条，19条所检项目合格。			
135	GX-B1322/21-1-26013~26029	2026. 1. 26	本次共检验电力电缆 17条，17条所检项目合格。			

136	GX-B1313/21-1-26021~26023	2026. 1. 26	本次共检电力变压器3台，3台电力变压器所检项目合格。	 <p>2026.1.20</p>
137	GX-B1305/21-1-26001	2026. 1. 26	综合判定：合格。	 <p>2026/01/14</p>


138	GX-B1495/25-1-26018~26023	2026. 1. 26	本次共检高压开关设备6台，6台高压开关设备所检项目合格。	
139	GX-B1321/20-1-26010~26011	2026. 1. 27	本次共检电力电缆2条，2条电力电缆所检项目合格。	


140	GX-B1451/20-1-25958~25983	2026. 1. 27	本次共检高压开关柜26台, 26台高压开关柜所检项目合格。	
141	GX-B1328/25-1-26005	2026. 1. 26	本次共检绝缘手套158只, 158只绝缘手套合格。	

142	GX-B1328/25-1-26006	2026. 1. 26	本次共检绝缘靴 122只，122只绝缘靴合格。	 <p>经纬: 110.1529330 纬度: 39.8056874 地址: 鄂尔多斯市东胜区114乡道在内蒙古双欣矿业公司附近 工程名称: 内蒙古双欣矿业公司 时间: 2026-01-09</p>
143	GX-B1328/25-1-26007	2026. 1. 26	本次共检验电器 219支，219支验电器合格。	 <p>施工记录 经纬: 110.152946 纬度: 39.805620 地址: 鄂尔多斯市东胜区114乡道在内蒙古双欣矿业有限公司附近 工程名称: 我的工程 时间: 2026-01-09</p>

144	GX-B1328/25-1-26008	2026. 1. 26	<p>本次共检绝缘杆 12支，12支绝缘杆合格。</p>	 <p>经纬: 110.152947 纬度: 39.8056199 地址: 鄂尔多斯市东胜区114乡道在内蒙古双欣矿业公司附近 工程名称: 内蒙古双欣矿业公司 时间: 2026-01-10</p>
145	GX-B1328/25-1-26009	2026. 1. 26	<p>本次共检便携式接地 和接地短路装置 15组，15组便携式接地 和接地短路装置合格。</p>	 <p>施工记录</p> <p>经纬: 110.152947 纬度: 39.805621 地址: 鄂尔多斯市东胜区114乡道在内蒙古双欣矿业 有限公司附近 工程名称: 我的工程 时间: 2026-01-10</p>

146	GX-B1328/25-1-26010	2026. 1. 26	本次共检绝缘手套40只，40只绝缘手套合格。	 <p>经度: 110.1529414 纬度: 39.8056345 地址: 鄂尔多斯市东胜区114乡道在内蒙古双欣矿业有限公司附近 工程名称: 内蒙古双欣矿业有限公司 时间: 2026-01-10</p>
147	GX-B1328/25-1-26011	2026. 1. 26	本次共检绝缘靴40只，40只绝缘靴合格。	 <p>经度: 110.1529676 纬度: 39.8056267 地址: 鄂尔多斯市东胜区114乡道在内蒙古双欣矿业有限公司附近 工程名称: 内蒙古双欣矿业有限公司 时间: 2026-01-10</p>

148	GX-B1328/25-1-26012	2026. 1. 26	<p>本次共检验电器 20支，20支验电器合格 。</p>	 <p>经度: 110.1529373 纬度: 39.8056704 地址: 鄂尔多斯市东胜区114乡道在内蒙古双欣矿业有限公司附近 工程名称: 内蒙古双欣矿业有限公司 时间: 2026-01-10</p>
149	GX-B1404/20-1-26001	2026. 1. 27	<p>所检电网谐波电压总 谐波畸变率、各次谐 波电压含有率、谐波 电流符合GB/T 14549- 1993 《电能质量 公用 电网谐波》要求。</p>	 <p>2026/1/16</p>

150	GX-B1404/20-1-26002	2026. 1. 27	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
151	GX-B1495/25-1-26018~26023	2026. 1. 27	本次共检高压开关设备6台，6台高压开关设备所检项目合格。	

152	GX-B1495/25-1-26004~26017	2026. 1. 27	本次共检高压开关设备14台，14台高压开关设备所检项目合格。 。	 <p>2026.01.15</p>
153	GX-B1312/20-1-26006~26009	2026. 1. 27	本次共检电力变压器4台，4台电力变压器所检项目合格。	 <p>2026.1.15</p>

154	GX-B1321/20-1-26008~26009	2026. 1. 26	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	 <p>2026.1.15</p>
155	GX-B1321/20-1-26010~26011	2026. 1. 27	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	 <p>2026/1/15</p>

156	GX-B1495/25-1-26001~26003	2026. 1. 27	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	
157	GX-B1451/20-1-26016~26040	2026. 1. 27	本次共检高压开关柜25台，25台高压开关柜所检项目合格。	

158	GX-B1316/23-1-26008	2026. 1. 29	所检项目合格。		 A photograph showing a worker in a white jacket and yellow hard hat working on a concrete structure outdoors. The worker is holding a tool and appears to be inspecting or measuring the structure. The background shows some greenery and a rocky surface. A timestamp '2026.1.13' is visible in the bottom right corner of the photo.
159	GX-B1316/23-1-26009	2026. 1. 29	所检项目合格。		 A photograph showing a worker in a white jacket and yellow hard hat working on a concrete structure outdoors. The worker is holding a tool and appears to be inspecting or measuring the structure. The background shows some greenery and a rocky surface. A timestamp '2026.1.13' is visible in the bottom right corner of the photo.

160	GX-B1328/25-1-26019	2026. 1. 29	本次共检绝缘胶垫74个，74个绝缘胶垫合格。	
161	GX-B1598/24-1-26001	2026. 1. 28	实测钢丝绳有效截面积损失百分比最大为1.92%，小于5%为正常。	

162	GX-B1598/24-1-26002	2026. 1. 28	实测钢丝绳有效截面积损失百分比最大为1.73%，小于5%为正常。 。	
163	GX-B1316/23-1-26004	2026. 1. 29	所检项目合格。	

164	GX-B1316/23-1-26005	2026. 1. 29	所检项目合格。		
165	GX-B1316/23-1-26006	2026. 1. 29	所检项目合格。		

166	GX-B1316/23-1-26007	2026. 1. 29	所检项目合格。	
167	GX-B1301/25-1-26003	2026. 1. 30	综合判定:合格。	

168	GX-B1310/21-1-26010	2026. 1. 30	符合标准要求	
-----	---------------------	-------------	--------	---