



序号	报告编号	发布日期	结论	影像资料
25	GX-B1598/24-2-25330	2026/1/14	<p>实测钢丝绳有效截面积损失百分比最大为1.01%，小于5%为正常。</p>	
26	GX-B1598/24-2-25331	2026/1/14	<p>实测钢丝绳有效截面积损失百分比最大为1.00%，小于5%为正常。</p>	

27	GX-B1598/24-2-25332	2026/1/14	实测钢丝绳有效截面积损失百分比最大为0.91%，小于5%为正常。 。	
28	GX-B1598/24-2-25333	2026/1/14	实测钢丝绳有效截面积损失百分比最大为1.08%，小于5%为正常。 。	

29	GX-B1598/24-2-25334	2026/1/14	<p>实测钢丝绳有效截面积损失百分比最大为1.05%，小于5%为正常。</p>	
30	GX-B1598/24-2-25335	2026/1/14	<p>实测钢丝绳有效截面积损失百分比最大为1.07%，小于5%为正常。</p>	

31	GX-B1310/21-2-25493	2026/1/13	符合标准要求。	
32	GX-B1428/21-2-25493	2026/1/13	无缺陷痕迹显示。	

33	GX-B1310/21-2-25494	2026/1/13	符合标准要求。	 <p>2025/12/30</p>
34	GX-B1428/21-2-25494	2026/1/13	无缺陷痕迹显示。	 <p>2025/12/30</p>

35	GX-B1300/26-2-26001	2026. 1. 20	综合判定：合格。	 <p>2026.1.14</p>
36	GX-B1301/25-2-26002	2026. 1. 20	综合判定：合格。	 <p>2026/1/15</p>

37	GX-B1301/25-2-26001	2026. 1. 20	综合判定:合格。	
38	GX-B1310/21-2-26002	2026/1/13	符合标准要求。	

39	GX-B1310/21-2-26003	2026/1/13	符合标准要求。	
40	GX-B1310/21-2-26004	2026/1/13	符合标准要求。	

41	GX-B1313/21-2-26004~26005	2026. 1. 21	所检项目合格	 <p>2026/01/19</p>
42	GX-B1322/21-2-26008~26009	2026. 1. 22	所检项目合格	 <p>2026/01/19</p>

43	GX-B1418/23-2-26001	2026. 1. 23	综合判定：合格	 <p>2026/01/14</p>
44	GX-B1416/22-2-26001	2026/1/23	综合判定：合格。	 <p>2025/09/07</p>

45	GX-B1612/23-2-25159	2026/1/9	所检项目合格。	
46	GX-B1310/21-2-26015	2026/1/30	符合标准要求。	

47	GX-B1310/21-2-26016	2026/1/30	符合标准要求。		 <p>2026_01_16</p>
48	GX-B1310/21-2-26017	2026/1/30	符合标准要求。		 <p>2026_01_16</p>

49	GX-B1310/21-2-26018	2026/1/30	符合标准要求。	
50	GX-B1310/21-2-26019	2026/1/30	符合标准要求。	

51	GX-B1310/21-2-26020	2026/1/30	符合标准要求。		 <p>2026/01/16</p>
52	GX-B1310/21-2-26021	2026/1/30	符合标准要求。		 <p>2026/01/16</p>

53	GX-B1310/21-2-26022	2026/1/30	符合标准要求。	 A worker in a red uniform and helmet is operating a large green industrial machine, possibly a pump or motor, in an indoor setting. The machine has a large yellow circular component. Another worker in a red uniform is visible in the background. The date 2026/01/30 is visible in the bottom right corner of the image.
54	GX-B1310/21-2-26023	2026/1/30	符合标准要求。	 A worker in a red uniform and helmet is operating a large yellow industrial machine outdoors. The machine has a large yellow circular component. The worker is standing on a platform. The date 2026/01/30 is visible in the bottom right corner of the image.

55	GX-B1310/21-2-26024	2026/1/30	符合标准要求。	
56	GX-B1428/21-2-26025	2026/1/30	无缺陷迹痕显示。	

57	GX-B1428/21-2-26026	2026/1/30	无缺陷迹痕显示。	 <p>2026/01/13</p>
58	GX-B1310/21-2-26027	2026/1/30	符合标准要求。	 <p>2026/01/16</p>