


序号	报告编号	发布日期	结论	影像资料
52	GX-B1568/26-F-26001~26006	2026. 1. 15	所检项目合格	
53	GX-B1475/26-F-26007~26011	2026. 1. 15	所检项目合格	

54	GX-B1569/26-F-26001	2026.1.16	<p>1) CO为缓慢氧化阶段的标志性气体；CO气体浓度增率临界值为105.57ppm/h；CO临界浓度33.70ppm。2) C2H4为加速氧化阶段的标志性气体；C2H4气体浓度临界值为0.16ppm，C2H4/C2H6烯烷比为0.16；临界温度为150.0℃，预警温度为140.0℃。3) C2H2为激烈氧化阶段的标志性气体；预警温度为300.1℃。</p>	
55	GX-B1601/26-F-26011	2026.1.16	所检项目合格	
56	GX-B1605/26-F-26091~26095	2026.1.20	所检项目合格	

57	GX-B1606/26-F-26091~26095	2026. 1. 20	所检项目合格	
58	GX-B1568/26-F-26091~26098	2026. 1. 20	所检项目合格	

59	GX-B1568/26-F-26060~26066	2026. 1. 21	所检项目合格	
60	GX-B1601/26-F-26014~26015	2026. 1. 22	所检项目合格	

61	GX-B1410/22-F-26001~26002	2026. 1. 22	所检项目合格	
62	GX-B1606/26-F-26039~26047	2026. 1. 22	所检项目合格	

63	GX-B1606/26-F-26048~26055	2026. 1. 22	所检项目合格	 <p>2026.1.12</p>
64	GX-B1605/26-F-26048~26055	2026. 1. 22	所检项目合格	 <p>2026.1.12</p>

65	GX-B1605/26-F-26039~26047	2026. 1. 22	所检项目合格	
66	GX-B1545/26-F-26001~26009	2026. 1. 22	所检项目合格	

67	GX-B1545/26-F-26010~26017	2026. 1. 22	所检项目合格	
68	GX-B1572/26-F-260001~260005	2026. 1. 27	所检项目合格	

69	GX-B1568/26-F-26021~26025	2026.1.26	所检项目合格	
70	GX-B1568/26-F-26077~26086	2026.1.26	所检项目合格	


71	GX-B1601/26-F-26012~26013	2026.1.26	所检项目合格	
72	GX-B1603/26-F-26005~26006	2026.1.26	所检项目合格	


73	GX-B1372/26-F-260024~260043	2026.1.26	本次共检验甲烷传感器20台,20台所检项目合格。”	
74	GX-B1374/26-F-260044~260047	2026.1.23	本次共检验一氧化碳传感器4台,4台所检项目合格。”	

75	GX-B1542/26-F-26061~26066	2026.1.23	本次共检验光干涉式 甲烷测定器6台，6台 所检项目合格	
76	GX-B1603/26-F-26007	2026.1.23	所检项目合格。	

77	GX-B1568/22-F-26012~26020	2026.1.23	本次共检验矿用风速表9台,9台所检项目合格。	
78	GX-B1540/26-F-260089~260113	2026.1.23	本次共检验甲烷检测报警仪25台,25台所检项目合格。"	

79	GX-B1540/26-F-260139~260140	2026.1.23	本次共检验甲烷检测报警仪2台,2台所检项目合格。"	 A photograph showing two individuals in a laboratory or workshop. They are standing at a workbench with various pieces of equipment, including what appears to be a gas detector or similar instrument. One person is holding a device, and the other is looking at it. The date stamp in the bottom right corner of the photo is 2026.1.16.
80	GX-B1372/26-F-260045~260052	2026.1.23	本次共检验煤矿用低浓度载体催化式甲烷传感器8台,8台所检项目合格	 A photograph showing a person in a dark winter coat working at a laboratory bench. The person is looking at a piece of equipment, possibly a gas sensor, which is connected to a larger machine. The date stamp in the bottom right corner of the photo is 2026.1.15.

81	GX-B1568/26-F-26039~26046	2026.1.23	本次共检验矿用风速表8台，8台所检项目合格。	
82	GX-B1593/26-F-26032~26034	2026.1.29	本次共检验烟雾传感器3台，3台所检项目合格。	

83	GX-B1603/26-F-26008	2026.1.29	所检项目合格。	 <p>2026.1.21</p>
84	GX-B1528/26-F-26019~26028	2026.1.30	所检项目合格	 <p>2026.1.21</p>

85	GX-B1529/26-F-26036~26045	2026.1.30	所检项目合格	
86	GX-B1646/26-F-260159~260168	2026.1.30	所检项目合格	

87	GX-B1540/26-F-260148~260153	2026.1.30	所检项目合格	
88	GX-B1544/26-F-26002~26006	2026.1.30	所检项目合格	

89	GX-B1544/26-F-26007~26016	2026.1.30	所检项目合格	
90	GX-B1373/26-F-26005~26014	2026.1.29	所检项目合格	

91	GX-B1373/26-F-26001~26004	2026.1.29	所检项目合格	
92	GX-B1465/26-F-26001~26010	2026.1.29	所检项目合格	

93	GX-B1466/26-F-26001~26003	2026.1.29	所检项目合格	
94	GX-B1374/26-F-26012~26031	2026.1.29	所检项目合格	

95	GX-B1592/26-F-26004~26006	2026.1.29	所检项目合格	 <p>2026.1.4</p>
96	GX-B1374/26-F-26032~26043	2026.1.29	所检项目合格	 <p>2025.1.6</p>

97	GX-B1601/26-F-26009~26010	2026.1.29	所检项目合格	
98	GX-B1568/26-F-26047~26052	2026.1.29	所检项目合格	

99	GX-B1568/26-F-26053~26059	2026.1.29	所检项目合格	
100	GX-B1411/26-F-26002	2026.1.29	所检项目合格	

101	GX-B1571/26-F-26001	2026.1.29	所检项目合格	 <p>2026/1/23</p>
102	GX-B1412/26-F-26001~26002	2026.1.29	所检项目合格	 <p>2026/1/23</p>

103	GX-B1410/26-F-26003~26022	2026.1.29	所检项目合格	
104	GX-B1592/26-F-26010~26013	2026.1.29	本次共检验负压传感器4台，4台所检项目合格。	

105	GX-B1593/26-F-26043~26046	2026.1.29	本次共检验烟雾传感器4台，4台所检项目合格。	
106	GX-B1409/26-F-26002	2026.1.29	所检项目合格。	

107	GX-B1410/26-F-26023~26037	2026.1.29	本次共检验一氧化碳传感器15台，15台所检项目合格。	
108	GX-B1540/26-F-260079~260088	2026.1.28	所检项目合格	

109	GX-B1529/26-F-26009~26015	2026.1.26	所检项目合格	
110	GX-B1540/26-F-260056~260078	2026.1.28	所检项目合格	

111	GX-B1529/26-F-26001~26007	2026.1.26	所检项目合格	
112	GX-B1540/26-F-260009~260030	2026.1.28	所检项目合格	


113	GX-B1540/26-F-260031~260055	2026.1.28	所检项目合格	 <p>2026.1.11</p>
114	GX-B1542/26-F-26031~26041	2026.1.26	所检项目合格	 <p>2026.1.10</p>

115	GX-B1528/26-F-26006~26012	2026.1.26	所检项目合格	
116	GX-B1528/26-F-26001~26005	2026.1.26	所检项目合格	

117	GX-B1529/26-F-26019~26028	2026.1.26	所检项目合格	
118	GX-B1543/26-F-26001~26007	2026.1.26	所检项目合格	


119	GX-B1540/26-F-260001~260007	2026.1.28	所检项目合格	
120	GX-B1603/26-F-26001~26004	2026. 1. 30	所检项目合格	

121	GX-B1602/26-F-26002	2026.1.30	所检项目合格	
122	GX-B1593/26-F-26001~26028	2026.1.29	所检项目合格	

123	GX-B1592/26-F-26007~26008	2026.1.29	所检项目合格	 <p>2026/1/24</p>
124	GX-B1466/26-F-26004~26005	2026.1.29	所检项目合格	 <p>2026/1/15</p>

125	GX-B1543/26-F-26009~26010	2026.1.29	所检项目合格	 <p>2026/1/14</p>
126	GX-B1540/26-F-260114~260138	2026.1.29	所检项目合格	 <p>2026/1/15</p>

127	GX-B1540/26-F-260141~260147	2026.1.29	所检项目合格	
128	GX-B1529/26-F-26029~26035	2026.1.29	所检项目合格	

129	GX-B1593/26-F-26029	2026.1.29	所检项目合格	
130	GX-B1374/26-F-26048	2026.1.30	所检项目合格	


131	GX-B1372/26-F-260063~260065	2026.1.30	所检项目合格	
132	GX-B1605/26-F-26056~26075	2026.1.29	所检项目合格	

133	GX-B1605/26-F-26076~26090	2026.1.30	所检项目合格	
134	GX-B1606/26-F-26056~26075	2026.1.30	所检项目合格	

135	GX-B1606/26-F-26076~26090	2026.1.30	所检项目合格	 <p>2026.1.14</p>
136	GX-B1568/26-F-26069~26076	2026. 1. 30	所检项目合格	 <p>2026.1.15</p>

137	GX-B1542/26-F-26042~26060	2026. 1. 30	所检项目合格	
138	GX-B1593/21-F-26035~26036	2026.1.30	所检项目合格	

139	GX-B1592/26-F-26009	2026.1.30	所检项目合格	 <p>2026.1.16</p>
140	GX-B1593/26-F-26001~26028	2026. 1. 29	所检项目合格	 <p>2026/1/5</p>

141	GX-B1592/26-F-26007~26008	2026. 1. 29	所检项目合格	 <p>2026/1/14</p>
142	GX-B1466/26-F-26004~26005	2026. 1. 29	所检项目合格	 <p>2026/1/15</p>

143	GX-B1543/26-F-26009~26010	2026. 1. 29	所检项目合格	
144	GX-B1540/26-F-260114~260138	2026. 1. 29	所检项目合格	

145	GX-B1540/26-F-260141~260147	2026. 1. 29	所检项目合格	
146	GX-B1529/26-F-26029~26035	2026. 1. 29	所检项目合格	

147	GX-B1593/26-F-26029	2026. 1. 29	所检项目合格	
148	GX-B1374/26-F-26048	2026. 1. 30	所检项目合格	