

序号	报告编号	发布日期	结论	影像资料
45	GX-B1364/25-A-251191	2026/1/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1366/25-A-25135	2026/1/5	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
47	GX-B1364/25-A-251188	2026/1/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
48	GX-B1364/25-A-251187	2026/1/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
49	GX-B1364/25-A-251186	2026/1/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
50	GX-B1364/25-A-251184	2026/1/5	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
51	GX-B1364/25-A-251183	2026/1/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
52	GX-B1364/25-A-251182	2026/1/5	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
53	GX-B1363/25-A-26003	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
54	GX-B1363/25-A-26004	2026/1/12	所检项目合格。	 A photograph showing two workers in grey protective suits and yellow gloves inspecting a large, industrial furnace or oven. The furnace has a conical top and two large doors that are open. The workers are looking into the interior of the furnace. The date '2026.01.03' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
55	GX-B1363/25-A-26006	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
56	GX-B1363/25-A-26007	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
57	GX-B1363/25-A-26008	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
58	GX-B1363/25-A-26009	2026/1/12	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
59	GX-B1363/25-A-25646	2026/1/7	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
60	GX-B1363/25-A-25645	2026/1/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
61	GX-B1363/25-A-25643	2026/1/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
62	GX-B1367/22-A-25084	2026/1/6	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
63	GX-B1367/22-A-25083	2026/1/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
64	GX-B1363/25-A-25650	2026/1/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
65	GX-B1363/25-A-25649	2026/1/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
66	GX-B1363/25-A-25648	2026/1/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
67	GX-B1363/25-A-25644	2026/1/5	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
68	GX-B1363/25-A-25627	2026/1/7	阻燃带宽度 极限偏差见 报告，其余 所检项目合 格。	 A photograph showing two men in light-colored work jackets examining a large, complex industrial machine. The machine has a conical top section and several vertical panels. One panel is open, and the men are looking into it. The background is a clean, industrial setting. A date stamp '2025 12 31' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
69	GX-B1363/25-A-26005	2026/1/8	拉伸强度见 报告内页； 其余所检项 目合格。	

序号	报告编号	发布日期	结论	影像资料
70	GX-B1363/25-A-26001	2026/1/7	阻燃带宽度 极限偏差见 报告内页， 其余所检项 目合格。	 A photograph showing two technicians in a laboratory setting. They are wearing light-colored work jackets and are looking into a large, open metal furnace or testing chamber. The furnace has a conical top section. The date '2026.01.02' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
71	GX-B1363/25-A-26002	2026/1/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
72	GX-B1363/25-A-26003	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
73	GX-B1363/25-A-26004	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
74	GX-B1363/25-A-26006	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
75	GX-B1363/25-A-26007	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
76	GX-B1363/25-A-26008	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
77	GX-B1363/25-A-26009	2026/1/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
78	GX-B1365/25-A-26001	2026/1/12	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
79	GX-B1366/25-A-26001	2026/1/12	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
80	GX-B1365/25-A-26002	2026/1/13	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
81	GX-B1366/25-A-26002	2026/1/13	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
82	GX-B1364/26-A-26012	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
83	GX-B1364/26-A-26020	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
84	GX-B1364/26-A-26009	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
85	GX-B1364/26-A-26010	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
86	GX-B1364/26-A-26011	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
87	GX-B1364/26-A-26001	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
88	GX-B1364/26-A-26002	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
89	GX-B1364/26-A-26003	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
90	GX-B1364/26-A-26004	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
91	GX-B1364/26-A-26005	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
92	GX-B1364/26-A-26015	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
93	GX-B1364/26-A-26016	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
94	GX-B1364/26-A-26017	2026/1/14	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
95	GX-B1364/26-A-26018	2026/1/14	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
96	GX-B1364/26-A-26014	2026/1/14	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
97	GX-B1364/26-A-26013	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
98	GX-B1364/26-A-26019	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
99	GX-B1364/26-A-26021	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
100	GX-B1364/26-A-26022	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
101	GX-B1364/26-A-26023	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
102	GX-B1364/26-A-26024	2026/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
103	GX-B1363/25-A-26017	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
104	GX-B1363/25-A-26016	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
105	GX-B1363/25-A-26014	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
106	GX-B1363/25-A-26011	2026/1/14	所检项目合格。	 <p>2026.01.07</p>

序号	报告编号	发布日期	结论	影像资料
107	GX-B1363/25-A-26010	2026/1/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
108	GX-B1364/26-A-26006	2026/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
109	GX-B1364/26-A-26007	2026/1/14	所检项目合格。	 <p>The image shows two individuals in grey work uniforms with the '中检公信' (CIC) logo on the back, viewed from behind. They are standing in a laboratory or control room, looking at a computer monitor. On the wall behind them is a yellow triangular warning sign with the Chinese characters '高温' (High Temperature) and a symbol of three exclamation marks. A timestamp '2026.01.08' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
110	GX-B1364/26-A-26008	2026/1/14	所检项目合格。	