


| 序号 | 报告编号                | 发布日期     | 结论      | 影像资料  |
|----|---------------------|----------|---------|---|
| 1  | GX-B1310/21-5-26001 | 2026.2.2 | 符合标准要求。 | <br>2026.1.4   |
| 2  | GX-B1427/21-5-26002 | 2026.2.2 | 符合标准要求。 | <br>2026.1.11 |

|   |                     |          |                        |  |  |
|---|---------------------|----------|------------------------|--|--|
| 3 | GX-B1328/25-5-26020 | 2026.2.2 | 本次共检绝缘手套12只，12只绝缘手套合格。 |   |  |
| 4 | GX-B1328/25-5-26021 | 2026.2.2 | 本次共检绝缘靴12只，12只绝缘靴合格。   |  |  |

|   |                     |          |                        |   |
|---|---------------------|----------|------------------------|---|
| 5 | GX-B1328/25-5-26018 | 2026.2.2 | 本次共检绝缘手套20只，20只绝缘手套合格。 |  2026/1/30 |
| 6 | GX-B1328/25-5-26019 | 2026.2.2 | 本次共检绝缘靴20只，20只绝缘靴合格。   |  2026/1/30 |

|   |                     |          |                      |  |
|---|---------------------|----------|----------------------|--|
| 7 | GX-B1328/25-5-26024 | 2026.2.2 | 本次共检绝缘手套2只，2只绝缘手套合格。 |   |
| 8 | GX-B1328/25-5-26025 | 2026.2.2 | 本次共检绝缘靴2只，2只绝缘靴合格。   |  |

|    |                     |          |         |   |
|----|---------------------|----------|---------|---|
| 9  | GX-B1328/25-5-26026 | 2026.2.2 | 所检项目合格。 | <br>2026.1.30  |
| 10 | GX-B1328/25-5-26027 | 2026.2.2 | 所检项目合格。 | <br>2026.1.30 |

|    |                     |            |                           |   |
|----|---------------------|------------|---------------------------|---|
| 11 | GX-B1350/21-5-26002 | 2026年2月2日  | 本次共检验接地装置6处，6处接地装置所检项目合格。 |  |
| 12 | GX-B1625/24-5-26001 | 2026. 2. 3 | 所检项目合格                    |  |

|    |                     |          |         |  |
|----|---------------------|----------|---------|--|
| 13 | GX-B1310/21-5-26004 | 2026.2.6 | 符合标准要求。 |   |
| 14 | GX-B1310/21-5-26005 | 2026.2.6 | 符合标准要求。 |  |

|    |                     |          |         |  |
|----|---------------------|----------|---------|--|
| 15 | GX-B1310/21-5-26006 | 2026.2.6 | 符合标准要求。 | <br>2026/01/25  |
| 16 | GX-B1310/21-5-26007 | 2026.2.6 | 符合标准要求。 | <br>2026/01/25 |

|    |                     |          |         |  |  |
|----|---------------------|----------|---------|--|--|
| 17 | GX-B1310/21-5-26008 | 2026.2.6 | 符合标准要求。 |   |  |
| 18 | GX-B1310/21-5-26009 | 2026.2.6 | 符合标准要求。 |  |  |

|    |                     |          |         |  |  |
|----|---------------------|----------|---------|--|--|
| 19 | GX-B1310/21-5-26010 | 2026.2.6 | 符合标准要求。 | <br>2026/01/25  |  |
| 20 | GX-B1310/21-5-26011 | 2026.2.6 | 符合标准要求。 | <br>2026/01/25 |  |

|    |                     |          |         |   |
|----|---------------------|----------|---------|---|
| 21 | GX-B1310/21-5-26012 | 2026.2.6 | 符合标准要求。 |  A photograph showing two workers in a industrial setting. One worker is standing on a platform or walkway, wearing a red hard hat, a light-colored jacket, and a safety harness. The other worker is seated or working on a lower level, wearing a blue jacket and a safety harness. They are positioned around a large, dark, cylindrical industrial tank. The background shows a large building with windows and some equipment. A timestamp '2026/01/25' is visible in the bottom right corner of the image. |
| 22 | GX-B1310/21-5-26013 | 2026.2.6 | 符合标准要求。 |  A photograph of a worker in an industrial setting. The worker is wearing a red hard hat, a grey long-sleeved shirt, and a blue safety harness. They are leaning over, working on a piece of equipment that appears to be a large metal drum or tank. The worker is holding a small device, possibly a tablet or a tool, in their hands. The background shows an industrial landscape with other structures and equipment. A timestamp '2026/01/25' is visible in the bottom right corner of the image.         |