

序号	报告编号	发布日期	结论	影像资料
1	GX-B1489/21-B-26012	2026.2.5	所检项目合格	 2026.1.30
2	GX-B1378/22-B-26015	2026.2.5	所检项目合格	 2026.1.30

3	GX-B1378/22-B-26016	2026.2.5	所检项目合格	 2026.2.3
4	GX-B1378/22-B-26017	2026.2.5	所检项目合格	 2026.2.3

5	GX-B1460/22-B-26002	2026.2.5	所检项目合格	
6	GX-B1489/21-B-26013	2026.2.9	所检项目合格	

7	GX-B1492/21-B-26012	2026.2.9	所检项目合格	 A photograph showing two men in a laboratory setting. One man is standing and looking down at a large, white, cylindrical piece of equipment with a glass bell jar on top. The other man is seated behind the equipment. There are various bottles and containers on the counter next to the machine. A yellow warning sign is visible in the background. 2026.2.9	
8	GX-B1378/22-B-26018	2026.2.9	所检项目合格	 A photograph showing two men in a laboratory setting. One man is standing and looking down at a large, white, cylindrical piece of equipment with a glass bell jar on top. The other man is seated behind the equipment. There are various bottles and containers on the counter next to the machine. A yellow warning sign is visible in the background. 2026.2.4	

9	GX-B1377/22-B-26022~B-26023	2026.2.9	所检项目合格		 2026.2.2	
10	GX-B1489/21-B-26014	2026.2.9	所检项目合格		 2026.2.4	

11	GX-B1489/21-B-26017	2026.2.9	所检项目合格	 A photograph showing two men in dark jackets and glasses working on a large, white industrial machine. The machine has a prominent glass front panel. A yellow warning sign is visible on the right side of the machine. The date '2026.2.5' is printed in the bottom right corner of the photo.
12	GX-B1489/21-B-26018	2026.2.9	所检项目合格	 A photograph showing two men in dark jackets and glasses working on a large, white industrial machine. The machine has a prominent glass front panel. A yellow warning sign is visible on the right side of the machine. The date '2026.2.5' is printed in the bottom right corner of the photo.

13	GX-B1489/21-B-26015	2026.2.9	所检项目合格	 A photograph showing two men in a laboratory setting. One man is standing and operating a large white machine with a black hose attached. The other man is seated at a desk in the background, looking at a computer screen. The room has yellow curtains and a red warning sign on the wall.
14	GX-B1489/21-B-26016	2026.2.9	所检项目合格	 A photograph showing two men standing in a laboratory. They are positioned next to a large white industrial machine, possibly a vacuum pump or compressor. The room has yellow curtains and a white air conditioning unit on the left. A small table in front of the machine holds some tools and containers.

15	GX-B1377/22-B-26024	2026. 2. 9	所检项目合格	 2026.2.4
16	GX-B1378/22-B-26020~B-26023	2026. 2. 10	所检项目合格	 2026.2.9

17	GX-B1377/22-B-26025~B-26027	2026.2.10	所检项目合格	
18	GX-B1377/22-B-26028	2026.2.10	所检项目合格	

19	GX-B1488/21-B-26001	2026.2.10	所检项目合格	 2026.2.5
20	GX-B1377/22-B-26029~B-26030	2026.2.10	所检项目合格	 2026.2.9

21	GX-B1489/21-B-26019	2026.2.10	所检项目合格	 A photograph showing two men in dark jackets and glasses standing in a room with light-colored curtains. They are positioned behind a large, rectangular industrial machine with a control panel and various ports. A yellow container sits on the floor to the left. The date '2026.2.5' is visible in the bottom right corner of the photo.
22	GX-B1492/21-B-26013	2026.2.10	所检项目合格	 A photograph showing two men in dark jackets and glasses standing in a room with light-colored curtains. They are positioned behind a large, cylindrical industrial machine with a control panel and a clear protective cover. The date '2026.2.5' is visible in the bottom right corner of the photo.

23	GX-B1377/22-B-26031	2026.2.11	所检项目合格	 A photograph showing two men in a room with yellow curtains. One man is standing behind a large, light-colored industrial machine with a perforated metal panel. The other man is standing to his left, looking at the machine. The machine has some labels and a small date stamp "2026.2.10".
----	---------------------	-----------	--------	---