

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|-------------|--------|--|
| 58 | GX-B1310/21-1-26020 | 2026. 2. 11 | 符合标准要求 |  <p>2026/01/21</p> |
| 59 | GX-B1310/21-1-26021 | 2026. 2. 11 | 符合标准要求 |  <p>2026/01/21</p> |

| | | | | | | |
|----|---------------------|-------------|---------|--|--|--|
| 60 | GX-B1428/21-1-26012 | 2026. 2. 11 | 无缺陷迹痕显示 | |  <p>2026/1/21</p> | |
| 61 | GX-B1427/21-1-26020 | 2026. 2. 11 | 符合标准要求 | |  <p>2026/01/21</p> | |

| | | | | |
|----|---------------------|-------------|---------|---|
| 62 | GX-B1427/21-1-26021 | 2026. 2. 11 | 符合标准要求 |  <p>2026/01/20</p> |
| 63 | GX-B1350/21-1-26006 | 2026. 2. 11 | 所检项目合格。 |  <p>2026/2/2</p> |

| | | | | |
|----|---------------------------|-------------|----------------------------|--|
| 64 | GX-B1322/21-1-26048~26049 | 2026. 2. 11 | 本次共检验电力电缆2条，2条所检项目合格。 。 |  |
| 65 | GX-B1328/25-1-26024 | 2026. 2. 12 | 本次共检绝缘手套32只，32只绝缘手套合格。 |  |

| | | | | |
|----|---------------------|-------------|-------------------------------|--|
| 66 | GX-B1328/25-1-26025 | 2026. 2. 12 | 本次共检绝缘靴 36只，36只绝缘靴合格。 。 |  |
| 67 | GX-B1328/25-1-26026 | 2026. 2. 12 | 本次共检验电器 27支，27支验电器合格。 。 |  |

| | | | | |
|----|---------------------|-------------|---|--|
| 68 | GX-B1328/25-1-26027 | 2026. 2. 12 | 本次共检绝缘杆 14支，14支绝缘杆合格。 。 |  |
| 69 | GX-B1328/25-1-26028 | 2026. 2. 12 | 本次共检便携式接地 和接地短路装置 27组，27组便携式接地 和接地短路装置合格。 。 |  |

| | | | | |
|----|---------------------|-------------|-----------------------------|--|
| 70 | GX-B1328/25-1-26021 | 2026. 2. 12 | 本次共检绝缘手套 6只，6只绝缘手套合 格 |  |
| 71 | GX-B1328/25-1-26022 | 2026. 2. 12 | 本次共检绝缘靴6只， 6只绝缘靴合格 |  |

| | | | | |
|----|---------------------|-------------|--------------------|---|
| 72 | GX-B1328/25-1-26023 | 2026. 2. 12 | 本次共检绝缘杆2套, 2套合格 |  <p>2026.2.9</p> |
| 73 | GX-B1341/24-9-26009 | 2026年2月12日 | 综合判定：合格。 |  <p>2026年2月10日</p> |

| | | | | |
|----|---------------------|-------------|-------------------------|--|
| 74 | GX-B1328/25-1-26029 | 2026. 2. 12 | 本次共检绝缘手套 4只，4只绝缘手套合格 |  |
| 75 | GX-B1328/25-1-26030 | 2026. 2. 12 | 本次共检绝缘靴2只， 2只绝缘靴合格 |  |

| | | | | | |
|----|---------------------|-------------|-----------------------------------|--|---|
| 76 | GX-B1328/25-1-26031 | 2026. 2. 12 | 本次共检便携式接地和接地短路装置1套，1套便携式接地和接地短路装置 | |  A photograph showing a portable grounding and short-circuiting device in a laboratory or testing room. The device consists of a yellow metal frame with a circular component at the top. It is surrounded by safety barriers and caution tape. A date stamp '2026.2.9' is visible in the bottom right corner of the image. |
| 77 | GX-B1304/26-1-26001 | 2026. 2. 12 | 综合判定：合格 | |  A photograph showing a worker in an orange safety suit and red hard hat operating a large industrial machine. The machine is green and yellow. The worker is wearing a face mask. The background shows an industrial setting with other workers and equipment. A date stamp '2026.02.12' is visible in the bottom right corner of the image. |

| | | | | |
|----|---------------------|-------------|-------------------------|--|
| 78 | GX-B1304/26-1-26002 | 2026. 2. 12 | 综合判定：合格 |  |
| 79 | GX-B1328/25-1-26032 | 2026. 2. 12 | 本次共检绝缘手套 4只，4只绝缘手套合格 |  |

| | | | | |
|----|---------------------|-------------|-----------------------|--|
| 80 | GX-B1328/25-1-26033 | 2026. 2. 12 | 本次共检绝缘靴4只, 4只绝缘靴合格 |  |
| 81 | GX-B1328/25-1-26034 | 2026. 2. 12 | 本次共检验电器1支, 1支验电器合格 |  |

| | | | | |
|----|---------------------|-------------|---|--|
| 82 | GX-B1328/25-1-26035 | 2026. 2. 12 | 本次共检绝缘杆1套, 1套绝缘杆合格 |  |
| 83 | GX-B1328/25-1-26036 | 2026. 2. 12 | 本次共检便携式接地 和接地短路装置2套, 2套便携式接地和接地 短路装置合格 |  |

| | | | | | | |
|----|---------------------|-------------|--------|--|--|--|
| 84 | GX-B1310/21-1-26036 | 2026. 2. 21 | 符合标准要求 | |  | |
| 85 | GX-B1427/21-1-26037 | 2026. 2. 21 | 符合标准要求 | |  | |

| | | | | |
|----|---------------------|-------------|----------|--|
| 86 | GX-B1304/26-1-26004 | 2026. 2. 21 | 综合判定：合格。 |  |
| 87 | GX-B1310/21-1-26041 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | |
|----|---------------------|-------------|--------|--|
| 88 | GX-B1310/21-1-26042 | 2026. 2. 21 | 符合标准要求 |  |
| 89 | GX-B1310/21-1-26043 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | |
|----|---------------------|-------------|--------|--|
| 90 | GX-B1310/21-1-26034 | 2026. 2. 21 | 符合标准要求 |  <p>2026/02/15</p> |
| 91 | GX-B1310/21-1-26035 | 2026. 2. 21 | 符合标准要求 |  <p>2026/02/15</p> |

| | | | | |
|----|---------------------|-------------|--------|--|
| 92 | GX-B1310/21-1-26044 | 2026. 2. 21 | 符合标准要求 |  |
| 93 | GX-B1310/21-1-26045 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | | |
|----|---------------------|-------------|--------|--|---|
| 94 | GX-B1310/21-1-26046 | 2026. 2. 21 | 符合标准要求 | |  <p>2026/2/12</p> |
| 95 | GX-B1310/21-1-26038 | 2026. 2. 21 | 符合标准要求 | |  <p>2026/2/14</p> |

| | | | | |
|----|---------------------|-------------|--------|--|
| 96 | GX-B1310/21-1-26039 | 2026. 2. 21 | 符合标准要求 |  |
| 97 | GX-B1310/21-1-26040 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | |
|----|---------------------|-------------|--------|---|
| 98 | GX-B1310/21-1-26054 | 2026. 2. 21 | 符合标准要求 |  <p>A photograph showing a worker wearing a red hard hat and a grey work jacket standing next to a large, green industrial machine. The worker is looking towards the camera. The machine has a circular opening and various components. A yellow timestamp '2026/2/15' is visible in the bottom right corner of the image.</p> |
| 99 | GX-B1310/21-1-26055 | 2026. 2. 21 | 符合标准要求 |  <p>A photograph showing a worker wearing an orange hard hat and a grey work jacket standing on a metal structure, possibly a bridge or a walkway. The worker is looking towards the camera. The structure is made of metal beams and has a railing. In the background, there are hills and a clear sky. A yellow timestamp '2026/2/15' is visible in the bottom right corner of the image.</p> |

| | | | | |
|-----|---------------------|-------------|----------|--|
| 100 | GX-B1310/21-1-26056 | 2026. 2. 21 | 符合标准要求 |  <p>2026/2/15</p> |
| 101 | GX-B1305/21-1-26002 | 2026. 2. 21 | 综合判定：合格。 |  <p>2026.02.21</p> |

| | | | | |
|-----|---------------------|-------------|---------------------------------------|---|
| 102 | GX-B1598/24-1-26016 | 2026. 2. 21 | 实测钢丝绳有效截面积损失百分比最大为2.46%，小于5%为正常。 。 |  <p>2026.2.15</p> |
| 103 | GX-B1598/24-1-26017 | 2026. 2. 21 | 实测钢丝绳有效截面积损失百分比最大为2.10%，小于5%为正常。 。 |  <p>2026.2.15</p> |

| | | | | |
|-----|---------------------|-------------|---------------------------------------|--|
| 104 | GX-B1598/24-1-26018 | 2026. 2. 21 | 实测钢丝绳有效截面积损失百分比最大为2.15%，小于5%为正常。 。 |  |
| 105 | GX-B1598/24-1-26019 | 2026. 2. 21 | 实测钢丝绳有效截面积损失百分比最大为2.60%，小于5%为正常。 。 |  |

| | | | | | |
|-----|---------------------|-------------|---------------------------------------|--|--|
| 106 | GX-B1598/24-1-26020 | 2026. 2. 21 | 实测钢丝绳有效截面积损失百分比最大为2.41%，小于5%为正常。 。 | |  |
| 107 | GX-B1598/24-1-26021 | 2026. 2. 21 | 实测钢丝绳有效截面积损失百分比最大为2.49%，小于5%为正常。 。 | |  |

| | | | | |
|-----|---------------------|-------------|---------------------------------------|--|
| 108 | GX-B1598/24-1-26022 | 2026. 2. 21 | 实测钢丝绳有效截面积损失百分比最大为3.26%，小于5%为正常。 。 |  <p>2026.2.15</p> |
| 109 | GX-B1382/26-1-26002 | 2026. 2. 10 | 综合判定:合格。 |  <p>2026/02/03</p> |

| | | | | |
|-----|---------------------|-------------|----------|--|
| 110 | GX-B1382/26-1-26003 | 2026. 2. 21 | 综合判定:合格。 |  |
| 111 | GX-B1382/26-1-26004 | 2026. 2. 10 | 综合判定:合格。 |  |

| | | | | |
|-----|---------------------|-------------|----------|--|
| 112 | GX-B1382/26-1-26005 | 2026. 2. 10 | 综合判定:合格。 |  |
| 113 | GX-B1310/21-1-26051 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-------------|--------|---|
| 114 | GX-B1310/21-1-26052 | 2026. 2. 21 | 符合标准要求 |  <p>A worker wearing a red hard hat and a grey jacket is standing on a metal structure. To the right, there is a large, circular, metallic component, possibly a part of a turbine or a large wheel. The background shows more of the industrial structure. A yellow timestamp '2026/2/15' is visible in the bottom right corner of the photo.</p> |
| 115 | GX-B1310/21-1-26053 | 2026. 2. 21 | 符合标准要求 |  <p>A worker wearing a red hard hat and a grey jacket is kneeling on a metal structure. They are working on a large, circular, metallic component. The worker is wearing a safety harness. The background shows more of the industrial structure. A yellow timestamp '2026/2/15' is visible in the bottom right corner of the photo.</p> |

| | | | | |
|-----|---------------------|-------------|--------|---|
| 116 | GX-B1310/21-1-26013 | 2026. 2. 21 | 符合标准要求 |  A worker in a grey uniform and red hard hat is operating a large green industrial machine. The worker is wearing blue gloves and is looking towards the camera. The machine has a large red wheel and a yellow handle. The date 2026/2/2 is visible in the bottom right corner of the photo. |
| 117 | GX-B1310/21-1-26014 | 2026. 2. 21 | 符合标准要求 |  A worker in a grey uniform and red hard hat is standing next to a large green industrial machine. The worker is wearing a blue tie and is looking towards the camera. The machine has a large black wheel and a yellow handle. The date 2026/2/2 is visible in the bottom right corner of the photo. |

| | | | | |
|-----|---------------------|-------------|--------|--|
| 118 | GX-B1310/21-1-26015 | 2026. 2. 21 | 符合标准要求 |  |
| 119 | GX-B1427/21-1-26016 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-------------|----------|--|
| 120 | GX-B1303/21-1-26003 | 2026. 2. 21 | 综合判定：合格。 |  |
| 121 | GX-B1310/21-1-26047 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-------------|--------|--|
| 122 | GX-B1310/21-1-26048 | 2026. 2. 21 | 符合标准要求 |  |
| 123 | GX-B1310/21-1-26049 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 124 | GX-B1427/21-1-26050 | 2026. 2. 21 | 符合标准要求 |  <p>2026/2/15</p> |
| 125 | GX-B1380/26-1-26001 | 2026. 2. 10 | 所检项目合格。 |  <p>2026/02/02</p> |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 126 | GX-B1380/26-1-26002 | 2026. 2. 10 | 所检项目合格。 |  |
| 127 | GX-B1380/26-1-26003 | 2026. 2. 10 | 所检项目合格。 |  |

| | | | | | |
|-----|---------------------|-------------|---------|--|--|
| 128 | GX-B1380/26-1-26004 | 2026. 2. 10 | 所检项目合格。 | |  |
| 129 | GX-B1380/26-1-26005 | 2026. 2. 10 | 所检项目合格。 | |  |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 130 | GX-B1380/26-1-26006 | 2026. 2. 10 | 所检项目合格。 |  |
| 131 | GX-B1380/26-1-26007 | 2026. 2. 10 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 132 | GX-B1380/26-1-26008 | 2026. 2. 10 | 所检项目合格。 |  |
| 133 | GX-B1310/21-1-26017 | 2026. 2. 21 | 符合标准要求 |  |

| | | | | | |
|-----|---------------------|-------------|--------|--|--|
| 134 | GX-B1310/21-1-26018 | 2026. 2. 21 | 符合标准要求 | |  <p>2026/2/3</p> |
| 135 | GX-B1427/21-1-26019 | 2026. 2. 21 | 符合标准要求 | |  <p>2026/2/3</p> |

| | | | | |
|-----|---------------------|-------------|--------|--|
| 136 | GX-B1310/21-1-26022 | 2026. 2. 24 | 符合标准要求 |  |
| 137 | GX-B1310/21-1-26023 | 2026. 2. 24 | 符合标准要求 |  |

| | | | | |
|-----|---------------------|-------------|----------|--|
| 138 | GX-B1310/21-1-26024 | 2026. 2. 24 | 符合标准要求 |  |
| 139 | GX-B1382/26-1-26006 | 2026. 2. 21 | 综合判定:合格。 |  |

| | | | | |
|-----|---------------------|-------------|----------|--|
| 140 | GX-B1309/26-1-26002 | 2026. 2. 24 | 所检项目合格。 |  |
| 141 | GX-B1500/26-1-26016 | 2026. 2. 24 | 综合判定：合格。 |  |

| | | | | | | |
|-----|---------------------|-------------|----------|--|--|--|
| 142 | GX-B1500/26-1-26017 | 2026. 2. 24 | 综合判定：合格。 | |  | |
| 143 | GX-B1500/26-1-26018 | 2026. 2. 24 | 综合判定：合格。 | |  | |

| | | | | | | |
|-----|---------------------|-------------|----------|--|--|--|
| 144 | GX-B1500/26-1-26019 | 2026. 2. 24 | 综合判定：合格。 | |  <p>2026/02/04</p> | |
| 145 | GX-B1309/26-1-26003 | 2026. 2. 24 | 所检项目合格。 | |  <p>2026.02.24</p> | |

| | | | | | |
|-----|---------------------|-------------|----------|--|--|
| 146 | GX-B1500/26-1-26020 | 2026. 2. 24 | 综合判定：合格。 | |  |
| 147 | GX-B1500/26-1-26021 | 2026. 2. 24 | 综合判定：合格。 | |  |

| | | | | | | |
|-----|---------------------|-------------|----------|--|--|--|
| 148 | GX-B1500/26-1-26022 | 2026. 2. 24 | 综合判定：合格。 | |  | |
| 149 | GX-B1500/26-1-26023 | 2026. 2. 24 | 综合判定：合格。 | |  | |

| | | | | |
|-----|---------------------|-------------|----------|--|
| 150 | GX-B1303/21-1-26003 | 2026. 2. 21 | 综合判定：合格。 |  |
| 151 | GX-B1304/26-1-26004 | 2026. 2. 22 | 综合判定：合格。 |  |

| | | | | |
|-----|---------------------|-------------|----------|--|
| 152 | GX-B1303/21-1-26004 | 2026. 2. 21 | 综合判定：合格。 |  |
| 153 | GX-B1380/26-1-26009 | 2026. 2. 21 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|-------------|--------|---|
| 154 | GX-B1380/26-1-26011 | 2026. 2. 25 | 所检项目合格 |  |
|-----|---------------------|-------------|--------|---|