

序号	报告编号	发布日期	结论	影像资料
129	GX-B1601/26-F-26106~26107	2026.2.26	所检项目合格	
130	GX-B1374/26-F-26079~26081	2026.2.26	所检项目合格	

131	GX-B1373/26-F-26031~26032	2026.2.26	所检项目合格	
132	GX-B1603/26-F-26014~26015	2026.2.25	所检项目合格	

133	GX-B1593/26-F-26084~26091	2026.2.26	所检项目合格	
134	GX-B1593/26-F-26092~26098	2026.2.26	所检项目合格	

135	GX-B1593/26-F-26077~26083	2026.2.26	所检项目合格	
136	GX-B1595/26-F-26023~26033	2026.2.27	所检项目合格	


137	GX-B1595/26-F-26016~26022	2026. 2. 26	所检项目合格	
138	GX-B1595/26-F-26011~26015	2026. 2. 26	所检项目合格	

139	GX-B1372/26-F-260138~260143	2026.2.27	所检项目合格	 <p>A photograph showing two female technicians in a laboratory. They are wearing grey lab coats. One technician is operating a piece of equipment on a blue lab bench, while the other is holding and reviewing a document. The background features a fume hood and various laboratory glassware. A timestamp '2026/2/11' is visible in the bottom right corner of the image.</p>
140	GX-B1373/26-F-26033	2026.2.27	所检项目合格	 <p>A photograph showing two technicians in a laboratory. They are wearing grey lab coats. One technician is adjusting a piece of equipment mounted on a tripod, while the other is observing. The background features a blue lab bench and a brown door. A timestamp '2026/2/11' is visible in the bottom right corner of the image.</p>

141	GX-B1475/26-F-26017	2026.2.27	所检项目合格	
142	GX-B1595/26-F-26034~26044	2026.2.27	本次共检验粉尘采样器11台，11台所检项目合格。	

143	GX-B1602/26-F-26007~ F-26010	2026.2.26	本次共检验直读式粉尘浓度测量仪4台，4台所检项目合格	
144	GX-B1409/26-F-26008	2026.2.28	所检项目合格	

145	GX-B1410/26-F-26135	2026.2.28	所检项目合格	
146	GX-B1373/26-F-26033	2026.2.28	所检项目合格	

147	GX-B1593/26-F-26099~26100	2026.2.28	本次共检验烟雾传感器2台，2台所检项目合格。	
148	GX-B1374/26-F-26082~26087	2026.2.28	本次共检验一氧化碳传感器6台，6台所检项目合格。	

149	GX-B1373/26-F-26030	2026.2.28	所检项目合格	
150	GX-B1644/26-F-26001~26004	2026.2.28	所检项目合格	

151	GX-B1603/26-F-26016~26018	2026.2.28	所检项目合格	
-----	---------------------------	-----------	--------	---