

序号	报告编号	发布日期	结论	影像资料
1 8 3	GX-B1363/25-A-26064	2026/2/12	所检项目合格。	 A photograph showing two men in grey work jackets and white face masks inspecting a large, yellow industrial furnace. The furnace has a large, dark metal door that is open. The man on the left is looking into the furnace, while the man on the right is looking at a control panel. The date '2026.02.10' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
1 8 4	GX-B1366/25-A-26015	2026/2/12	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 5	GX-B1364/26-A-26096	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 6	GX-B1364/26-A-26097	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 7	GX-B1364/26-A-26098	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 8	GX-B1364/26-A-26099	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 9	GX-B1364/26-A-26106	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 0	GX-B1364/26-A-26100	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 1	GX-B1364/26-A-26101	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 2	GX-B1364/26-A-26102	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 3	GX-B1364/26-A-26103	2026/2/12	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 4	GX-B1364/26-A-26104	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 5	GX-B1364/26-A-26105	2026/2/12	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 6	GX-B1364/26-A-26107	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 7	GX-B1364/26-A-26095	2026/2/12	所检项目均不合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 8	GX-B1363/25-A-26065	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 9	GX-B1363/25-A-26066	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
200	GX-B1364/26-A-26109	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
201	GX-B1364/26-A-26110	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
202	GX-B1538/26-A-26006	2026/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
203	GX-B1363/25-A-26065	2026/2/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
204	GX-B1363/25-A-26066	2026/2/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
205	GX-B1363/25-A-26067	2026/2/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
206	GX-B1363/25-A-26070	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
207	GX-B1363/25-A-26068	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
208	GX-B1363/25-A-26069	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
209	GX-B1366/25-A-26016	2026/2/27	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
210	GX-B1364/26-A-26118	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 1 1	GX-B1364/26-A-26117	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 1 2	GX-B1364/26-A-26116	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 1 3	GX-B1364/26-A-26115	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 1 4	GX-B1364/26-A-26114	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 1 5	GX-B1364/26-A-26113	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 1 6	GX-B1364/26-A-26112	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 1 7	GX-B1364/26-A-26111	2026/2/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
218	GX-B1363/25-A-26068	2026/2/27	所检项目合格。	 A photograph showing two men in light-colored lab coats or work uniforms. They are standing in a laboratory or industrial setting, looking at a large, complex piece of machinery. The machine has a large, conical, metallic top section. One man is on the left, looking down at the machine, and the other is on the right, looking towards the camera. The date '2026.02.25' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
2 1 9	GX-B1363/25-A-26069	2026/2/27	所检项目合格。	