



序号	报告编号	发布日期	结论	影像资料
1	GX-B1382/26-1-26007	2026. 3. 2	综合判定:合格。	 A photograph showing two workers in safety gear (hard hats, high-visibility vests, and gloves) standing on an industrial platform or walkway. The background shows metal structures and pipes. A red timestamp '2026. 02. 10' is visible in the bottom right corner of the image.
2	GX-B1308/23-1-26002	2026. 3. 2	综合判定: 合格	 A photograph showing a worker in safety gear (hard hat, high-visibility vest, and gloves) working in a confined space, possibly a tunnel or underground area. The worker is illuminated by a bright light source, likely a headlamp. A yellow timestamp '2026/1/26' is visible in the bottom right corner of the image.

3	GX-B1303/21-1-26001	2026. 3. 3	综合判定：合格	
4	GX-B1303/21-1-26002	2026. 3. 3	综合判定：合格	

5	GX-B1303/21-1-26005	2026. 3. 3	综合判定：合格	
6	GX-B1305/21-1-26003	2026. 3. 4	综合判定：合格	

7	GX-B1305/21-1-26005	2026. 3. 4	综合判定：合格	 A photograph showing several workers in orange high-visibility safety suits and white hard hats. They are gathered around a large, dark, curved industrial component, possibly a turbine or part of a power plant. One worker in the foreground is holding a flashlight, illuminating the surface. A yellow date stamp '2026/02/26' is visible in the bottom right corner of the image.
8	GX-B1304/26-1-26005	2026. 3. 4	综合判定：合格	 A photograph of a worker in a red safety suit and red hard hat operating a piece of green industrial machinery. The worker is focused on the task. In the foreground, there is a yellow and black warning sign with a gear icon, indicating a rotating part. A yellow date stamp '26.' is visible in the bottom right corner of the image.

9	GX-B1303/21-1-26006	2026. 3. 4	综合判定：合格	
10	GX-B1303/21-1-26007	2026. 3. 4	综合判定：合格	

11	GX-B1303/21-1-26008	2026. 3. 5	综合判定：合格	
12	GX-B1310/21-1-26072	2026. 3. 5	符合标准要求	

13	GX-B1310/21-1-26073	2026. 3. 5	符合标准要求	
14	GX-B1310/21-1-26074	2026. 3. 5	符合标准要求	

15	GX-B1310/21-1-26075	2026. 3. 5	符合标准要求			
16	GX-B1310/21-1-26076	2026. 3. 5	符合标准要求			

17	GX-B1310/21-1-26077	2026. 3. 5	符合标准要求		 <p>2026/2/26</p>
18	GX-B1310/21-1-26057	2026. 3. 4	符合标准要求		 <p>2026/2/26</p>

19	GX-B1310/21-1-26058	2026. 3. 4	符合标准要求	
20	GX-B1310/21-1-26059	2026. 3. 4	符合标准要求	

21	GX-B1310/21-1-26060	2026. 3. 4	符合标准要求			
22	GX-B1310/21-1-26061	2026. 3. 4	符合标准要求			

23	GX-B1310/21-1-26062	2026. 3. 4	符合标准要求	 <p>2026/2/23</p>
24	GX-B1310/21-1-26063	2026. 3. 4	符合标准要求	 <p>2026/2/24</p>

25	GX-B1310/21-1-26064	2026. 3. 4	符合标准要求		 A photograph showing a worker in a red safety vest and white hard hat standing in a tunnel. The worker is positioned next to a large piece of machinery, possibly a conveyor or a pump. The tunnel walls are dark and rocky. A yellow timestamp '2026/2/24' is visible in the bottom right corner of the image.	
26	GX-B1310/21-1-26065	2026. 3. 4	符合标准要求		 A photograph showing a worker in a red safety vest and white hard hat kneeling in a tunnel. The worker is working on a piece of machinery, possibly a pump or a conveyor. The tunnel walls are dark and rocky. A yellow timestamp '2026/2/24' is visible in the bottom right corner of the image.	

27	GX-B1310/21-1-26066	2026. 3. 4	符合标准要求	 <p>2026/2/24</p>
28	GX-B1310/21-1-26067	2026. 3. 4	符合标准要求	 <p>2026/2/24</p>

29	GX-B1310/21-1-26068	2026. 3. 4	符合标准要求	
30	GX-B1310/21-1-26069	2026. 3. 4	符合标准要求	

31	GX-B1310/21-1-26070	2026. 3. 4	符合标准要求		 <p>2026/2/25</p>
32	GX-B1310/21-1-26071	2026. 3. 4	符合标准要求		 <p>2026/2/25</p>