

序号	报告编号	发布日期	结论	影像资料
1	GX-B1313/26-5-26021~26025	2026. 3. 3	本次共检电力变压器5台，5台电力变压器所检项目合格。	
2	GX-B1350/21-5-26004	2026. 3. 3	本次共检验接地装置1处，1处接地装置所检项目合格。	

3	GX-B1328/26-5-26028	2026. 3. 3	本次共检绝缘手套2只，2只绝缘手套合格。		
4	GX-B1328/26-5-26029	2026. 3. 3	本次共检绝缘靴2只，2只绝缘靴合格。		

5	GX-B1328/26-5-26030	2026. 3. 3	本次共检绝缘杆1组， 1组绝缘杆合格。	
6	GX-B1328/26-5-26031	2026. 3. 3	本次共检验电器1个， 1个验电器合格。	

7	GX-B1328/26-5-26032	2026. 3. 3	本次共检便携式接地和接地短路装置1套，1套便携式接地和接地短路装置合格。	
8	GX-B1307/26-5-26001	2026. 3. 3	综合判定：合格。	

9	GX-B1307/26-5-26002	2026. 3. 3	综合判定：合格。	
10	GX-B1323/21-5-26054~26058	2026. 3. 3	所检项目合格。	

11	GX-B1323/21-5-26059~26065	2026. 3. 3	所检项目合格。	 A worker wearing a hard hat and safety gear is operating a piece of machinery in a dark, possibly underground, environment. The worker is positioned on the left side of the frame, facing right. The machinery is complex and appears to be part of a larger system. A date stamp '2026. 1. 16' is visible in the bottom right corner of the image.
12	GX-B1323/21-5-26076~26080	2026. 3. 3	所检项目合格。	 A worker wearing a hard hat and safety gear is operating a piece of machinery in a well-lit industrial setting. The worker is positioned on the left side of the frame, facing right. The machinery is large and complex, with various components and pipes. The background shows a long, narrow corridor with overhead lights and other equipment. A date stamp '2026. 1. 18' is visible in the bottom right corner of the image.

13	GX-B1323/21-5-26035~26038	2026. 3. 3	所检项目合格。	
14	GX-B1323/21-5-26039~26045	2026. 3. 3	所检项目合格。	 

15	GX-B1323/21-5-26046~26049	2026. 3. 3	所检项目合格。	
16	GX-B1323/21-5-26050~26053	2026. 3. 3	所检项目合格。	