

序号	报告编号	发布日期	结论	影像资料
1	GX-B1377/22-B-26032	2026. 3. 2	所检项目合格	
2	GX-B1377/22-B-26038~B-26040	2026. 3. 5	所检项目合格	

3	GX-B1377/22-B-26041	2026. 3. 5	所检项目合格	
4	GX-B1377/22-B-26042	2026. 3. 5	所检项目合格	

5	GX-B1377/22-B-26033	2026. 3. 5	所检项目合格	 A photograph showing two men in a laboratory or workshop. They are standing behind a piece of equipment, possibly a testing machine, and looking at it. The man on the left is wearing a grey jacket and glasses, and the man on the right is wearing a dark jacket. The background shows a clean, well-lit room with a door and some equipment.
6	GX-B1377/22-B-26034	2026. 3. 5	本次共检变压器绝缘油油样1个，1个油样不合格。	 A photograph showing a man in a grey jacket working in a laboratory. He is standing at a bench, looking at some equipment. The background shows a window with orange curtains and some laboratory equipment.

7	GX-B1377/22-B-26035~B-26037	2026. 3. 5	所检项目合格	
8	GX-B1378/22-B-26024~B-26025	2026. 3. 5	所检项目合格	

9	GX-B1377/22-B-26043~B-26045	2026. 3. 5	所检项目合格	
---	-----------------------------	------------	--------	---