





序号	报告编号	发布日期	结论	影像资料
95	GX-B1310/21-2-26101	2026. 3. 7	符合标准要求。	 A photograph showing two workers in black safety suits and red hard hats standing on a metal platform. The platform has two large yellow wheels. The background shows an industrial setting with various pipes and structures. A timestamp '2026/02/12' is visible in the bottom right corner of the image.
96	GX-B1310/21-2-26102	2026. 3. 7	符合标准要求。	 A photograph showing two workers in black safety suits and red hard hats standing in an industrial environment. They are positioned near a large piece of machinery or a structure. The background shows various pipes and structural elements. A timestamp '2026/02/12' is visible in the bottom right corner of the image.

97	GX-B1350/21-2-26006	2026. 3. 7	所检项目合格	
98	GX-B1350/21-2-26007	2026. 3. 7	所检项目合格	

99	GX-B1350/21-2-26009	2026. 3. 7	所检项目合格	 <p>2026/02/06</p>
100	GX-B1574/20-2-26001	2026. 3. 7	所检项目合格	 <p>2026/01/19</p>

101	GX-B1309/26-2-26002	2026. 3. 7	所检项目合格	 <p>A photograph showing a worker in a bright orange safety suit and yellow helmet standing on a green metal staircase inside a tunnel. The worker is leaning over a large, dark-colored pipe, likely inspecting it. The tunnel walls are rough and rocky, and there are some lights visible in the distance. A timestamp '2026/02/04' is visible in the bottom right corner of the image.</p>
102	GX-B1309/26-2-26006	2026. 3. 7	所检项目合格	 <p>A photograph showing two workers in bright orange safety suits and yellow helmets in an industrial setting. One worker is standing and looking towards the camera, while the other is kneeling on the floor, possibly working on a piece of equipment. The background shows various pipes, electrical panels, and machinery. A timestamp '2026/02/04' is visible in the bottom right corner of the image.</p>

103	GX-B1500/26-2-26017	2026. 3. 7	综合判定：合格	
104	GX-B1500/26-2-26018	2026. 3. 7	综合判定：合格	

105	GX-B1500/26-2-26019	2026. 3. 7	综合判定：合格	 <p>2026/02/04</p>
106	GX-B1500/26-2-26020	2026. 3. 7	综合判定：合格	 <p>2026/02/04</p>

107	GX-B1500/26-2-26034	2026. 3. 7	综合判定：合格	 A photograph showing two workers in orange safety suits and yellow hard hats standing in an industrial setting. They are positioned near large machinery and pipes. The worker on the right is holding a clipboard. A timestamp '2026/02/03' is visible in the bottom right corner of the image.
108	GX-B1500/26-2-26035	2026. 3. 7	综合判定：合格	 A photograph showing two workers in orange safety suits and yellow hard hats standing in an industrial setting. They are positioned near large machinery and pipes. The worker on the right is holding a clipboard. A timestamp '2026/02/03' is visible in the bottom right corner of the image.

109	GX-B1500/26-2-26036	2026. 3. 7	综合判定：合格	 <p>2026/02/03</p>
110	GX-B1500/26-2-26037	2026. 3. 7	综合判定：合格	 <p>2026/02/04</p>

111	GX-B1515/22-2-26002	2026. 3. 7	滚筒绳衬直径与钢丝绳直径之比小于50倍。除上述问题外，其余所检项目合格。	 <p>2026/01/27</p>
112	GX-B1324/26-2-26001~26004	2026/3/2	所检项目合格。	 <p>2026/02/06</p>

113	GX-B1310/21-2-26106	2026/3/9	符合标准要求。	 <p>2026/2/12</p>
114	GX-B1310/21-2-26107	2026/3/9	符合标准要求。	 <p>2026/2/12</p>

115	GX-B1310/21-2-26108	2026/3/9	符合标准要求。	
116	GX-B1310/21-2-26109	2026/3/9	符合标准要求。	

117	GX-B1310/21-2-26110	2026/3/9	符合标准要求。	
118	GX-B1310/21-2-26111	2026/3/9	符合标准要求。	

119	GX-B1310/21-2-26112	2026/3/9	符合标准要求。	 <p>2026/2/13</p>
120	GX-B1310/21-2-26113	2026/3/9	符合标准要求。	 <p>2026/2/13</p>

121	GX-B1310/21-2-26114	2026/3/9	符合标准要求。	 <p>2026/2/13</p>
122	GX-B1310/21-2-26115	2026/3/9	符合标准要求。	 <p>2026/2/13</p>

123	GX-B1310/21-2-26116	2026/3/9	符合标准要求。		 <p>2026/2/13</p>	
124	GX-B1310/21-2-26117	2026/3/9	符合标准要求。		 <p>2026/2/13</p>	

125	GX-B1500/26-2-26030	2026. 3. 11	综合判定：合格	
126	GX-B1500/26-2-26031	2026. 3. 11	综合判定：合格	

127	GX-B1500/26-2-26032	2026. 3. 11	综合判定：合格	 <p>2025/02/07</p>
128	GX-B1500/26-2-26033	2026. 3. 11	综合判定：合格	 <p>2025/02/07</p>

129	GX-B1500/26-2-26021	2026/3/6	综合判定：合格。	 <p>2026/2/6</p>
130	GX-B1500/26-2-26022	2026/3/6	综合判定：合格。	 <p>2026/2/6</p>

131	GX-B1500/26-2-26023	2026/3/6	综合判定：合格。	 <p>2026/2/6</p>
132	GX-B1309/26-2-26003	2026/3/6	所检项目合格。	 <p>2026/2/6</p>

133	GX-B1310/21-2-26118	2026. 3. 7	符合标准要求。	
134	GX-B1310/21-2-26119	2026. 3. 7	符合标准要求。	

135	GX-B1310/21-2-26120	2026. 3. 7	符合标准要求。	
136	GX-B1310/21-2-26121	2026. 3. 7	符合标准要求。	

137	GX-B1310/21-2-26122	2026. 3. 8	符合标准要求。	 <p>2026/03/03</p>
138	GX-B1310/21-2-26123	2026. 3. 8	符合标准要求。	 <p>2026/03/03</p>

139	GX-B1310/21-2-26124	2026. 3. 8	符合标准要求。	
140	GX-B1310/21-2-26125	2026. 3. 8	符合标准要求。	

141	GX-B1310/21-2-26126	2026. 3. 8	符合标准要求。	 <p>2026/03/03</p>
142	GX-B1428/21-2-26126	2026. 3. 8	无缺陷迹痕显示。	 <p>2026/03/03</p>

143	GX-B1310/21-2-26127	2026. 3. 8	符合标准要求。	
144	GX-B1428/21-2-26127	2026. 3. 8	无缺陷痕迹显示。	

145	GX-B1310/21-2-26128	2026. 3. 8	符合标准要求。	
146	GX-B1428/21-2-26128	2026. 3. 8	无缺陷迹痕显示。	



147	GX-B1310/21-2-26129	2026. 3. 8	符合标准要求。	
148	GX-B1428/21-2-26129	2026. 3. 8	无缺陷迹痕显示。	



149	GX-B1310/21-2-26132	2026. 3. 13	符合标准要求。	 <p>2026/03/02</p>
150	GX-B1309/26-2-26005	2026. 3. 13	所检项目合格。	 <p>2026/03/09</p>

151	GX-B1500/26-2-26027	2026. 3. 13	综合判定：合格。	
152	GX-B1500/26-2-26028	2026. 3. 13	综合判定：合格。	

153	GX-B1500/26-2-26029	2026. 3. 13	综合判定：合格。	
154	GX-B1307/26-2-26001	2026. 3. 14	综合判定：合格。	

155	GX-B1307/26-2-26002	2026. 3. 14	综合判定：合格。	
156	GX-B1307/26-2-26003	2026. 3. 14	综合判定：合格。	

157	GX-B1307/26-2-26004	2026. 3. 14	综合判定：合格。	
158	GX-B1307/26-2-26005	2026. 3. 14	综合判定：合格。	

159	GX-B1307/26-2-26006	2026. 3. 14	综合判定：合格。		
160	GX-B1307/26-2-26007	2026. 3. 14	综合判定：合格。		

161	GX-B1350/21-2-26008	2026. 3. 14	所检项目合格			
162	GX-B1380/26-2-26008	2026. 3. 12	所检项目合格			