

序号	报告编号	发布日期	结论	影像资料
103	GX-B1310/21-3-26111	2026. 3. 5	符合标准要求。	
104	GX-B1310/21-3-26114	2026. 3. 5	符合标准要求。	

105	GX-B1310/21-3-26046	2026. 3. 6	符合标准要求。	
106	GX-B1310/21-3-26049	2026. 3. 6	符合标准要求。	

107	GX-B1310/21-3-26052	2026. 3. 6	符合标准要求。	
108	GX-B1310/21-3-26118	2026. 3. 6	符合标准要求。	

109	GX-B1310/21-3-26121	2026. 3. 6	符合标准要求。	
110	GX-B1310/21-3-26112	2026. 3. 5	符合标准要求。	

111	GX-B1310/21-3-26113	2026. 3. 5	符合标准要求。	
112	GX-B1427/21-3-26026	2026. 3. 5	符合标准要求。	

113	GX-B1310/21-3-26115	2026. 3. 5	符合标准要求。			
114	GX-B1427/21-3-26027	2026. 3. 5	符合标准要求。			

115	GX-B1310/21-3-26116	2026. 3. 5	符合标准要求。		
116	GX-B1310/21-3-26044	2026. 3. 6	符合标准要求。		

117	GX-B1310/21-3-26045	2026. 3. 6	符合标准要求。	
118	GX-B1310/21-3-26119	2026. 3. 6	符合标准要求。	

119	GX-B1310/21-3-26120	2026. 3. 6	符合标准要求。		 A worker wearing a red hard hat and a grey work jacket is shown in a close-up, working on a metal structure. The worker is looking towards the camera. A yellow timestamp '2026.2.22' is visible in the bottom right corner of the photo.	
120	GX-B1427/21-3-26028	2026. 3. 6	符合标准要求。		 A worker wearing a red hard hat and a grey work jacket is standing in an industrial setting. The worker is looking towards the camera. A yellow timestamp '2026.2.22' is visible in the bottom right corner of the photo.	

121	GX-B1310/21-3-26047	2026. 3. 6	符合标准要求。	 A worker wearing a red hard hat, safety glasses, and a grey work jacket with a red safety harness is standing on a steel structure. The worker is holding a tool or device. A yellow date stamp '2026.2.23' is visible in the bottom right corner of the photo.
122	GX-B1310/21-3-26048	2026. 3. 6	符合标准要求。	 A worker wearing a red hard hat, safety glasses, and a grey work jacket is crouching on a metal platform. The worker is looking towards the camera. A large, dark, circular metal component is visible next to the worker. A yellow date stamp '2026.2.23' is visible in the bottom right corner of the photo.

123	GX-B1427/21-3-26014	2026. 3. 6	符合标准要求。	 A photograph of a worker wearing a red hard hat, safety glasses, and a grey work jacket with an orange safety harness. The worker is standing on a metal structure, possibly a staircase or platform, with a date stamp '2026.2.23' in the bottom right corner.
124	GX-B1310/21-3-26050	2026. 3. 6	符合标准要求。	 A photograph of a worker wearing a red hard hat, safety glasses, and a grey work jacket with an orange safety harness. The worker is working on a metal structure, possibly a staircase or platform, with a date stamp '2026.2.23' in the bottom right corner.

125	GX-B1310/21-3-26051	2026. 3. 6	符合标准要求。		
126	GX-B1427/21-3-26015	2026. 3. 6	符合标准要求。		

127	GX-B1427/21-3-26013	2026. 3. 6	符合标准要求。	
128	GX-B1382/26-3-26011	2026. 3. 6	综合判定：合格。	

129	GX-B1382/26-3-26012	2026. 3. 6	综合判定：合格。		 A photograph of a worker wearing a grey work jacket, dark pants, and a red hard hat. The worker is standing on a red safety mat in an industrial environment. In the background, there are metal structures and other workers. A yellow timestamp '2025.2.22' is visible in the bottom right corner of the photo.
130	GX-B1382/26-3-26013	2026. 3. 6	综合判定：合格。		 A photograph of a worker wearing a grey work jacket, dark pants, and a red hard hat. The worker is standing in an industrial setting, possibly near a large piece of machinery or a lift. A yellow timestamp '2025.2.22' is visible in the bottom right corner of the photo.

131	GX-B1382/26-3-26014	2026. 3. 6	综合判定：合格。	
132	GX-B1382/26-3-26015	2026. 3. 6	综合判定：合格。	

133	GX-B1382/26-3-26016	2026. 3. 6	综合判定：合格。	
134	GX-B1380/26-3-26031	2026. 3. 6	所检项目合格。	

135	GX-B1380/26-3-26032	2026. 3. 6	所检项目合格。	
136	GX-B1380/26-3-26033	2026. 3. 6	所检项目合格。	

137	GX-B1380/26-3-26034	2026. 3. 6	所检项目合格。	
138	GX-B1380/26-3-26035	2026. 3. 6	所检项目合格。	

139	GX-B1380/26-3-26036	2026. 3. 6	所检项目合格。		 <p>2026.2.23</p>
140	GX-B1310/21-3-26145	2026. 3. 6	符合标准要求		 <p>2026.2.28</p>

141	GX-B1310/21-3-26148	2026. 3. 6	符合标准要求			
142	GX-B1310/21-3-26150	2026. 3. 6	符合标准要求			

143	GX-B1310/21-3-26152	2026. 3. 6	符合标准要求			
144	GX-B1310/21-3-26154	2026. 3. 6	符合标准要求			

145	GX-B1310/21-3-26146	2026. 3. 6	符合标准要求	
146	GX-B1310/21-3-26147	2026. 3. 6	符合标准要求	

147	GX-B1427/21-3-26036	2026. 3. 6	符合标准要求	
148	GX-B1310/21-3-26149	2026. 3. 6	符合标准要求	

149	GX-B1310/21-3-26151	2026. 3. 6	符合标准要求	
150	GX-B1310/21-3-26153	2026. 3. 6	符合标准要求	

151	GX-B1310/21-3-26155	2026. 3. 6	符合标准要求	
152	GX-B1382/26-3-26020	2026. 3. 5	综合判定：合格。	

153	GX-B1380/26-3-26038	2026. 3. 6	所检项目合格。	
154	GX-B1305/21-3-26004	2026. 3. 8	综合判定：合格。	

155	GX-B1305/21-3-26006	2026. 3. 8	综合判定：合格。	
156	GX-B1305/21-3-26007	2026. 3. 8	综合判定：合格。	

157	GX-B1303/21-3-26008	2026. 3. 8	综合判定：合格。	
158	GX-B1303/21-3-26009	2026. 3. 7	综合判定：合格。	

159	GX-B1303/21-3-26016	2026. 3. 8	综合判定：合格。	
160	GX-B1305/21-3-26009	2026. 3. 6	综合判定：合格。	

161	GX-B1305/21-3-26010	2026. 3. 6	综合判定：合格。	
162	GX-B1305/21-3-26011	2026. 3. 6	综合判定：合格。	

163	GX-B1598/24-3-26017	2026. 3. 7	实测钢丝绳有效截面积损失百分比最大为1.99%，小于5%为正常。	
164	GX-B1598/24-3-26018	2026. 3. 7	实测钢丝绳有效截面积损失百分比最大为1.95%，小于5%为正常。	

165	GX-B1598/24-3-26019	2026. 3. 7	实测钢丝绳有效截面积损失百分比最大为1.51%，小于5%为正常。	
166	GX-B1598/24-3-26020	2026. 3. 7	实测钢丝绳有效截面积损失百分比最大为2.09%，小于5%为正常。	

167	GX-B1598/24-3-26021	2026. 3. 7	实测钢丝绳有效截面积损失百分比最大为2.04%，小于5%为正常。	 <p>2026/02/14</p>
168	GX-B1598/24-3-26022	2026. 3. 7	实测钢丝绳有效截面积损失百分比最大为1.63%，小于5%为正常。	 <p>2026/02/14</p>

169	GX-B1598/24-3-26023	2026. 3. 7	实测钢丝绳有效截面积损失百分比最大为2.54%，小于5%为正常。	 <p>2026.02.14</p>
170	GX-B1303/26-3-26017	2026. 3. 10	综合判定：合格。	 <p>2026.03.04</p>

171	GX-B1427/21-3-26037	2026. 3. 10	符合标准要求	 <p>2026.03.04</p>
172	GX-B1310/21-3-26161	2026. 3. 10	符合标准要求	 <p>2026.03.04</p>



173	GX-B1310/21-3-26162	2026. 3. 10	符合标准要求		 <p>2026.03.04</p>	
174	GX-B1310/21-3-26163	2026. 3. 10	符合标准要求		 <p>2026.03.04</p>	



175	GX-B1303/26-3-26018	2026. 3. 11	综合判定：合格。	 <p>2026.03.08</p>
176	GX-B1313/26-3-26047~26048	2026. 3. 10	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2026.02.05</p>

177	GX-B1313/26-3-26049~26050	2026. 3. 10	本次共检电力变压器2台，2台电力变压器所检项目合格。		 <p>2026.02.06</p>	
178	GX-B1313/26-3-26055	2026. 3. 10	所检项目合格。		 <p>2026.02.06</p>	

179	GX-B1313/26-3-26060~26061	2026. 3. 10	本次共检电力变压器2台，2台电力变压器所检项目合格。	
180	GX-B1451/20-3-26127~26142	2026. 3. 10	本次共检高压开关设备16台，16台高压开关设备所检项目合格。	



181	:GX-B1451/20-3-26143~26149	2026. 3. 10	本次共检高压开关设备7台，7台高压开关设备所检项目合格。	 <p>2026.02.06</p>
182	:GX-B1451/20-3-26150~25164	2026. 3. 10	本次共检高压开关设备15台，15台高压开关设备所检项目合格。	 <p>2025.02.06</p>

183	GX-B1451/20-3-26170~26181	2026. 3. 10	本次共检高压开关设备12台，12台高压开关设备所检项目合格。	 <p>2026.02.07</p>
184	GX-B1598/24-3-26030	2026. 3. 10	实测钢丝绳有效截面积损失百分比最大为0.42%，小于5%为正常。	 <p>2026. 3. 5</p>



185	GX-B1598/24-3-26031	2026. 3. 10	实测钢丝绳有效截面积损失百分比最大为0.45%，小于5%为正常。 。	
186	GX-B1598/24-3-26032	2026. 3. 10	实测钢丝绳有效截面积损失百分比最大为0.43%，小于5%为正常。 。	

187	GX-B1598/24-3-26033	2026. 3. 10	实测钢丝绳有效截面积损失百分比最大为0.48%，小于5%为正常。	 A worker wearing a red helmet and a safety harness is pointing towards a blue steel structure. Another worker is partially visible in the background. The date '2026. 3. 5' is visible in the bottom right corner of the image.
188	GX-B1382/26-3-26021	2026. 3. 10	综合判定：合格。	 A worker wearing a red helmet and safety harness is standing in front of a blue steel structure. Another worker is visible in the background. The date '2026.03.04' is visible in the bottom right corner of the image.

189	GX-B1380/26-3-26039	2026. 3. 10	所检项目合格。			
190	GX-B1380/26-3-26040	2026. 3. 10	所检项目合格。			

191	GX-B1310/21-3-26166	2026. 3. 11	符合标准要求。		
192	GX-B1310/21-3-26167	2026. 3. 11	符合标准要求。		

193	GX-B1310/21-3-26168	2026. 3. 11	符合标准要求。		 <p>2026.03.08</p>	
194	GX-B1310/21-3-26169	2026. 3. 11	符合标准要求。		 <p>2026.03.08</p>	

195	GX-B1598/24-3-26024	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为0.85%，小于5%为正常。	 <p>2026. 2. 13</p>
196	GX-B1598/24-3-26025	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为0.92%，小于5%为正常。	 <p>2026. 2. 13</p>



197	GX-B1598/24-3-26026	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为0.89%，小于5%为正常。	
198	GX-B1598/24-3-26027	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为0.94%，小于5%为正常。	

199	GX-B1598/24-3-26028	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为3.85%，小于5%为正常。	
200	GX-B1598/24-3-26029	2026. 3. 11	实测钢丝绳有效截面积损失百分比最大为3.90%，小于5%为正常。	

201	GX-B1427/21-3-26038	2026. 3. 11	符合标准要求	
202	GX-B1310/21-3-26170	2026. 3. 11	符合标准要求	

203	GX-B1310/21-3-26171	2026. 3. 11	符合标准要求	 <p>2026.03.05</p>
204	GX-B1310/21-3-26172	2026. 3. 11	符合标准要求	 <p>2026.03.05</p>

205	GX-B1329/21-3-26084~26086	2026. 3. 12	本次共检氧化锌避雷器3组，3组氧化锌避雷器所检项目合格。	 <p>2026. 2. 25</p>
206	GX-B1328/26-3-26047	2026. 3. 12	本次共检绝缘手套4只，4只绝缘手套合格。	 <p>2026. 2. 25</p>

207	GX-B1328/26-3-26048	2026. 3. 12	本次共检绝缘靴4只， 4只绝缘靴合格。	 <p>2026. 2. 25</p>
208	GX-B1328/26-3-26049	2026. 3. 12	本次共检验电器2支， 2支验电器合格。	 <p>2026. 2. 25</p>

209	GX-B1328/26-3-26050	2026. 3. 12	本次共检便携式接地和接地短路装置2套，2套便携式接地和接地短路装置合格。	
210	GX-B1451/26-3-26200~26202	2026. 3. 12	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	

211	GX-B1313/26-3-26066	2026. 3. 12	所检项目合格。			
212	GX-B1324/26-3-26056	2026. 3. 12	所检项目合格。			

213	GX-B1328/26-3-26039	2026. 3. 12	本次共检绝缘手套42只，42只绝缘手套合格。		
214	GX-B1328/26-3-26040	2026. 3. 12	本次共检绝缘靴42只，42只绝缘靴合格。		

215	GX-B1328/26-3-26041	2026. 3. 12	本次共检验电器 10支，10支验电器合格。 。	
216	GX-B1328/26-3-26042	2026. 3. 12	本次共检便携式接地 和接地短路装置 22套，22套便携式接地 和接地短路装置合格。 。	

217	GX-B1328/26-3-26043	2026. 3. 12	本次共检绝缘杆2组， 2组绝缘杆合格。	
218	GX-B1328/26-3-26044	2026. 3. 12	本次共检绝缘胶垫10 件，10件绝缘胶垫合 格。	


219	GX-B1350/21-3-26004	2026. 3. 12	本次共检验接地装置7处，7处所检项目合格。	
220	GX-B1350/21-3-26005	2026. 3. 12	本次共检验接地装置20处，20处所检项目合格。	

221	GX-B1350/21-3-26006	2026. 3. 12	本次共检验接地装置 11处，11处所检项目合格。	
222	GX-B1322/26-3-26057~26058	2026. 3. 12	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	

223	GX-B1329/26-3-26043~26052	2026. 3. 12	本次共检氧化锌避雷器10组，10组氧化锌避雷器所检项目合格。	
224	GX-B1329/26-3-26053~26067	2026. 3. 12	本次共检氧化锌避雷器15组，15组氧化锌避雷器所检项目合格。	

225	GX-B1329/26-3-26070~26073	2026. 3. 12	本次共检氧化锌避雷器4组，4组氧化锌避雷器所检项目合格。	 <p>2026.02.25</p>
226	GX-B1451/26-3-26189~26192	2026. 3. 12	本次共检高压开关设备4台，4台高压开关设备所检项目合格。	 <p>2026.02.25</p>

227	GX-B1324/26-3-26054	2026. 3. 13	所检项目合格。	 A photograph showing two workers in safety gear (hard hats and jackets) working on electrical equipment. One worker is kneeling and using a tool on a device on the floor, while the other stands nearby. The equipment is connected to a power source. A timestamp '2026.02.25' is visible in the bottom right corner of the photo.
228	GX-B1313/26-3-26064	2026. 3. 12	所检项目合格。	 A photograph of a worker in safety gear (yellow hard hat and brown jacket) standing next to a large electrical transformer. The worker is looking towards the camera. The transformer is a large, cylindrical unit with cooling fins. A timestamp '2026.02.25' is visible in the bottom right corner of the photo.

229	GX-B1350/21-3-26009	2026. 3. 13	本次共检验接地装置2处，2处所检项目合格。	
230	GX-B1322/26-3-26138~26141	2026. 3. 13	本次共检电力电缆4条，4条电力电缆所检项目合格。	

231	GX-B1322/26-3-26107~26108	2026. 3. 12	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	
232	GX-B1322/26-3-26109~26118	2026. 3. 12	本次共检电力电缆10 条，10条电力电缆所 检项目合格。	

233	GX-B1322/26-3-26122~26131	2026. 3. 12	本次共检电力电缆10条，10条电力电缆所检项目合格。	 <p>2026.02.06</p>
234	GX-B1322/26-3-26132~26137	2026. 3. 12	本次共检电力电缆6条，6条电力电缆所检项目合格。	 <p>2026.02.07</p>