

序号	报告编号	发布日期	结论	影像资料
42	GX-B1382/26-4-26001	2026. 3. 4	所检项目合格	 <p>2026/2/13</p>
43	GX-B1382/26-4-26002	2026. 3. 4	所检项目合格	 <p>2026/2/14</p>

44	GX-B1382/26-4-26003	2026. 3. 4	所检项目合格	 A photograph showing three workers in an industrial environment. Two workers on the left and right are wearing dark blue uniforms with orange safety stripes and red hard hats. The worker in the center is wearing a grey work jacket and a red hard hat. They are standing in front of a large piece of machinery with yellow and black safety railings. A red timestamp '2026/2/14' is visible in the bottom right corner of the photo.
45	GX-B1380/26-4-26007	2026. 3. 3	所检项目合格	 A photograph showing two workers in an industrial setting. Both workers are wearing blue uniforms with orange safety stripes and blue hard hats. They are standing on a metal platform or walkway next to a large piece of machinery. A red timestamp '2026/2/15' is visible in the bottom right corner of the photo.

46	GX-B1380/26-4-26001	2026. 3. 4	所检项目合格	
47	GX-B1380/26-4-26002	2026. 3. 4	所检项目合格	

48	GX-B1380/26-4-26003	2026. 3. 4	所检项目合格	 <p>2026/2/7</p>
49	GX-B1313/26-4-26026~26030	2026/3/4	本次共检电力变压器5台，5台电力变压器所检项目合格。	 <p>2026/2/8</p>



50	GX-B1313/26-4-26031~26035	2026/3/4	本次共检电力变压器5台，5台电力变压器所检项目合格。	
51	GX-B1380/26-4-26004	2026. 3. 4	所检项目合格	

52	GX-B1380/26-4-26005	2026. 3. 4	所检项目合格		 A photograph showing two workers in safety gear (hard hats, high-visibility vests, and boots) inspecting a structure. One worker is holding a flashlight. The structure appears to be a metal frame or scaffolding. A red timestamp '2026/2/13' is visible in the bottom right corner of the image.
53	GX-B1380/26-4-26006	2026. 3. 4	所检项目合格		 A photograph showing a worker in safety gear (hard hat, high-visibility vest, and boots) inspecting a structure. The worker is holding a flashlight. The structure appears to be a metal frame or scaffolding. A red timestamp '2026/2/14' is visible in the bottom right corner of the image.

54	GX-B1328/26-4-26029	2026. 3. 10	本次共检绝缘手套 2只，2只绝缘手套合 格。	
55	GX-B1328/26-4-26030	2026. 3. 10	本次共检绝缘靴2只， 2只绝缘靴合格。	

56	GX-B1328/26-4-26031	2026. 3. 10	本次共检验电器1支， 1支验电器合格。	
57	GX-B1328/26-4-26026	2026. 3. 10	本次共检绝缘手套20 只，20只绝缘手套合 格。	

58	GX-B1328/26-4-26027	2026. 3. 10	本次共检绝缘靴 20只，20只绝缘靴合格。 。	 <p>2026.3.3</p>
59	GX-B1500/26-4-26005	2026. 3. 13	综合判定：合格。	 <p>2026. 2. 10</p>

60	GX-B1500/26-4-26006	2026. 3. 13	综合判定：合格。	
61	GX-B1304/26-4-26011	2026. 3. 13	综合判定：合格。	

62	GX-B1380/26-4-26008	2026. 3. 13	所检项目合格	 A photograph showing two workers in blue uniforms and hard hats (one red, one blue) inspecting a structure in a confined space. The worker in the foreground is holding a clipboard and looking at the camera. The worker in the background is looking towards the structure. The date '2026/2/15' is visible in the bottom right corner of the photo.
----	---------------------	-------------	--------	--