

序号	报告编号	发布日期	结论	影像资料
58	GX-B1350/21-7-26001	2026/3/5	本次共检接地装置18处, 18处所检项目合格。	 <p>鄂尔多斯市国润矿业开发有限公司 2026/02/07</p>
59	GX-B1310/21-7-26006	2026/3/6	符合标准要求	 <p>2026/01/23</p>


60	GX-B1310/21-7-26007	2026/3/6	符合标准要求	 <p>2026/01/23</p>
61	GX-B1310/21-7-26008	2026/3/6	符合标准要求	 <p>2026/01/23</p>

62	GX-B1428/21-7-26008	2026/3/6	无缺陷迹痕显示	
63	GX-B1310/21-7-26009	2026/3/6	符合标准要求	

64	GX-B1428/21-7-26009	2026/3/6	无缺陷迹痕显示	
65	GX-B1304/26-7-26003	2026/3/9	综合判定：合格。	

66	GX-B1304/26-7-26001	2026/3/9	综合判定：合格。	
67	GX-B1598/24-7-26007	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.28%，小于5%为正常。	

68	GX-B1598/24-7-26008	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.42%，小于5%为正常。	
69	GX-B1598/24-7-26009	2026/3/9	实测钢丝绳有效截面积损失百分比最大为2.04%，小于5%为正常。	

70	GX-B1598/24-7-26010	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.93%，小于5%为正常。	
71	GX-B1598/24-7-26011	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.04%，小于10%为正常。	

72	GX-B1598/24-7-26012	2026/3/9	实测钢丝绳有效截面积损失百分比最大为1.41%，小于10%为正常。	
73	GX-B1598/24-7-26001	2026/3/9	实测钢丝绳有效截面积损失百分比最大为3.18%，小于5%为正常。	

74	GX-B1598/24-7-26002	2026/3/9	实测钢丝绳有效截面积损失百分比最大为4.33%，小于5%为正常。	
75	GX-B1598/24-7-26003	2026/3/9	实测钢丝绳有效截面积损失百分比最大为4.74%，小于5%为正常。	

76	GX-B1598/24-7-26004	2026/3/9	实测钢丝绳有效截面积损失百分比最大为4.69%，小于5%为正常。	
77	GX-B1310/21-7-26013	2026. 3. 11	符合标准要求	

78	GX-B1310/21-7-26014	2026. 3. 11	符合标准要求	
79	GX-B1310/21-7-26015	2026. 3. 11	符合标准要求	

80	GX-B1310/21-7-26016	2026. 3. 11	符合标准要求		
81	GX-B1310/21-7-26017	2026. 3. 11	符合标准要求		

82	GX-B1310/21-7-26018	2026. 3. 11	符合标准要求		
83	GX-B1310/21-7-26019	2026. 3. 11	符合标准要求		

84	GX-B1310/21-7-26020	2026. 3. 11	符合标准要求	
85	GX-B1310/21-7-26021	2026. 3. 11	符合标准要求	

86	GX-B1310/21-7-26025	2026. 3. 11	符合标准要求	 <p>2026. 2. 26</p>
87	GX-B1310/21-7-26026	2026. 3. 11	符合标准要求	 <p>2026. 2. 26</p>

88	GX-B1310/21-7-26027	2026. 3. 11	符合标准要求	
89	GX-B1310/21-7-26028	2026. 3. 11	符合标准要求	

90	GX-B1310/21-7-26029	2026. 3. 11	符合标准要求	 <p>2026. 2. 27</p>
91	GX-B1310/21-7-26030	2026. 3. 11	符合标准要求	 <p>2026. 2. 27</p>

92	GX-B1328/26-7-26006	2026. 3. 13	本次共检绝缘手套 4只，4只绝缘手套合 格。	
93	GX-B1328/26-7-26007	2026. 3. 13	本次共检绝缘靴4只， 4只绝缘靴合格。	

94	GX-B1495/26-7-26468~26488	2026. 3. 15	本次共检高压开关柜21台，21台高压开关柜所检项目合格。	
95	GX-B1312/26-7-26111~26112	2026. 3. 15	本次共检电力变压器2台，2台电力变压器所检项目合格。	



96	GX-B1312/26-7-26113	2026. 3. 15	所检项目合格。	
97	GX-B1321/26-7-26123~26126	2026. 3. 15	本次共检电力电缆 4条，4条电力电缆所 检项目合格。	

98	GX-B1380/26-7-26001	2026/3/13	所检项目合格。	
99	GX-B1380/26-7-26002	2026/3/13	所检项目合格。	

100	GX-B1380/26-7-26003	2026/3/13	所检项目合格。	
101	GX-B1380/26-7-26004	2026/3/13	所检项目合格。	

102	GX-B1380/26-7-26005	2026/3/13	所检项目合格。	
103	GX-B1380/26-7-26006	2026/3/13	所检项目合格。	

104	GX-B1382/26-7-26001	2026/3/13	综合判定：合格。	
105	GX-B1382/26-7-26002	2026/3/13	综合判定：合格。	

106	GX-B1382/26-7-26003	2026/3/13	综合判定：合格。			
107	GX-B1382/26-7-26004	2026/3/13	综合判定：合格。			

108	GX-B1382/26-7-26005	2026/3/13	综合判定：合格。	
109	GX-B1305/21-7-26002	2026/3/13	综合判定：合格。	