










序号	报告编号	发布日期	结论	影像资料
33	GX-B1362/23-A-26113	2026/3/6	合格	
34	GX-B1362/23-A-26114	2026/3/6	合格	



35	GX-B1362/23-A-26115	2026/3/6	合格	
36	GX-B1362/23-A-26116	2026/3/6	合格	

37	GX-B1362/23-A-26145	2026/3/6	合格	
38	GX-B1362/23-A-26158	2026/3/9	合格	

39	GX-B1362/23-A-26159	2026/3/9	合格	
40	GX-B1362/23-A-26162	2026/3/9	合格	

41	GX-B1362/23-A-26169	2026/3/9	合格	
42	GX-B1362/23-A-26160	2026/3/9	不合格	


43	GX-B1362/23-A-26161	2026/3/9	不合格	
44	GX-B1362/23-A-26163	2026/3/9	合格	

45	GX-B1362/23-A-26164	2026/3/9	合格	
46	GX-B1362/23-A-26165	2026/3/9	合格	



47	GX-B1362/23-A-26166	2026/3/9	合格	
48	GX-B1362/23-A-26167	2026/3/9	合格	

49	GX-B1362/23-A-26122	2026/3/9	合格	
50	GX-B1362/23-A-26123	2026/3/9	合格	



51	GX-B1362/23-A-26124	2026/3/9	合格	
52	GX-B1362/23-A-26125	2026/3/9	合格	



53	GX-B1362/23-A-26126	2026/3/9	合格	
54	GX-B1362/23-A-26127	2026/3/9	合格	

55	GX-B1362/23-A-26128	2026/3/9	所检项目合格	
56	GX-B1362/23-A-26129	2026/3/9	所检项目合格	


57	GX-B1362/23-A-26130	2026/3/9	所检项目合格	
58	GX-B1362/23-A-26131	2026/3/9	所检项目合格	


59	GX-B1362/23-A-26132	2026/3/9	所检项目合格	
60	GX-B1362/23-A-26133	2026/3/9	所检项目合格	

61	GX-B1362/23-A-26134	2026/3/9	合格	
62	GX-B1362/23-A-26135	2026/3/9	合格	

63	GX-B1362/23-A-26136	2026/3/9	合格	
64	GX-B1362/23-A-26137	2026/3/9	合格	



65	GX-B1362/23-A-26138	2026/3/9	合格	
66	GX-B1362/23-A-26139	2026/3/9	合格	

67	GX-B1362/23-A-26140	2026/3/9	合格	
68	GX-B1362/23-A-26141	2026/3/9	合格	

69	GX-B1362/23-A-26142	2026/3/9	合格	
70	GX-B1362/23-A-26143	2026/3/9	合格	



71	GX-B1362/23-A-26144	2026/3/9	所检项目合格	
72	GX-B1362/23-A-26168	2026/3/10	合格	



73	GX-B1362/23-A-26170	2026/3/10	合格	
74	GX-B1362/23-A-26171	2026/3/10	合格	

75	GX-B1362/23-A-26172	2026/3/10	合格	 A photograph showing a worker in a light-colored uniform operating a large industrial machine. Another worker is standing nearby, observing the process. The date stamp '2026/3/9' is visible in the bottom right corner of the image.
76	GX-B1362/23-A-26175	2026/3/10	所检项目合格	 A photograph showing a worker in a light-colored uniform inspecting a component on a workbench. Another worker is visible in the background, operating a machine. The date stamp '2026/3/9' is visible in the bottom right corner of the image.

77	GX-B1362/23-A-26176	2026/3/10	所检项目合格	
78	GX-B1362/23-A-26146	2026/3/11	所检项目合格	



79	GX-B1362/23-A-26147	2026/3/11	所检项目合格	
80	GX-B1362/23-A-26148	2026/3/11	所检项目合格	

81	GX-B1362/23-A-26149	2026/3/11	所检项目合格	
82	GX-B1362/23-A-26150	2026/3/11	所检项目合格	



83	GX-B1362/23-A-26151	2026/3/11	所检项目合格	
84	GX-B1362/23-A-26177	2026/3/11	所检项目合格	



85	GX-B1362/23-A-26188	2026/3/11	所检项目合格	
86	GX-B1362/23-A-26189	2026/3/11	所检项目合格	

87	GX-B1362/23-A-26190	2026/3/11	所检项目合格	
88	GX-B1362/23-A-26191	2026/3/11	最小钢丝破断拉力总和1567.05kN，其余所检项目合格。	

89	GX-B1362/23-A-26192	2026/3/11	最小钢丝破断拉力总和1569.58kN，其余所检项目合格。	
90	GX-B1362/23-A-26193	2026/3/11	最小钢丝破断拉力总和1560.28kN，其余所检项目合格。	

91	GX-B1362/23-A-26194	2026/3/11	最小钢丝破断拉力总和1552.86kN，其余所检项目合格。	
92	GX-B1361/26-A-26110	2026/3/11	合格	

93	GX-B1361/26-A-26111	2026/3/11	合格	
94	GX-B1361/26-A-26112	2026/3/11	合格	



95	GX-B1362/23-A-26173	2026/3/11	合格	
96	GX-B1362/23-A-26174	2026/3/11	合格	

97	GX-B1362/23-A-26152	2026/3/13	所检项目合格	
98	GX-B1362/23-A-26153	2026/3/13	所检项目合格	



99	GX-B1362/23-A-26154	2026/3/13	所检项目合格	
100	GX-B1362/23-A-26155	2026/3/13	所检项目合格	

101	GX-B1362/23-A-26156	2026/3/13	所检项目合格	
102	GX-B1362/23-A-26157	2026/3/13	所检项目合格	

103	GX-B1362/23-A-26178	2026/3/12	合格	
104	GX-B1362/23-A-26179	2026/3/12	合格	

105	GX-B1362/23-A-26180	2026/3/12	合格	
106	GX-B1362/23-A-26181	2026/3/12	合格	

107	GX-B1362/23-A-26182	2026/3/12	合格	
108	GX-B1362/23-A-26183	2026/3/12	合格	



109	GX-B1362/23-A-26184	2026/3/12	合格	
110	GX-B1362/23-A-26185	2026/3/12	合格	

111	GX-B1362/23-A-26186	2026/3/13	所检项目合格	 A photograph showing two men in grey work uniforms working in a workshop. They are positioned around a large, light-colored industrial machine. One man is leaning over the machine, while the other stands beside him, looking on. A yellow timestamp '2026/3/12' is visible in the bottom right corner of the image.
112	GX-B1362/23-A-26195	2026/3/13	不合格	 A photograph showing two men in grey work uniforms in a workshop. The man in the foreground is focused on a large, perforated metal component resting on a workbench. The second man is standing behind him, looking towards the machine. A yellow timestamp '2026/3/12' is visible in the bottom right corner of the image.

113	GX-B1362/23-A-26196	2026/3/13	所检项目合格	
114	GX-B1362/23-A-26197	2026/3/13	所检项目合格	

115	GX-B1362/23-A-26198	2026/3/13	所检项目合格	
116	GX-B1362/23-A-26199	2026/3/13	合格	

117	GX-B1362/23-A-26200	2026/3/13	不合格	
118	GX-B1362/23-A-26201	2026/3/16	合格	

119	GX-B1362/23-A-26202	2026/3/16	不合格	
120	GX-B1362/23-A-26203	2026/3/16	合格	

121	GX-B1362/23-A-26187	2026/3/16	合格	
-----	---------------------	-----------	----	---