



序号	报告编号	发布日期	结论	影像资料
163	GX-B1313/26-2-26033~26035	2026/3/17	所检项目合格。	 <p>2026/02/07</p>
164	GX-B1309/26-2-26007	2026. 3. 16	所检项目合格	 <p>2026/02/04</p>

165	GX-B1309/26-2-26008	2026. 3. 16	所检项目合格	
166	GX-B1500/26-2-26038	2026. 3. 16	综合判定：合格	

167	GX-B1500/26-2-26039	2026. 3. 16	综合判定：合格	
168	GX-B1500/26-2-26040	2026. 3. 16	综合判定：合格	

169	GX-B1500/26-2-26041	2026. 3. 16	综合判定：合格	
170	GX-B1500/26-2-26042	2026. 3. 16	综合判定：合格	

171	GX-B1500/26-2-26043	2026. 3. 16	综合判定：合格	
172	GX-B1500/26-2-26044	2026. 3. 16	综合判定：合格	

173	GX-B1500/26-2-26045	2026. 3. 16	综合判定：合格		 A photograph showing a worker in an orange protective suit and yellow hard hat operating a large piece of industrial machinery. The worker is standing on a metal grate platform. The machinery is blue and green. A date stamp '2026/02/04' is visible in the bottom right corner of the image.
174	GX-B1500/26-2-26046	2026. 3. 16	综合判定：合格		 A photograph showing a worker in an orange protective suit and yellow hard hat operating a large piece of industrial machinery. The worker is standing on a metal grate platform. The machinery is blue and green. A date stamp '2026/02/04' is visible in the bottom right corner of the image.

175	GX-B1328/26-2-26041	2026. 3. 13	本次共检绝缘手套80只，80只绝缘手套合格。	
176	GX-B1328/26-2-26042	2026. 3. 13	本次共检绝缘鞋80只，80只绝缘鞋合格。	

177	GX-B1500/26-2-26024	2026/3/17	综合判定：合格。	 A photograph showing two workers in blue uniforms and red hard hats in a tunnel. They are standing next to a large green industrial machine with various pipes and valves. The machine has a sign that says '新用' (Newly Used). The date '2026/02/08' is visible in the bottom right corner of the photo.
178	GX-B1500/26-2-26025	2026/3/17	综合判定：合格。	 A photograph showing two workers in blue uniforms and red hard hats in a tunnel. They are standing next to a large green industrial machine with various pipes and valves. The machine has a sign that says '新用' (Newly Used). The date '2026/02/08' is visible in the bottom right corner of the photo.

179	GX-B1500/26-2-26026	2026/3/17	综合判定：合格。		 A photograph showing three workers in a tunnel. They are wearing dark work clothes and hard hats (one red, one blue, one yellow). They are standing near a piece of machinery, possibly a generator or motor, with various pipes and cables around it. The tunnel walls are rough and grey. A date stamp '2026/02/08' is visible in the bottom right corner of the photo.
180	GX-B1309/26-2-26004	2026/3/17	所检项目合格。		 A photograph showing two workers in a tunnel. They are wearing dark work clothes and red hard hats. They are standing on a concrete platform or step. There is a piece of equipment on the ground in front of them. The tunnel walls are rough and grey. A date stamp '2026/02/08' is visible in the bottom right corner of the photo.

181	GX-B1309/26-2-26007	2026. 3. 16	所检项目合格		 <p>2026/02/04</p>	
182	GX-B1309/26-2-26008	2026. 3. 16	所检项目合格		 <p>2026/02/04</p>	

183	GX-B1500/26-2-26038	2026. 3. 16	综合判定：合格	 <p>2026/02/03</p>
184	GX-B1500/26-2-26039	2026. 3. 16	综合判定：合格	 <p>2026/02/03</p>

185	GX-B1500/26-2-26040	2026. 3. 16	综合判定：合格			
186	GX-B1500/26-2-26041	2026. 3. 16	综合判定：合格			

187	GX-B1500/26-2-26042	2026. 3. 16	综合判定：合格	
188	GX-B1500/26-2-26043	2026. 3. 16	综合判定：合格	

189	GX-B1500/26-2-26044	2026. 3. 16	综合判定：合格		
190	GX-B1500/26-2-26045	2026. 3. 16	综合判定：合格		

191	GX-B1500/26-2-26046	2026. 3. 16	综合判定：合格		 <p>2026/02/04</p>
192	GX-B1328/26-2-26041	2026. 3. 13	本次共检绝缘手套80只，80只绝缘手套合格。		 <p>2026/02/03</p>



193	GX-B1328/26-2-26042	2026. 3. 13	本次共检绝缘鞋 80只，80只绝缘鞋合格。 。	
194	GX-B1313/26-2-26033~26035	2026/3/17	所检项目合格。	



195	GX-B1500/26-2-26024	2026/3/17	综合判定：合格。	 A photograph showing two workers in blue uniforms and red hard hats standing next to a large green industrial machine in a tunnel. The machine is connected to a network of pipes. A date stamp '2026/02/08' is visible in the bottom right corner of the image.
196	GX-B1500/26-2-26025	2026/3/17	综合判定：合格。	 A photograph showing two workers in blue uniforms and red hard hats standing next to a large green industrial machine in a tunnel. The machine is connected to a network of pipes. A date stamp '2026/02/08' is visible in the bottom right corner of the image.



197	GX-B1500/26-2-26026	2026/3/17	综合判定：合格。		 A photograph showing three workers in a tunnel. They are wearing dark work clothes and hard hats (one red, one blue, one yellow). They are standing near a piece of machinery, possibly a generator or motor, with various pipes and cables around it. The tunnel walls are rough and grey. A date stamp '2026/02/08' is visible in the bottom right corner of the photo.
198	GX-B1309/26-2-26004	2026/3/17	所检项目合格。		 A photograph showing two workers in a tunnel. They are wearing dark work clothes and red hard hats. They are standing on a concrete platform or step. There is a piece of equipment, possibly a generator or motor, on the platform. The tunnel walls are rough and grey. A date stamp '2026/02/08' is visible in the bottom right corner of the photo.



199	GX-B1304/26-2-26013	2026/3/17	综合判定：合格。	 <p>2026/2/9</p>
200	GX-B1322/26-2-26087~26090	2026. 3. 18	所检项目合格	 <p>2026/03/04</p>


201	GX-B1451/26-2-26180~26201	2026. 3. 18	所检项目合格	 A photograph showing several workers in a control room or substation. They are wearing red hard hats and dark work clothes. One worker in the foreground is wearing a grey jacket and a red hard hat with a headlamp. They are standing near a control panel with various buttons and screens. The date stamp '2026/03/04' is visible in the bottom right corner of the photo.
202	GX-B1451/26-2-26202~26206	2026. 3. 18	所检项目合格	 A photograph of a worker in a grey jacket and red hard hat kneeling on the floor next to a control panel. The worker is looking towards the camera. The control panel has various buttons and labels. The date stamp '2026/03/05' is visible in the bottom right corner of the photo.

203	GX-B1329/26-2-26041~26066	2026. 3. 18	所检项目合格	
204	GX-B1328/26-2-26031	2026. 3. 20	合格	

205	GX-B1328/26-2-26032	2026. 3. 20	合格	 <p>2026/02/05</p>
206	GX-B1328/26-2-26033	2026. 3. 20	合格	 <p>2026/02/05</p>

207	GX-B1328/26-2-26034	2026. 3. 20	合格	 A photograph of an indoor room with green epoxy flooring. In the foreground, there is a red plastic stool and a yellow bucket. A person wearing a red hard hat and dark clothing is sitting on the floor in the background. On the wall, there is a banner with the Chinese characters '工匠精神' (Craftsmanship Spirit) and a row of small framed pictures. A date stamp '2026/02/05' is visible in the bottom right corner of the photo.
208	GX-B1328/26-2-26035	2026. 3. 20	合格	 A photograph of the same room as above, showing the green floor, red stool, yellow bucket, and person in the background. The banner and framed pictures are also visible. A date stamp '2026/02/05' is present in the bottom right corner.

209	GX-B1328/26-2-26050	2026. 3. 20	合格	
210	GX-B1328/26-2-26051	2026. 3. 20	合格	

211	GX-B1328/26-2-26052	2026. 3. 20	合格	
212	GX-B1328/26-2-26053	2026. 3. 20	合格	

213	GX-B1304/26-2-26014	2026/3/20	综合判定：合格。	 <p>2026/02/09</p>
214	GX-B1380/26-2-26011	2026/3/20	所检项目合格。	 <p>03月 07 2026.03.07 星期六 福建省龙岩市漳平市芦芝镇673县道</p>

215	GX-B1350/21-2-26012	2026. 3. 23	所检项目合格。	 A worker in a blue uniform and red helmet is kneeling on a green surface, operating a piece of equipment. The date 2026.3.10 is visible in the bottom right corner of the photo.
216	GX-B1350/21-2-26013	2026. 3. 23	所检项目合格。	 A worker in a blue uniform and red helmet is kneeling in a dark tunnel, using a flashlight to inspect a surface. The date 2026.3.11 is visible in the bottom right corner of the photo.

217	GX-B1322/26-2-26091~26100	2026. 3. 23	本次共检电力电缆10条，10条电力电缆所检项目合格。	
218	GX-B1322/26-2-26101~26113	2026. 3. 23	本次共检电力电缆13条，13条电力电缆所检项目合格。	

219	GX-B1322/26-2-26114~26117	2026. 3. 23	本次共检电力电缆 4条，4条电力电缆所 检项目合格。	
220	GX-B1536/26-2-26002	1905/7/18	综合判定：合格。	

221	GX-B1520/26-2-26001	2026/3/23	综合判定：合格。	
222	GX-B1520/26-2-26002	2026/3/23	综合判定：合格。	

223	GX-B1520/26-2-26003	2026/3/23	综合判定：合格。			
224	GX-B1520/26-2-26004	2026/3/23	综合判定：合格。			

225	GX-B1520/26-2-26005	2026/3/23	综合判定：合格。		
226	GX-B1520/26-2-26006	2026/3/23	综合判定：合格。		

227	GX-B1520/26-2-26007	2026/3/23	综合判定：合格。	
228	GX-B1520/26-2-26008	2026/3/23	综合判定：合格。	

229	GX-B1520/26-2-26009	2026/3/23	综合判定：合格。	
230	GX-B1520/26-2-26010	2026/3/23	综合判定：合格。	