

序号	报告编号	发布日期	结论	影像资料
25	GX-B1310/21-Z-26026	2026年3月16日	符合标准要求。	 <p>2026/3/3</p>
26	GX-B1310/21-Z-26027	2026年3月16日	符合标准要求。	 <p>2026/3/3</p>

27	GX-B1428/21-Z-26014	2026年3月20日	无缺陷迹痕显示	 <p>A photograph showing a worker in an orange uniform and red helmet inspecting a tunnel interior. The worker is holding a flashlight, and the tunnel walls are visible. A yellow timestamp '2026/3/4' is present in the bottom right corner of the image.</p>
28	GX-B1428/21-Z-26015	2026年3月20日	无缺陷迹痕显示	 <p>A photograph showing two workers in orange uniforms and red helmets standing in a tunnel. They are positioned in front of a large circular opening. A yellow timestamp '2026/3/4' is present in the bottom right corner of the image.</p>

29	GX-B1428/21-Z-26016	2026年3月20日	无缺陷迹痕显示	
30	GX-B1428/21-Z-26017	2026年3月20日	无缺陷迹痕显示	

31	GX-B1428/21-Z-26018	2026年3月20日	无缺陷迹痕显示	
32	GX-B1428/21-Z-26019	2026年3月20日	无缺陷迹痕显示	

33	GX-B1310/21-Z-26023	2026年3月20日	符合标准要求	 <p>2026/3/3</p>
34	GX-B1310/21-Z-26024	2026年3月20日	符合标准要求	 <p>2026/3/3</p>

35	GX-B1310/21-Z-26025	2026年3月20日	符合标准要求	
36	GX-B1310/21-Z-26021	2026年3月20日	符合标准要求	

37	GX-B1310/21-Z-26022	2026年3月20日	符合标准要求	 <p>2026/3/7</p>
38	GX-B1309/26-Z-26001	2026年3月23日	所检项目合格。	 <p>2026/3/5</p>

39	GX-B1500/26-Z-26001	2026年3月23日	综合判定：合格。	 <p>2026/3/5</p>
40	GX-B1500/26-Z-26002	2026年3月23日	综合判定：合格。	 <p>2026/3/5</p>

41	GX-B1500/26-Z-26003	2026年3月23日	综合判定：合格。	 <p>2026/3/5</p>
42	GX-B1309/26-Z-26002	2026年3月23日	所检项目合格。	 <p>2026/3/6</p>

43	GX-B1500/26-Z-26004	2026年3月23日	综合判定：合格。	 A photograph showing two workers in orange safety suits and red hard hats. One worker is holding a clipboard and looking at the other worker, who is pointing towards a piece of industrial machinery. The background shows a complex industrial environment with pipes and equipment. A yellow timestamp '2026/3/6' is visible in the bottom right corner of the image.
44	GX-B1500/26-Z-26005	2026年3月23日	综合判定：合格。	 A photograph showing two workers in orange safety suits and red hard hats standing in an industrial setting. They are positioned near a large piece of machinery, possibly a pump or motor. The workers appear to be inspecting or discussing the equipment. A yellow timestamp '2026/3/6' is visible in the bottom right corner of the image.

45	GX-B1500/26-Z-26006	2026年3月23日	综合判定：合格。	 A photograph showing two workers in orange safety suits and red helmets inspecting a large electrical control cabinet. One worker is pointing at the cabinet's controls, while the other holds a clipboard. The cabinet has various warning signs and a 'Gincan' logo. A yellow timestamp '2026/3/6' is visible in the bottom right corner of the photo.
----	---------------------	------------	----------	--