

序号	报告编号	发布日期	结论	影像资料
8	GX-B1410/26-F-26136	2026.3.6	所检项目合格	
9	GX-B1411/26-F-26009	2026.3.9	所检项目合格	

10	GX-B1540/26-F-260277~260295	2026.3.6	所检项目合格	
11	GX-B1374/26-F-26088~26091	2026.3.9	所检项目合格	

12	GX-B1465/26-F-26016~26022	2026.3.6	所检项目合格	
13	GX-B1644/26-F-26005	2026.3.9	所检项目合格	

14	GX-B1644/26-F-26008~26009	2026.3.9	所检项目合格	
15	GX-B1475/26-F-26018~26028	2026.3.6	所检项目合格	

16	GX-B1601/26-F-26108~26118	2026.3.9	本次共检验风速传感器11台，11台所检项目合格。	
17	GX-B1409/26-F-26009~26013	2026.3.9	本次共检验温度传感器5台，5台所检项目合格	

18	GX-B1644/26-F-26006	2026.3.9	所检项目合格	
19	GX-B1412/26-F-26004	2026.3.10	所检项目合格	

20	GX-B1411/26-F-26036~26037	2026.3.10	所检项目合格	
21	GX-B1601/26-F-26119~26133	2026.3.10	所检项目合格	

22	GX-B1592/26-F-26025~26026	2026.3.10	所检项目合格	
23	GX-B1410/26-F-26137~26141	2026.3.10	所检项目合格	

24	GX-B1410/26-F-26160~26168	2026.3.10	所检项目合格	 <p>2026.3.5</p>
25	GX-B1410/26-F-26169~26172	2026.3.10	所检项目合格	 <p>2026.3.5</p>

26	GX-B1605/26-F-26128~26131	2026.3.10	所检项目合格	
27	GX-B1606/26-F-26128~26131	2026.3.10	所检项目合格	

28	GX-B1592/26-F-26023	2026.3.4	所检项目合格	
29	GX-B1592/26-F-26027~26032	2026.3.11	本次共检验差压传感器6台，6台所检项目合格。	

30	GX-B1465/26-F-26023	2026.3.11	所检项目合格	
31	GX-B1374/26-F-26092	2026.3.12	所检项目合格	

32	GX-B1372/26-F-260144	2026.3.11	所检项目合格	 <p>2026/3/3</p>
33	GX-B1373/26-F-26034~26038	2026.3.11	所检项目合格	 <p>2026/3/3</p>

34	GX-B1605/26-F-26122~26123	2026.3.11	所检项目合格	 A photograph showing two technicians in grey lab coats working in a laboratory. They are positioned in front of a piece of scientific equipment with a blue and white color scheme. The technician on the left is looking down at something on the equipment, while the one on the right is looking towards the camera. The date '2026/3/3' is visible in the bottom right corner of the image.
35	GX-B1606/26-F-26126~26127	2026.3.11	所检项目合格	 A photograph showing two technicians in grey lab coats in a laboratory. The technician on the left is holding a white document or clipboard and looking at it. The technician on the right is looking towards the camera. They are standing in front of the same piece of scientific equipment as in the first image. The date '2026/3/3' is visible in the bottom right corner of the image.

36	GX-B1605/26-F-26132~26143	2026.3.12	所检项目合格	
37	GX-B1606/23-F-26132~26143	2026.3.11	所检项目合格	

38	GX-B1593/26-F-26106~26110	2026.3.11	所检项目合格	
39	GX-B1529/26-F-26096~26100	2026.3.10	所检项目合格	



40	GX-B1528/26-F-26061~26065	2026.3.10	所检项目合格	
41	GX-B1601/26-F-26145~26178	2026.3.11	所检项目合格	

42	GX-B1601/26-F-26142~26144	2026.3.10	所检项目合格	
43	GX-B1593/26-F-26106~26110	2026.3.11	所检项目合格	

44	GX-B1603/26-F-26019~26020	2026.3.10	所检项目合格	
45	GX-B1529/26-F-26096~26100	2026.3.11	所检项目合格	

46	GX-B1528/26-F-26061~26065	2026.3.10	所检项目合格	
47	GX-B1544/21-F-26029~26033	2026.3.12	所检项目合格	

48	GX-B1646/26-F-26001~26005	2026.3.10	所检项目合格	
49	GX-B1409/26-F-26029~26031	2026. 3. 10	所检项目合格	

50	GX-B1411/26-F-26038~26039	2026. 3. 10	所检项目合格	
51	GX-B1412/26-F-26005~26007	2026.3.10	所检项目合格	

52	GX-B1374/26-F-26100~26101	2026.3.13	所检项目合格	
53	GX-B1372/26-F-260150~260153	2026.3.13	所检项目合格	

54	GX-B1475/26-F-26030~26032	2026.3.13	所检项目合格	
55	GX-B1373/26-F-26041	2026.3.13	所检项目合格	

56	GX-B1409/26-F-26029~26031	2026. 3. 10	所检项目合格	 <p>2026.3.5</p>
57	GX-B1411/26-F-26038~26039	2026. 3. 10	所检项目合格	 <p>2026.3.5</p>

58	GX-B1412/26-F-26005~26007	2026.3.10	所检项目合格	
59	GX-B1545/26-F-26020~26023	2026. 3. 13	所检项目合格	

60	GX-B1606/26-F-26122~26125	2026. 3. 13	所检项目合格	
61	GX-B1605/26-F-26124~26127	2026.3.17	所检项目合格	

62	GX-B1605/26-F-26144~26155	2026.3.18	本次共检验多参数气体测定器12台，12台所检项目合格。	 A photograph showing two female technicians in a laboratory. They are wearing grey lab coats and white gloves. One technician is using a pipette to transfer liquid into a small vial, while the other stands beside her, holding a light blue document or checklist. The background shows laboratory equipment and a sink area. A date stamp '2026.3.6' is visible in the bottom right corner of the photo.
63	GX-B1606/26-F-26144~26155	2026.3.17	本次共检验多参数气体测定器12台，12台所检项目合格。	 A photograph showing two female technicians in a laboratory. They are wearing grey lab coats and white gloves. One technician is using a pipette to transfer liquid into a small vial, while the other stands beside her, holding a light blue document or checklist. The background shows laboratory equipment and a sink area. A date stamp '2026.3.6' is visible in the bottom right corner of the photo.

64	GX-B1545/26-F-26024~26035	2026.3.18	本次共检验多参数气体测定器12台，12台所检项目合格。	
65	GX-B1540/26-F-260356~260371	2026.3.13	本次共检验报警仪16台，16台所检项目合格。	

66	GX-B1372/26-F-260149	2026.3.13	所检项目合格。	 A photograph showing two female technicians in grey lab coats standing in a laboratory. They are positioned next to a piece of scientific equipment, possibly a spectrophotometer or similar analytical instrument. The technician on the right is smiling at the camera. The date '2026.3.9' is visible in the bottom right corner of the photo.
67	GX-B1409/26-F-26017~26018	2026.3.13	所检项目合格	 A photograph showing two female technicians in grey lab coats working at a laboratory bench. They are looking at a computer monitor which displays a software interface. The technician on the right is pointing at the screen. The date '2026.3.3' is visible in the bottom right corner of the photo.

68	GX-B1409/26-F-26019~26028	2026.3.13	所检项目合格	
69	GX-B1410/26-F-26142~26159	2026.3.11	所检项目合格	

70	GX-B1411/26-F-26010~26029	2026. 3. 17	所检项目合格	
71	GX-B1411/26-F-26030~26035	2026. 3. 17	所检项目合格	

72	GX-B1409/26-F-26014~26016	2026.3.17	所检项目合格	
73	GX-B1593/26-F-26101~26105	2026.3.17	所检项目合格	

74	GX-B1601/26-F-26134~26141	2026.3.17	所检项目合格	
75	GX-B1592/26-F-26024	2026.3.17	所检项目合格	

76	GX-B1540/26-F-260272~260276	2026.3.17	所检项目合格	
77	GX-B1528/26-F-26066~26070	2026.3.17	所检项目合格	

78	GX-B1540/26-F-260346~260355	2026.3.17	所检项目合格	
----	-----------------------------	-----------	--------	---