





序号	报告编号	发布日期	结论	影像资料
79	GX-B1605/26-F-26156~26157	2026.3.20	所检项目合格	
80	GX-B1606/26-F-26156~26157	2026.3.19	所检项目合格	

81	GX-B1605/26-F-26158~26161	2026.3.19	所检项目合格	
82	GX-B1606/26-F-26158~26161	2026.3.19	所检项目合格	

83	GX-B1568/26-F-26244~26245	2026.3.19	所检项目合格	
84	GX-B1592/26-F-26033	2026.3.19	所检项目合格。	

85	GX-B1571/26-F-26002~26006	2026.3.18	本次共检验硫化氢传感	
86	GX-B1605/26-F-26162~26181	2026.3.19	本次共检验多参数气体测定器20台，20台所检项目合格。	

87	GX-B1605/26-F-26182~26201	2026.3.19	本次共检验多参数气体测定器20台，20台所检项目合格。	 A photograph showing two female technicians in grey lab coats working in a laboratory. They are positioned in front of a blue and white fume hood. The technician on the right is holding a small device, possibly a gas detector, and looking at it. The technician on the left is also looking towards the device. The background shows various laboratory equipment and shelves.
88	GX-B1605/26-F-26202~26211		本次共检验多参数气体测定器10台，10台所检项目合格。	 A photograph showing two female technicians in grey lab coats working in a laboratory. They are positioned in front of a blue and white fume hood. The technician on the right is holding a small device, possibly a gas detector, and looking at it. The technician on the left is also looking towards the device. The background shows various laboratory equipment and shelves.

89	GX-B1568/26-F-26237~26242	2026.3.19	本次共检验矿用风速表	
90	GX-B1568/26-F-26243		所检项目合格。	

91	GX-B1568/26-F-26233~26236	2026. 3. 19	所检项目合格	
92	GX-B1568/26-F-26237~26242	2026. 3. 19	所检项目合格	

93	GX-B1601/26-F-26181~26190	2026.3.19	所检项目合格	 <p>2026.3.9</p>
94	GX-B1410/26-F-26173~26194	2026.3.19	所检项目合格	 <p>2026.3.13</p>

95	GX-B1605/26-F-26202~26211	2026.3.20	所检项目合格	 <p>2026/3/17</p>
96	GX-B1411/26-F-26041~26042	2026. 3. 19	所检项目合格	 <p>2026.3.13</p>

97	GX-B1606/26-F-26212~26218	2026. 3. 20	所检项目合格	
98	GX-B1605/26-F-26212~26218	2026. 3. 20	所检项目合格	

99	GX-B1410/26-F-26173~26194	2026. 3. 20	所检项目合格	
100	GX-B1411/26-F-26040	2026.3.19	所检项目合格	