

序号	报告编号	发布日期	结论	影像资料
139	GX-B1303/21-5-26006	2026. 3. 16	综合判定：合格。	 A photograph showing three workers in a factory setting. One worker in a grey shirt and red helmet is standing on a platform, looking at a large, curved metal component. Two other workers in orange and white shirts and red helmets are standing nearby, one holding a clipboard. The date '2026/2/24' is visible in the bottom right corner of the image.
140	GX-B1382/26-5-26005	2026. 3. 16	所检项目合格。	 A photograph showing a worker in an orange protective suit and red helmet working on a complex industrial structure. The worker is positioned on a platform, surrounded by various metal beams and components. The date '2026/2/25' is visible in the bottom right corner of the image.

141	GX-B1382/26-5-26006	2026. 3. 16	综合判定:合格。		
142	GX-B1310/21-5-26099	2026. 3. 16	符合标准要求。		

143	GX-B1310/21-5-26100	2026. 3. 16	符合标准要求。	
144	GX-B1310/21-5-26101	2026. 3. 16	符合标准要求。	

145	GX-B1380/26-5-26011	2026. 3. 16	所检项目合格。	
-----	---------------------	-------------	---------	---