

序号	报告编号	发布日期	结论	影像资料
263	GX-B1451/26-3-26210~26212	2026. 3. 23	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	
264	GX-B1321/20-3-26211~26221	2026. 3. 25	本次共检电力电缆11条，11条电力电缆所检项目合格。	


265	GX-B1321/20-3-26222~26224	2026. 3. 25	本次共检电力电缆3条，3条电力电缆所检项目合格。	
266	GX-B1321/20-3-26225~25232	2026. 3. 25	本次共检电力电缆8条，8条电力电缆所检项目合格。	

267	GX-B1321/20-3-26233~26242	2026. 3. 25	本次共检电力电缆10条，10条电力电缆所检项目合格。	
268	GX-B1451/26-3-26005~26008	2026. 3. 24	本次共检高压开关设备4台，4台高压开关设备所检项目合格。	



269	GX-B1451/26-3-26009~26020	2026. 3. 24	本次共检高压开关设备12台，12台高压开关设备所检项目合格。	
270	GX-B1310/21-3-26194	2026. 3. 20	符合标准要求。	


271	GX-B1310/21-3-26195	2026. 3. 20	符合标准要求。	 <p>HONOR 80 Pro 160MP Matrix Camera 2026.3.14</p>
272	GX-B1310/21-3-26196	2026. 3. 20	符合标准要求。	 <p>HONOR 80 Pro 160MP Matrix Camera 2026.3.14</p>

273	GX-B1310/21-3-26197	2026. 3. 20	符合标准要求。	
274	GX-B1310/21-3-26198	2026. 3. 20	符合标准要求。	

275	GX-B1310/21-3-26199	2026. 3. 20	符合标准要求。	
276	GX-B1310/21-3-26200	2026. 3. 20	符合标准要求。	

277	GX-B1350/21-3-26018	2026. 3. 20	本次共检验接地装置6处，6处所检项目合格。 。	
278	GX-B1404/20-3-26008	2026. 3. 24	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	

279	GX-B1404/20-3-26009	2026. 3. 24	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
280	GX-B1324/26-3-26058	2026. 3. 30	所检项目合格。	

281	GX-B1350/21-3-26019	2026. 3. 30	本次共检验接地装置2处，2处所检项目合格。	
282	GX-B1322/26-3-26169~26171	2026. 3. 30	本次共检电力电缆3条，3条电力电缆所检项目合格。	

283	GX-B1322/26-3-26172~26173	2026. 3. 30	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	 <p>2026.3.25</p>
284	GX-B1322/26-3-26174	2026. 3. 30	所检项目合格。	 <p>2026.3.25</p>

285	GX-B1418/26-3-26001	2026. 3. 30	综合判定：合格。		
286	GX-B1451/26-3-26215~26217	2026. 3. 31	所检项目合格。		

287	GX-B1329/26-3-26152	2026. 3. 31	所检项目合格。	
288	GX-B1451/26-3-26218	2026. 3. 31	所检项目合格。	

289	GX-B1303/26-3-26019	2026. 3. 31	综合判定：合格。	
290	GX-B1313/26-3-26071~26074	2026. 3. 30	所检项目合格。	

291	GX-B1313/26-3-26075~26077	2026. 3. 30	所检项目合格。	 A photograph showing a worker in a grey jacket and red helmet working on a transformer. The worker is standing on a platform, and there are yellow test equipment and cables connected to the transformer. The date 2026.3.29 is visible in the bottom right corner of the photo.
292	GX-B1313/26-3-26078~26079	2026. 3. 30	所检项目合格。	 A photograph showing a worker in a grey jacket and red helmet working on a transformer. The transformer is labeled 'T-10 G' and '2#'. The worker is standing next to the transformer, and there are yellow test equipment and cables connected to it. The date 2026.3.29 is visible in the bottom right corner of the photo.