



序号	报告编号	发布日期	结论	影像资料
91	GX-B1328/26-4-26032	3. 24	本次共检绝缘杆2组， 2组绝缘杆合格	 <p>2026.3.5</p>
92	GX-B1307/26-4-26007	2026. 3. 24	综合判定：合格	 <p>2026-02-24</p>

93	GX-B1307/26-4-26008	2026. 3. 24	综合判定：合格	 <p>2026-02-28</p>
94	GX-B1307/26-4-26009	2026. 3. 24	综合判定：合格	 <p>2026-02-28</p>

95	GX-B1382/26-4-26005	2026. 3. 24	综合判定：合格	
96	GX-B1382/26-4-26006	2026. 3. 24	综合判定：合格	

97	GX-B1310/26-4-26050	2026. 3. 23	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	 <p>2026-03-01</p>
98	GX-B1310/26-4-26051	2026. 3. 23	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	 <p>2026-03-01</p>

99	GX-B1380/26-4-26016	2026. 3. 24	所检项目合格	 <p>2026-03-01</p>
100	GX-B1380/26-4-26017	2026. 3. 24	所检项目合格	 <p>2026-03-01</p>

101	GX-B1328/26-4-26037	2026. 3. 24	本次共检绝缘手套 4只，4只绝缘手套合 格。	 A photograph showing an electrical testing room. A red safety net is stretched across the foreground. In the background, a worker wearing a red hard hat is seated at a desk. A yellow metal stand holds several white cylindrical objects, likely insulating gloves. A date stamp '2026/03/09' is visible in the bottom right corner of the image.
102	GX-B1328/26-4-26038	2026. 3. 24	本次共检绝缘靴4只， 4只绝缘靴合格。	 A photograph showing an electrical testing room, similar to the one above. A red safety net is stretched across the foreground. In the background, a worker wearing a red hard hat is seated at a desk. A yellow metal stand holds several white cylindrical objects, likely insulating boots. A date stamp '2026/03/09' is visible in the bottom right corner of the image.

103	GX-B1328/26-4-26039	2026. 3. 24	本次共检验电器2支， 2支验电器合格。		
104	GX-B1328/26-4-26040	2026. 3. 24	本次共检便携式接地 和接地短路装置2套， 2套便携式接地和接地 短路装置合格。		

105	GX-B1323/26-4-26022	2026. 3. 25	所检项目合格。	
106	GX-B1598/24-4-26001	2026/3/17	实测钢丝绳有效截面积损失百分比最大为1.22%，小于5%为正常。 。	

107	GX-B1598/24-4-26002	2026/3/17	实测钢丝绳有效截面积损失百分比最大为1.16%，小于5%为正常。 。	 <p>2026.2.11</p>
108	GX-B1598/24-4-26003	2026/3/17	实测钢丝绳有效截面积损失百分比最大为1.19%，小于5%为正常。 。	 <p>2026.2.11</p>

109	GX-B1598/24-4-26004	2026/3/17	实测钢丝绳有效截面积损失百分比最大为1.28%，小于5%为正常。 。		
110	GX-B1310/21-4-26072	2026/3/23	符合标准要求。		

111	GX-B1310/21-4-26073	2026/3/23	符合标准要求。	 <p>2026/3/1</p>
112	GX-B1310/21-4-26074	2026/3/23	符合标准要求。	 <p>2026/3/1</p>

113	GX-B1310/21-4-26075	2026/3/23	符合标准要求。	 <p>2026/3/1</p>
114	GX-B1310/21-4-26076	2026/3/23	符合标准要求。	 <p>2026/3/1</p>

115	GX-B1310/21-4-26077	2026/3/23	符合标准要求。	
116	GX-B1310/21-4-26078	2026/3/23	符合标准要求。	

117	GX-B1310/21-4-26079	2026/3/23	符合标准要求。	 A worker in a grey uniform and red helmet is working on a large, dark, cylindrical industrial tank. The worker is wearing a safety harness and is positioned on a metal platform or scaffolding. The background shows industrial structures and pipes. A red date stamp '2026/3/1' is visible in the bottom right corner of the image.
118	GX-B1310/21-4-26080	2026/3/23	符合标准要求。	 A worker in a grey uniform and red helmet is working on a mechanical component, possibly a valve or a pump, which is mounted on a metal structure. The worker is wearing blue gloves and is using a tool. Another person in a blue uniform is partially visible in the background. A red date stamp '2026/3/1' is visible in the bottom right corner of the image.

119	GX-B1310/21-4-26081	2026/3/23	符合标准要求。	
120	GX-B1310/21-4-26082	2026/3/23	符合标准要求。	

121	GX-B1310/21-4-26083	2026/3/23	符合标准要求。	
122	GX-B1310/21-4-26084	2026/3/23	符合标准要求。	

123	GX-B1303/26-4-26003	2026/3/25	综合判定：合格。	
124	GX-B1303/26-4-26004	2026/3/25	综合判定：合格。	

125	GX-B1303/26-4-26007	2026/3/25	综合判定：合格。	
126	GX-B1303/26-4-26008	2026/3/25	综合判定：合格。	

127	GX-B1310/21-4-26085	2026. 3. 23	符合标准要求。	
128	GX-B1310/21-4-26086	2026. 3. 23	符合标准要求。	

129	GX-B1310/21-4-26087	2026. 3. 23	符合标准要求。	 <p>2026/3/4</p>
130	GX-B1310/21-4-26088	2026. 3. 23	符合标准要求。	 <p>2026/3/4</p>

131	GX-B1310/21-4-26089	2026. 3. 23	符合标准要求。	
132	GX-B1310/21-4-26090	2026. 3. 23	符合标准要求。	

133	GX-B1310/21-4-26101	2026. 3. 23	符合标准要求。	 <p>2026/3/4</p>
134	GX-B1310/21-4-26102	2026. 3. 23	符合标准要求。	 <p>2026/3/4</p>  <p>2026/3/4</p>

135	GX-B1310/21-4-26103	2026. 3. 23	符合标准要求。	
136	GX-B1310/21-4-26104	2026. 3. 23	符合标准要求。	

137	GX-B1380/26-4-26020	2026. 3. 25	所检项目合格	
138		2026. 3. 25	综合判定：合格。	

139	GX-B1303/26-4-26005	2026. 3. 25	综合判定：合格。	 <p>2026/3/3</p>
140	GX-B1310/21-4-26091	2026/3/25	符合标准要求。	 <p>2026/3/5</p>

141	GX-B1310/21-4-26092	2026/3/25	符合标准要求。	
142	GX-B1310/21-4-26093	2026/3/25	符合标准要求。	

143	GX-B1310/21-4-26094	2026/3/25	符合标准要求。	 <p>2026/3/5</p>
144	GX-B1310/21-4-26095	2026/3/25	符合标准要求。	 <p>2026/3/5</p>

145	GX-B1310/21-4-26096	2026/3/25	符合标准要求。	
146	GX-B1310/21-4-26097	2026/3/25	符合标准要求。	

147	GX-B1310/21-4-26098	2026/3/25	符合标准要求。	
148	GX-B1310/21-4-26099	2026/3/25	符合标准要求。	

149	GX-B1310/21-4-26100	2026/3/25	符合标准要求。	
150	GX-B1303/26-4-26009	2026/3/25	符合标准要求。	

151	GX-B1380/26-4-26023	2026. 3. 25	所检项目合格	
152	GX-B1380/26-4-26024	2026. 3. 25	所检项目合格	

153	GX-B1382/26-4-26009	2026. 3. 25	综合判定：合格	
154	GX-B1382/26-4-26010	2026. 3. 25	综合判定：合格	

155	GX-B1303/26-4-26006	2026. 3. 25	综合判定：合格。	 <p>2026/3/2</p>
156	GX-B1304/26-4-26014	2026. 3. 25	综合判定：合格。	 <p>2026/3/3</p>

157	GX-B1310/21-4-26105	2026. 3. 25	符合标准要求。	 <p>2026/3/2</p>
158	GX-B1310/21-4-26106	2026. 3. 25	符合标准要求。	 <p>2026/3/2</p>

159	GX-B1310/21-4-26107	2026. 3. 25	符合标准要求。	
160	GX-B1310/21-4-26108	2026. 3. 25	符合标准要求。	

161	GX-B1310/21-4-26109	2026. 3. 25	符合标准要求。	 <p>2026/3/3</p>
162	GX-B1310/21-4-26110	2026. 3. 25	符合标准要求。	 <p>2026/3/3</p>

163	GX-B1310/21-4-26111	2026. 3. 25	符合标准要求。	
164	GX-B1310/21-4-26112	2026. 3. 25	符合标准要求。	

165	GX-B1310/21-4-26113	2026. 3. 25	符合标准要求。	 <p>A photograph showing a worker in a red hard hat and safety harness working on a large, dark metal structure, possibly a piece of machinery or a component of a vessel. The worker is positioned on the left side of the frame, facing right. The background is dark and industrial.</p>
166	GX-B1380/26-4-26021	2026. 3. 25	所检项目合格	 <p>A photograph showing a worker in a white uniform and red hard hat standing in a narrow industrial corridor. The worker is holding a white document or clipboard. The corridor is lined with metal walls and has various pipes and equipment visible. The floor is dark and appears to be made of metal or concrete.</p>

167	GX-B1380/26-4-26022	2026. 3. 25	所检项目合格	
168	GX-B1382/26-4-26008	2026. 3. 25	综合判定：合格	

169	GX-B1303/26-4-26006	2026. 3. 25	综合判定：合格。	 <p>2026/3/2</p>
170	GX-B1304/26-4-26014	2026. 3. 25	综合判定：合格。	 <p>2026/3/3</p>

171	GX-B1310/21-4-26105	2026. 3. 25	符合标准要求。	 <p>2026/3/2</p>
172	GX-B1310/21-4-26106	2026. 3. 25	符合标准要求。	 <p>2026/3/2</p>

173	GX-B1310/21-4-26107	2026. 3. 25	符合标准要求。	
174	GX-B1310/21-4-26108	2026. 3. 25	符合标准要求。	

175	GX-B1310/21-4-26109	2026. 3. 25	符合标准要求。	
176	GX-B1310/21-4-26110	2026. 3. 25	符合标准要求。	

177	GX-B1310/21-4-26111	2026. 3. 25	符合标准要求。	
178	GX-B1310/21-4-26112	2026. 3. 25	符合标准要求。	

179	GX-B1310/21-4-26113	2026. 3. 25	符合标准要求。	 <p>A photograph showing a worker in a red hard hat and safety harness working on a large, dark metal structure, possibly a piece of machinery or a component of a vessel. The worker is positioned on the left side of the frame, facing right. The background is dark and industrial.</p>
180	GX-B1380/26-4-26021	2026. 3. 25	所检项目合格	 <p>A photograph showing a worker in a white protective suit and red hard hat standing in a narrow industrial corridor. The worker is holding a white document or clipboard. The corridor is lined with metal structures and pipes, and the lighting is somewhat dim.</p>

181	GX-B1380/26-4-26022	2026. 3. 25	所检项目合格	
182	GX-B1382/26-4-26008	2026. 3. 25	综合判定：合格	