

序号	报告编号	发布日期	结论	影像资料
146	GX-B1310/21-5-26103	2026. 3. 23	符合标准要求。	 A photograph showing a worker in a dark, industrial setting. The worker is wearing a red hard hat and is using a bright flashlight to inspect a piece of equipment. The scene is dimly lit, with the primary light source being the flashlight. A timestamp '2026/3/13' is visible in the bottom right corner of the image.
147	GX-B1350/21-5-26008	2026. 3. 25	本次共检验接地装置3处，3处接地装置所检项目合格。	 A photograph showing a worker wearing a red hard hat and a yellow protective suit. The worker is kneeling on a concrete floor, inspecting a piece of equipment. The background features a large yellow structure and a blue wall. A timestamp '2026/3/11' is visible in the bottom right corner of the image.

148	GX-B1300/26-5-26005	2026. 3. 25	综合判定：合格。	
149	GX-B1300/26-5-26006	2026. 3. 25	综合判定：合格。	

150	GX-B1301/25-5-26004	2026. 3. 25	综合判定:合格。	
151	GX-B1382/26-5-26009	2026. 3. 26	所检项目合格。	

152	GX-B1382/26-5-26010	2026. 3. 26	综合判定:不合格。	 A photograph showing two workers in red safety suits and helmets standing in an industrial environment, possibly a mine or factory. They are positioned near a metal structure. A yellow timestamp '2026/3/16' is visible in the bottom right corner of the image.
153	GX-B1380/26-5-26016	2026. 3. 26	除罐内尺寸、扶手、罐体顶部项目不合格外，其余所检项目合格。	 A photograph showing a worker in a red safety suit and helmet inspecting a structure, likely a tank or container, in an industrial setting. The worker is holding a clipboard. A yellow timestamp '2026/3/16' is visible in the bottom right corner of the image.

154	GX-B1301/23-5-26002	2026. 3. 26	综合判定:合格。	
155	GX-B1301/23-5-26003	2026. 3. 26	综合判定:合格。	

156	GX-B1310/21-5-26113	2026. 3. 25	符合标准要求。	
157	GX-B1310/21-5-26114	2026. 3. 25	符合标准要求。	

158	GX-B1310/21-5-26115	2026. 3. 25	符合标准要求。	 A worker in a red safety suit and helmet is working on a metal structure, possibly a ladder or scaffolding, in an industrial setting. The worker is positioned on a platform, and the background shows a complex network of pipes and structural elements. A yellow timestamp '2026/3/16' is visible in the bottom right corner of the image.
159	GX-B1427/21-5-26021	2026. 3. 25	符合标准要求。	 A worker in a red safety suit and helmet is standing on a metal structure, possibly a ladder or scaffolding, in an industrial setting. The worker is wearing a yellow safety vest and is positioned on a platform. The background shows a complex network of pipes and structural elements. A yellow timestamp '2026/3/16' is visible in the bottom right corner of the image.

160	GX-B1303/26-5-26009	2026/3/27	综合判定：不合格。	
161	GX-B1621/26-5-26001	2026/3/27	所检项目合格。	

162	GX-B1621/26-5-26002	2026/3/27	所检项目合格。	
163	GX-B1621/26-5-26003	2026/3/27	所检项目合格。	



164	GX-B1621/26-5-26004	2026/3/27	所检项目合格。			
165	GX-B1621/26-5-26005	2026/3/27	所检项目合格。			

166	GX-B1621/26-5-26006	2026/3/27	所检项目合格。	
167	GX-B1621/26-5-26007	2026/3/27	所检项目合格。	

168	GX-B1621/26-5-26008	2026/3/27	所检项目合格。	 A photograph showing a construction site. A large area is covered with a bright green tarp. Two workers in orange safety gear and red hard hats are visible. One worker is kneeling on the ground, and the other is standing. The background shows a rocky, excavated hillside. A yellow timestamp '2026/03/16' is in the bottom right corner.
169	GX-B1621/26-5-26009	2026/3/27	所检项目合格。	 A photograph showing a construction site. A large area is covered with a white tarp. A worker in a grey jacket and red hard hat is standing near a blue tarp. In the foreground, there is a large metal drum on a wooden frame. Another worker in an orange safety jacket and red hard hat is visible in the foreground. The background shows a rocky, excavated hillside. A yellow timestamp '2026/03/16' is in the bottom right corner.



170	GX-B1621/26-5-26010	2026/3/27	所检项目合格。	 <p>2026/03/15</p>
171	GX-B1321/20-5-26026-26033	2026. 3. 27	本次共检电力电缆 8条，8条电力电缆所 检项目合格。	 <p>2026. 1. 8</p>

172	GX-B1323/21-5-26066-26074	2026. 3. 27	所检项目合格。	
173	GX-B1307/26-5-26003	2026/3/27	综合判定：合格。	

174	GX-B1307/26-5-26004	2026/3/27	综合判定：合格。	
175	GX-B1307/26-5-26005	2026/3/27	综合判定：合格。	

176	GX-B1307/26-5-26006	2026/3/27	综合判定：合格。	
177	GX-B1307/26-5-26007	2026/3/27	综合判定：合格。	

178	GX-B1307/26-5-26008	2026/3/27	综合判定：合格。		
179	GX-B1307/26-5-26009	2026/3/27	综合判定：合格。		

180	GX-B1307/26-5-26010	2026/3/27	综合判定：合格。		
181	GX-B1307/26-5-26011	2026/3/27	综合判定：合格。		

182	GX-B1328/25-5-26001	2026. 3. 12	本次共检绝缘手套186只，186只绝缘手套合格。	
183	GX-B1328/25-5-26002	2026. 3. 12	本次共检绝缘靴160只，160只绝缘靴合格。	

184	GX-B1328/25-5-26003	2026. 3. 12	本次共检验电器 60支，60支验电器合格。 。	
185	GX-B1328/25-5-26004	2026. 3. 12	本次共检便携式接地 和接地短路装置 63套，63套便携式接地 和接地短路装置合格。 。	

186	GX-B1328/25-5-26005	2026. 3. 12	本次共检绝缘杆 10支，10支绝缘杆合格。 。	
187	GX-B1328/25-5-26006	2026. 3. 12	本次共检绝缘胶垫294 个，294个绝缘胶垫合 格。	

188	GX-B1495/25-5-26173~26174	2026. 3. 27	本次共检防爆型高压 配电装置2台，2台防 爆型高压配电装置所 检项目合格。	
189	GX-B1495/25-5-26116~26130	2026. 3. 27	本次共检高压开关柜 15台，15台高压开关柜 所检项目合格。	

190	GX-B1495/26-5-26069~26090	2026. 3. 27	本次共检高压开关柜22台，22台高压开关柜所检项目合格。	
191	GX-B1495/25-5-26175~26192	2026. 3. 27	本次共检防爆型高压配电装置18台，18台防爆型高压配电装置所检项目合格。	


192	GX-B1495/25-5-26040~26057	2026. 3. 27	本次共检高压开关柜18台，18台高压开关柜所检项目合格。	 2026.1.14
193	GX-B1495/25-5-26193~26206	2026. 3. 27	本次共检防爆型高压配电装置14台，14台防爆型高压配电装置所检项目合格。	 2026.1.14

194	GX-B1495/25-5-26208~26232	2026. 3. 27	本次共检防爆型高压 配电装置25台，25台防 爆型高压配电装置所 检项目合格。	
195	GX-B1495/25-5-26147~26172	2026. 3. 27	本次共检防爆型高压 配电装置26台，26台防 爆型高压配电装置所 检项目合格。	

196	GX-B1495/25-5-26131~26146	2026. 3. 27	本次共检防爆型高压 配电装置16台，16台防 爆型高压配电装置所 检项目合格。	
197	GX-B1495/25-5-26101~26115	2026. 3. 27	本次共检防爆型高压 配电装置15台，15台防 爆型高压配电装置所 检项目合格。	

198	GX-B1495/25-5-26024~26039	2026. 3. 27	本次共检高压开关柜16台，16台高压开关柜所检项目合格。	 <p>2026.1.12</p>
199	GX-B1495/25-5-26233~26248	2026. 3. 27	本次共检防爆型高压配电装置16台，16台防爆型高压配电装置所检项目合格。	 <p>2026.1.17</p>

200	GX-B1495/25-5-26249~26270	2026. 3. 27	本次共检防爆型高压 配电装置22台，22台防 爆型高压配电装置所 检项目合格。	
201	GX-B1495/25-5-26091~26100	2026. 3. 27	本次共检高压开关柜 10台，10台高压开关柜 所检项目合格。	

202	GX-B1495/25-5-26058~26068	2026. 3. 27	本次共检高压开关柜 11台，11台高压开关柜 所检项目合格。	
-----	---------------------------	-------------	--------------------------------------	---