

序号	报告编号	发布日期	结论	影像资料
46	GX-B1328/26-Z-26014	2026年3月25日	本次共检绝缘手套56只，56只绝缘手套合格。	
47	GX-B1328/26-Z-26015	2026年3月25日	本次共检绝缘靴60只，60只绝缘靴合格。	

48	GX-B1328/26-Z-26016	2026年3月25日	本次共检验电器 24支，24支验电器合格	 A photograph showing three workers in red protective suits and hard hats working outdoors. One worker in the foreground is leaning over a wooden chair, possibly testing equipment. The background shows a building and other workers. A yellow timestamp '2026/3/8' is visible in the bottom right corner of the image.
49	GX-B1328/26-Z-26017	2026年3月25日	本次共检便携式接地 和接地短路装置 10组，10组便携式接地 和接地短路装置合格 。	 A photograph showing workers in red protective suits and hard hats working outdoors. One worker is sitting on a wooden chair, and another is standing nearby. The background shows a building and other workers. A yellow timestamp '2026/3/8' is visible in the bottom right corner of the image.

50	GX-B1328/26-Z-26018	2026年3月25日	本次共检绝缘杆 14支，14支绝缘杆合格。 。	
51	GX-B1328/26-Z-26019	2026年3月25日	本次共检绝缘胶垫43 块，43块绝缘胶垫合 格。	

52	GX-B1322/26-Z-26001~26003	2026年3月26日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	 A worker in a grey uniform and red helmet is working on a large electrical cabinet. The cabinet has several red cables connected to it. The worker is using a tool to work on the cables. The date 2026/3/2 is visible in the bottom right corner of the image.
53	GX-B1322/26-Z-26004~26009	2026年3月26日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	 A worker in an orange uniform and red helmet is working on a large electrical cabinet in a hallway. The worker is kneeling on the floor and using a tool to work on the cabinet. The date 2026/3/13 is visible in the bottom right corner of the image.

54	GX-B1322/26-Z-26010	2026年3月26日	所检项目合格。	 <p>2026/3/13</p>
55	GX-B1322/26-Z-26011~26021	2026年3月26日	本次共检验电力电缆11条，11条电力电缆所检项目合格。	 <p>2026/3/14</p>

56	GX-B1322/26-Z-26022~26031	2026年3月26日	本次共检验电力电缆10条，10条电力电缆所检项目合格。	
57	GX-B1322/26-Z-26032~26035	2026年3月26日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	

58	: GX-B1322/26-Z-26036~26045	2026年3月26日	本次共检验电力电缆10条，10条电力电缆所检项目合格。	 <p>2026/3/16</p>
59	GX-B1322/26-Z-26046~26049	2026年3月26日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	 <p>2026/3/16</p>

60	GX-B1322/26-Z-26050~26057	2026年3月26日	本次共检验电力电缆8条，8条电力电缆所检项目合格。	 A photograph showing two workers in red safety uniforms and hard hats. One worker is kneeling on the floor, working on a piece of equipment inside an open electrical cabinet. The other worker stands next to him, observing. The scene is a narrow aisle between rows of electrical cabinets. A yellow timestamp '2026/3/17' is visible in the bottom right corner of the photo.
61	GX-B1322/26-Z-26058~26062	2026年3月26日	本次共检验电力电缆5条，5条电力电缆所检项目合格。	 A photograph showing two workers in red safety uniforms and hard hats. One worker is kneeling on the floor, working on a piece of equipment inside an open electrical cabinet. The other worker stands next to him, observing. The scene is a narrow aisle between rows of electrical cabinets. A yellow timestamp '2026/3/18' is visible in the bottom right corner of the photo.

62	GX-B1322/26-Z-26063~26074	2026年3月26日	本次共检验电力电缆12条，12条电力电缆所检项目合格。	
63	GX-B1314/21-Z-26001~26002	2026年3月24日	本次共检电抗器2台，2台电抗器所检项目合格。	

64	GX-B1301/26-Z-26001	2026年3月27日	综合判定:合格。	
65	GX-B1304/26-Z-26001		综合判定:合格。	

66	GX-B1520/26-Z-26001	2026年3月27日	综合判定：合格。	
67	GX-B1520/26-Z-26002	2026年3月27日	综合判定：合格。	

68	GX-B1520/26-Z-26003	2026年3月27日	综合判定：合格。	
69	GX-B1520/26-Z-26004	2026年3月27日	综合判定：合格。	



70	GX-B1520/26-Z-26005	2026年3月27日	综合判定：合格。	
71	GX-B1520/26-Z-26006	2026年3月27日	综合判定：合格。	

72	GX-B1520/26-Z-26007	2026年3月27日	综合判定：合格。	
73	GX-B1520/26-Z-26008	2026年3月27日	综合判定：合格。	

74	GX-B1520/26-Z-26009	2026年3月27日	综合判定：合格。	
75	GX-B1520/26-Z-26010	2026年3月27日	综合判定：合格。	

76	GX-B1539/22-Z-26001	2026年3月27日	所检项目合格。	
77	GX-B1539/22-Z-26002	2026年3月27日	所检项目合格。	

78	GX-B1539/22-Z-26003	2026年3月27日	所检项目合格。	
79	GX-B1309/26-Z-26001	2026年3月27日	所检项目合格。	

80	GX-B1500/26-Z-26001	2026年3月27日	综合判定：合格。	 <p>2026/3/5</p>
81	GX-B1500/26-Z-26002	2026年3月27日	综合判定：合格。	 <p>2026/3/5</p>

82	GX-B1500/26-Z-26003	2026年3月27日	综合判定：合格。	 <p>2026/3/5</p>
83	GX-B1309/26-Z-26003	2026年3月27日	所检项目合格。	 <p>2026/3/6</p>

84	GX-B1500/26-Z-26007	2026年3月27日	综合判定：合格。	
85	GX-B1500/26-Z-26008	2026年3月27日	综合判定：合格。	

86	GX-B1500/26-Z-26009	2026年3月27日	综合判定：合格。	 <p>2026/3/6</p>
87	GX-B1309/26-Z-26004	2026年3月27日	所检项目合格。	 <p>2026/3/6</p>

88	GX-B1500/26-Z-26010	2026年3月27日	综合判定：合格。	
89	GX-B1500/26-Z-26011	2026年3月27日	综合判定：合格。	

90	GX-B1500/26-Z-26012	2026年3月27日	综合判定：合格。	 <p>2026/3/6</p>
91	GX-B1309/26-Z-26002	2026年3月27日	所检项目合格。	 <p>2026/3/6</p>

92	GX-B1500/26-Z-26004	2026年3月27日	综合判定：合格。	
93	GX-B1500/26-Z-26005	2026年3月27日	综合判定：合格。	

94	GX-B1500/26-Z-26006	2026年3月27日	综合判定：合格。	 <p>2026/3/6</p>
95	GX-B1309/26-Z-26005	2026年3月27日	所检项目合格。	 <p>2026/3/7</p>

96	GX-B1500/26-Z-26013	2026年3月27日	综合判定：合格。	
97	GX-B1500/26-Z-26014	2026年3月27日	综合判定：合格。	

98	GX-B1500/26-Z-26015	2026年3月27日	综合判定：合格。	 A photograph showing two workers in orange safety suits and red helmets. They are standing in front of a white control panel with various buttons and lights. A large red circle with the number '3' is visible on the panel. The date '2026/3/7' is printed in yellow at the bottom right of the image.
99	GX-B1309/26-Z-26006	2026年3月27日	所检项目合格。	 A photograph showing two workers in orange safety suits and red helmets. They are in a tunnel-like environment, looking at some equipment or a device. The date '2026/3/7' is printed in yellow at the bottom right of the image.



100	GX-B1500/26-Z-26016	2026年3月27日	综合判定：合格。	 A photograph showing two workers in orange protective suits and red hard hats. They are standing in an industrial environment, possibly a tunnel or underground facility, with various pipes and machinery visible. One worker is looking at a handheld device. A yellow timestamp '2026/3/7' is visible in the bottom right corner of the image.
101	GX-B1500/26-Z-26017	2026年3月27日	综合判定：合格。	 A photograph showing two workers in orange protective suits and red hard hats. They are standing in an industrial environment, possibly a tunnel or underground facility, with various pipes and machinery visible. One worker is looking at a handheld device. A yellow timestamp '2026/3/7' is visible in the bottom right corner of the image.

102	GX-B1500/26-Z-26018	2026年3月27日	综合判定：合格。	 A photograph showing two workers in orange safety suits and red hard hats standing next to a large blue industrial machine in a tunnel. The machine has various pipes and valves. A yellow timestamp '2026/3/27' is visible in the bottom right corner of the photo.
103	GX-B1500/26-Z-26019	2026年3月27日	综合判定：合格。	 A photograph showing two workers in orange safety suits and red hard hats inspecting a control panel in a tunnel. One worker is holding a clipboard. The control panel has various buttons and lights. A yellow timestamp '2026/3/27' is visible in the bottom right corner of the photo.

104	GX-B1350/21-Z-26005	2026年3月27日	本次共检验接地装置9处，9处所检项目合格。 。	 A photograph showing two workers in safety gear (red helmets, orange and grey uniforms) inspecting a ground device. One worker is holding a device, and the other is standing nearby. The date stamp '2026/3/12' is visible in the bottom right corner of the image.
105	GX-B1350/21-Z-26006	2026年3月27日	本次共检验接地装置2处，2处所检项目合格。 。	 A photograph showing a worker in safety gear (red helmet, orange uniform) inspecting a ground device. The worker is holding a device and looking at it. The date stamp '2026/3/16' is visible in the bottom right corner of the image.

106	GX-B1350/21-Z-26007	2026年3月27日	本次共检验接地装置2处，2处所检项目合格。	
107	GX-B1350/21-Z-26008	2026年3月27日	本次共检验接地装置25处，25处所检项目合格。	



108	GX-B1324/26-Z-26001~26004	2026年3月27日	所检项目合格。	 <p>2026/3/27</p>
109	GX-B1324/26-Z-26005~26007	2026年3月27日	所检项目合格。	 <p>2026/3/14</p>

110	GX-B1324/26-Z-26008~26010	2026年3月27日	所检项目合格。	
111	GX-B1324/26-Z-26011~26013	2026年3月27日	所检项目合格。	

112	GX-B1380/26-Z-26001	2026-03-30	所检项目合格。	
113	GX-B1451/26-Z-26001~26007	2026年3月31日	本次共检高压开关设备7台，7台高压开关设备所检项目合格。 。	

114	GX-B1451/26-Z-26008~26016	2026年3月31日	本次共检高压开关设备9台，9台高压开关设备所检项目合格。 。	
115	GX-B1451/26-Z-26017~26028	2026年3月31日	本次共检高压开关设备12台，12台高压开关设备所检项目合格。 。	

116	GX-B1451/26-Z-26029~26034	2026年3月31日	本次共检高压开关设备6台，6台高压开关设备所检项目合格	 <p>2026/3/15</p>
117	GX-B1451/26-Z-26035~26044	2026年3月31日	本次共检高压开关设备10台，10台高压开关设备所检项目合格。	 <p>2026/3/16</p>

118	GX-B1451/26-Z-26045~26051	2026年3月31日	本次共检高压开关设备7台，7台高压开关设备所检项目合格	
119	GX-B1451/26-Z-26052~26063	2026年3月31日	本次共检高压开关设备12台，12台高压开关设备所检项目合格。 。	

120	GX-B1451/26-Z-26064~26070	2026年3月31日	<p>本次共检高压开关设备7台，7台高压开关设备所检项目合格。</p> <p>。</p>	
121	GX-B1451/26-Z-26071~26085	2026年3月31日	<p>本次共检高压开关设备15台，15台高压开关设备所检项目合格。</p> <p>。</p>	

122	GX-B1451/26-Z-26086~26089	2026年3月31日	本次共检高压开关设备4台，4台高压开关设备所检项目合格。 。	 <p>2026/3/2</p>
123	GX-B1336/26-Z-26001~26014	2026年3月31日	本次共检母线14条，14条母线所检项目合格。 。	 <p>2026/3/20</p>

124	GX-B1336/26-Z-26015~26016	2026年3月31日	本次共检母线2条，2条母线所检项目合格。 。	 <p>2026/3/20</p>
125	GX-B1336/26-Z-26017~26018	2026年3月31日	本次共检母线2条，2条母线所检项目合格。 。	 <p>2026/3/20</p>

126	GX-B1332/26-Z-26001~26006	2026年3月31日	本次共检电力电容器6台，6台电力电容器所检项目合格。	
127	GX-B1332/26-Z-26007~26012	2026年3月31日	本次共检电力电容器6台，6台电力电容器所检项目合格。	

128	GX-B1332/26-Z-26013~26021	2026年3月31日	本次共检电力电容器9台，9台电力电容器所检项目合格。	
129	GX-B1329/26-Z-26035~26049	2026年3月31日	本次共检氧化锌避雷器15组，15组氧化锌避雷器所检项目合格。	

130	B1417/22-Z-26001	2026年3月31日	综合判定：合格。	
131	GX-B1417/22-Z-26002	2026年3月31日	综合判定：合格。	

132	GX-B1417/22-Z-26003	2026年3月31日	综合判定：合格。	
133	GX-B1417/22-Z-26004	2026年3月31日	综合判定：合格。	

134	GX-B1417/22-Z-26005	2026年3月31日	综合判定：合格。	
135	GX-B1337/26-Z-26001~26012	2026年3月31日	本次共检互感器 12台，12台互感器所检 项目合格。	

136	GX-B1337/26-Z-26013~26033	2026年3月31日	本次共检互感器 21台，21台互感器所检 项目合格。	
137	GX-B1337/26-Z-26034~26051	2026年3月31日	本次共检互感器 18台，18台互感器所检 项目合格。	

138	GX-B1337/26-Z-26052~26075	2026年3月31日	本次共检互感器 24台，24台互感器所检 项目合格。	 A worker in a red safety suit and helmet is kneeling in a room with several electrical cabinets. He is working on one of the cabinets, which has its door open. A yellow date stamp '2026/3/15' is visible in the bottom right corner of the photo.
139	GX-B1337/26-Z-26076~26093	2026年3月31日	本次共检互感器 18台，18台互感器所检 项目合格。	 Two workers in red safety suits and helmets are working in a room with several electrical cabinets. One worker is kneeling and working on a cabinet, while the other is standing nearby. A yellow date stamp '2026/3/15' is visible in the bottom right corner of the photo.

140	GX-B1337/26-Z-26094~26113	2026年3月31日	本次共检互感器 20台，20台互感器所检 项目合格。	
141	GX-B1337/26-Z-26114~26129	2026年3月31日	本次共检互感器 16台，16台互感器所检 项目合格。	



142	GX-B1337/26-Z-26130~26153	2026年3月31日	本次共检互感器 24台，24台互感器所检 项目合格。	
143	GX-B1337/26-Z-26154~26169	2026年3月31日	本次共检互感器 16台，16台互感器所检 项目合格。	


144	GX-B1337/26-Z-26170~26199	2026年3月31日	本次共检互感器30台，30台互感器所检项目合格。	 <p>2026/3/19</p>
145	GX-B1313/26-Z-26001~26002	2026年3月30日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2026/3/2</p>

146	GX-B1313/26-Z-26003~26005	2026年3月30日	本次共检电力变压器3台，3台电力变压器所检项目合格。	
147	GX-B1313/26-Z-26006~26007	2026年3月30日	本次共检电力变压器2台，2台电力变压器所检项目合格。	

148	GX-B1313/26-Z-26008	2026年3月30日	所检项目合格。	 A photograph showing two workers in safety gear (hard hats and work clothes) standing next to a blue transformer. One worker is wearing a grey shirt and pants, while the other is in a red jumpsuit. They are outdoors, and a yellow toolbox is visible on the ground. A date stamp '2026/3/8' is in the bottom right corner.
149	GX-B1313/26-Z-26009~26012	2026年3月30日	本次共检电力变压器4台，4台电力变压器所检项目合格。	 A photograph showing two workers in safety gear (hard hats and work clothes) inspecting a transformer. One worker is standing and looking at a document, while the other is kneeling and working on the transformer. A yellow toolbox is visible on the ground. A date stamp '2026/3/14' is in the bottom right corner.

150	GX-B1313/26-Z-26013~26014	2026年3月30日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 A worker in an orange uniform and red helmet is standing inside a large electrical cabinet, working on the internal components. A date stamp '2026/3/15' is visible in the bottom right corner of the photo.
151	GX-B1313/26-Z-26015~26016	2026年3月30日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 A worker in an orange uniform and red helmet is kneeling inside a large electrical cabinet, working on the internal components. A date stamp '2026/3/15' is visible in the bottom right corner of the photo.

152	GX-B1313/26-Z-26017~26018	2026年3月30日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2026/3/16</p>
153	GX-B1313/26-Z-26019~26020	2026年3月30日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2026/3/16</p>

154	GX-B1313/26-Z-26021~26024	2026年3月30日	本次共检电力变压器4台，4台电力变压器所检项目合格。	
155	GX-B1313/26-Z-26025~26027	2026年3月30日	本次共检电力变压器3台，3台电力变压器所检项目合格。	

156	GX-B1313/26-Z-26028	2026年3月30日	所检项目合格。	 A photograph showing a worker in a red uniform and helmet working on a transformer. The worker is standing on a concrete base, and another worker in a red uniform is visible in the foreground, holding a clipboard. The date 2026/3/19 is visible in the bottom right corner of the image.
157	GX-B1313/26-Z-26029~26031	2026年3月30日	本次共检电力变压器3台，3台电力变压器所检项目合格。	 A photograph showing a worker in a red uniform and helmet standing next to a transformer. The worker is wearing a headlamp and is looking at the transformer. The date 2026/3/20 is visible in the bottom right corner of the image.