

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|-----------------------------|-------------|--------|--|
| 33 | GX-B1377/22-B-26059~B-26060 | 2026. 3. 23 | 所检项目合格 |  A photograph showing two men in a laboratory or office environment. They are standing behind a table with a piece of white equipment. One man is pointing at the equipment while the other looks on. The background includes a window with orange curtains and some items on the table. A timestamp '2026.3.17' is visible in the bottom right corner of the image. |
| 34 | GX-B1492/21-B-26019 | 2026. 3. 25 | 所检项目合格 |  A photograph showing two men in a laboratory or office environment. They are standing behind a table with a piece of white equipment. One man is pointing at the equipment while the other looks on. The background includes a window with orange curtains and some items on the table. A timestamp '2026.3.18' is visible in the bottom right corner of the image. |

| | | | | |
|----|-----------------------------|-------------|--------|---|
| 35 | GX-B1492/21-B-26020 | 2026. 3. 25 | 所检项目合格 |  A photograph showing two men in a laboratory setting. They are focused on a piece of scientific equipment, likely a spectrophotometer or similar analytical instrument. One man is adjusting a component on the machine while the other looks on. The background shows a window with light-colored curtains and a wall with a red notice and a yellow warning sign. A small timestamp '2026.3.18' is visible in the bottom right corner of the image. |
| 36 | GX-B1377/22-B-26072~B-26077 | 2026. 3. 26 | 所检项目合格 |  A photograph showing two men in a laboratory setting, similar to the one above. They are working with a different piece of laboratory equipment, possibly a spectrophotometer. Both men are looking intently at the machine. The background features a window with light-colored curtains and a wall with a red notice and a yellow warning sign. A small timestamp '2026.3.24' is visible in the bottom right corner of the image. |

| | | | | |
|----|-----------------------------|-------------|--------|--|
| 37 | GX-B1377/22-B-26078 | 2026. 3. 26 | 所检项目合格 |  A photograph showing two men in a laboratory or office setting. They are looking at a white machine with a perforated top panel. One man is pointing at the machine while the other looks on. The machine has a yellow warning triangle on the side. The date '2026.3.23' is visible in the bottom right corner of the photo. |
| 38 | GX-B1377/22-B-26061~B-26064 | 2026. 3. 31 | 所检项目合格 |  A photograph showing two men in a laboratory or office setting. They are looking at a white machine with a perforated top panel. One man is pointing at the machine while the other looks on. The machine has a yellow warning triangle on the side. The date '2026.3.19' is visible in the bottom right corner of the photo. |

| | | | | |
|----|---------------------|-------------|--------|--|
| 39 | GX-B1378/22-B-26049 | 2026. 3. 31 | 所检项目合格 |  |
| 40 | GX-B1378/22-B-26054 | 2026. 3. 27 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-------------|--------|--|
| 41 | GX-B1378/22-B-26055~B-26056 | 2026. 3. 27 | 所检项目合格 |  A photograph showing two men in a laboratory setting. They are standing behind a table with a piece of scientific equipment, possibly a spectrophotometer or a similar analytical instrument. One man is pointing at the top of the device while the other looks on. The background includes a window with light-colored curtains and some laboratory supplies on a shelf to the left. A small timestamp '2026.3.27' is visible in the bottom right corner of the image. |
| 42 | GX-B1378/22-B-26057 | 2026. 3. 27 | 所检项目合格 |  A photograph showing two men in a laboratory setting, similar to the one above. They are standing behind a table with the same piece of scientific equipment. The man on the left is pointing at the device, and the man on the right is looking at it. The background is consistent with the first image, showing a window with curtains and laboratory supplies. A small timestamp '2026.3.27' is visible in the bottom right corner of the image. |