

序号	报告编号	发布日期	结论	影像资料
2 3 8	GX-B1538/26-A-26013	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 3 9	GX-B1538/26-A-26014	2026/3/18	所检项目合格。	 <p>The photograph shows two individuals in grey work uniforms. The person in the foreground has 'CIC 中检公信' printed on the back of their jacket. They are standing in front of a piece of industrial equipment with a control panel and a warning sign that reads '注意高温' (Caution High Temperature). A date stamp '2026.03.12' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
240	GX-B1538/26-A-26015	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 1	GX-B1538/26-A-26016	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 2	GX-B1538/26-A-26017	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 3	GX-B1538/26-A-26018	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 4	GX-B1538/26-A-26019	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 5	GX-B1538/26-A-26020	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 6	GX-B1458/26-A-26007	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 7	GX-B1538/26-A-26008	2026/3/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 8	GX-B1538/26-A-26010	2026/3/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 4 9	GX-B1538/26-A-26011	2026/3/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
250	GX-B1538/26-A-26012	2026/3/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
251	GX-B1364/26-A-26166	2026/3/19	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 5 2	GX-B1364/26-A-26167	2026/3/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 5 3	GX-B1364/26-A-26168	2026/3/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 5 4	GX-B1363/25-A-26098	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
255	GX-B1363/25-A-26097	2026/3/18	所检项目合格。	 A photograph showing two workers in grey protective suits and yellow gloves operating a large blue industrial machine with two doors. The machine has a white top section. A date stamp '2026 03 15' is visible in the bottom right corner of the photo. A warning sign is also visible on the machine's door.

序号	报告编号	发布日期	结论	影像资料
2 5 6	GX-B1363/25-A-26096	2026/3/18	所检项目合格。	 A photograph showing two workers in a laboratory setting. They are wearing grey lab coats and safety glasses. One worker is wearing yellow gloves. They are inspecting a large, industrial-looking furnace or oven with its doors open. The furnace has a conical top and a cylindrical chimney-like structure. The date '2026.03.14' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
2 5 7	GX-B1363/25-A-26095	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 5 8	GX-B1363/25-A-26094	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 5 9	GX-B1363/25-A-26100	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1363/25-A-26099	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
261	GX-B1363/25-A-26104	2026/3/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 6 2	GX-B1363/25-A-26105	2026/3/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 6 3	GX-B1363/25-A-26102	2026/3/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 6 4	GX-B1363/25-A-26101	2026/3/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 6 5	GX-B1363/25-A-26103	2026/3/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
266	GX-B1363/25-A-26106	2026/3/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 6 7	GX-B1364/26-A-26179	2026/3/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
268	GX-B1364/26-A-26180	2026/3/23	所检项目合格。	 <p>The image shows two technicians in grey uniforms with the '中检公信' (CIC) logo on their backs. They are in a laboratory setting. One technician is operating a piece of equipment with a '注意高温' (High Temperature) warning sign. The date '2026 03 21' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
269	GX-B1364/26-A-26177	2026/3/23	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
270	GX-B1364/26-A-26173	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
271	GX-B1364/26-A-26174	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 7 2	GX-B1364/26-A-26175	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 7 3	GX-B1364/26-A-26176	2026/3/21	所检项目不合格。	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1364/26-A-26178	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 7 5	GX-B1364/26-A-26181	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
276	GX-B1364/26-A-26182	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 7 7	GX-B1364/26-A-26183	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 7 8	GX-B1364/26-A-26184	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 7 9	GX-B1364/26-A-26185	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1364/26-A-26186	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
281	GX-B1364/26-A-26187	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1364/26-A-26188	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
283	GX-B1364/26-A-26189	2026/3/21	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
284	GX-B1364/26-A-26190	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
285	GX-B1364/26-A-26191	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
286	GX-B1364/26-A-26192	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
287	GX-B1364/26-A-26193	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
288	GX-B1364/26-A-26194	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
289	GX-B1364/26-A-26195	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
290	GX-B1364/26-A-26196	2026/3/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
291	GX-B1367/26-A-26021	2026/3/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 9 2	GX-B1458/26-A-26008	2026/3/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 9 3	GX-B1458/26-A-26009	2026/3/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 9 4	GX-B1363/25-A-26107	2026/3/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 9 5	GX-B1363/25-A-26108	2026/3/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
296	GX-B1363/25-A-26109	2026/3/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2 9 7	GX-B1365/25-A-26019	2026/3/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
298	GX-B1365/25-A-26020	2026/3/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
2 9 9	GX-B1365/25-A-26021	2026/3/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
300	GX-B1366/25-A-26024	2026/3/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
3 0 1	GX-B1366/25-A-26025	2026/3/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
3 0 2	GX-B1366/25-A-26026	2026/3/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
3 0 3	GX-B1363/25-A-26112	2026/3/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 0 4	GX-B1363/25-A-26111	2026/3/26	所检项目合格。	