


序号	报告编号	发布日期	结论	影像资料
1	GX-B1324/26-3-26034~26039	2026. 4. 1	所检项目合格。	
2	GX-B1324/26-3-26040~26045	2026. 4. 1	所检项目合格。	

3	:GX-B1324/26-3-26046~26051	2026. 4. 1	所检项目合格。	
4	GX-B1313/26-3-26064	2026. 4. 2	所检项目合格。	

5	GX-B1324/26-3-26053	2026. 4. 2	所检项目合格。	
6	GX-B1322/26-3-26165~26167	2026. 4. 1	所检项目合格。	

7	GX-B1323/26-3-26236~26239	2026. 4. 3	所检项目合格。	
8	GX-B1323/26-3-26240~26242	2026. 4. 3	所检项目合格。	

9	GX-B1323/26-3-26243~26244	2026. 4. 3	所检项目合格。		 <p>2026.1.31</p>
10	GX-B1323/26-3-26245~26248	2026. 4. 3	所检项目合格。		 <p>2026.2.1</p>

11	GX-B1350/21-3-26015	2026. 4. 3	所检项目合格。	
12	GX-B1322/26-3-26159~26162	2026. 4. 3	所检项目合格。	


13	GX-B1310/21-3-26206	2026. 4. 3	符合标准要求。		 A worker wearing a blue long-sleeved uniform, a red hard hat, and a red tool bag is working on a large, complex industrial machine. The machine has various components, including a large circular part. The worker is focused on the task. A yellow timestamp '2026.4.1' is visible in the bottom right corner of the photo.	
14	GX-B1310/21-3-26207	2026. 4. 3	符合标准要求。		 A worker wearing a blue uniform, a red hard hat, and a red tool bag is standing next to a large, dark industrial wheel. The worker is looking at the wheel. The background shows a concrete wall and some pipes. A yellow timestamp '2026.4.1' is visible in the bottom right corner of the photo.	

15	GX-B1310/21-3-26208	2026. 4. 3	符合标准要求。	 <p>2026.4.1</p>
16	GX-B1310/21-3-26209	2026. 4. 3	符合标准要求。	 <p>2026.4.1</p>

17	GX-B1310/21-3-26210	2026. 4. 3	符合标准要求。	 A worker in a blue jacket and red helmet is working on a large green industrial machine with a yellow circular component. The worker is positioned on the left side of the machine, and the machine is located in a tunnel or underground setting. The date 2026.4.1 is visible in the bottom right corner of the image.
18	GX-B1310/21-3-26211	2026. 4. 3	符合标准要求。	 A worker in a blue jacket and red helmet is working on a large industrial machine in a tunnel. The worker is positioned on a metal structure, and the machine is located in a tunnel or underground setting. The date 2026.4.1 is visible in the bottom right corner of the image.

19	GX-B1310/21-3-26212	2026. 4. 3	符合标准要求。	
20	GX-B1310/21-3-26213	2026. 4. 3	符合标准要求。	

21	GX-B1310/21-3-26214	2026. 4. 3	符合标准要求。	 <p>2026.4.1</p>
22	GX-B1328/26-3-26108	2026. 4. 7	本次共检绝缘手套36只，36只绝缘手套合格。	 <p>2026/4/1</p>

23	GX-B1328/26-3-26109	2026. 4. 7	本次共检绝缘靴 36只，36只绝缘靴合格。 。	
24	GX-B1328/26-3-26110	2026. 4. 7	本次共检验电器9支， 9支验电器合格。	

25	GX-B1328/26-3-26111	2026. 4. 7	本次共检绝缘杆 18组，18组绝缘杆合格。 。	 A photograph showing a testing stand with two yellow vertical posts and a black horizontal bar. The stand is positioned in a laboratory or workshop with a tiled floor and white walls. A date stamp '2026/4/1' is visible in the bottom right corner of the image.
26	GX-B1328/26-3-26112	2026. 4. 7	本次共检便携式接地 和接地短路装置9套， 9套便携式接地和接地 短路装置合格。	 A photograph showing a testing stand similar to the one in the first row, but with green components instead of yellow. It is located in the same laboratory setting. A date stamp '2026/4/1' is visible in the bottom right corner of the image.

27	GX-B1495/20-3-26231~26239	2026. 4. 3	本次共检高压开关设备9台，9台高压开关设备所检项目合格。	
28	GX-B1495/20-3-26240~26249	2026. 4. 3	本次共检高压开关设备10台，10台高压开关设备所检项目合格。	

29	GX-B1495/20-3-26250~26254	2026. 4. 3	本次共检高压开关设备5台，5台高压开关设备所检项目合格。		 <p>2026.01.31</p>
30	GX-B1495/20-3-26265~26274	2026. 4. 3	本次共检高压开关设备10台，10台高压开关设备所检项目合格。		 <p>2026.02.01</p>

31	GX-B1495/20-3-26275~26284	2026. 4. 3	本次共检高压开关设备10台，10台高压开关设备所检项目合格。		 A photograph showing several workers in blue work clothes and red hard hats standing in a control room or office, looking at computer monitors. The room is dimly lit, with light coming from the screens. A timestamp '2026.02.02' is visible in the bottom right corner of the photo.	
32	GX-B1329/26-3-26088	2026. 4. 3	所检项目合格。		 A photograph of a worker wearing a red hard hat and a black jacket, kneeling on a light-colored tiled floor. The worker is positioned next to a large, grey metal cabinet, likely a high-voltage switchgear. The worker appears to be inspecting or working on a component on the floor. A timestamp '2026/3/3' is visible in the bottom right corner of the photo.	

33	GX-B1451/26-3-26188	2026. 4. 3	所检项目合格。	
34	GX-B1337/26-3-26001~26002	2026. 4. 3	本次共检电流互感器2只，2只所检项目合格。	