


序号	报告编号	发布日期	结论	影像资料
33	GX-B1309/26-1-26006	2026. 4. 7	所检项目合格	 A photograph showing a worker in a red hard hat, safety glasses, and a grey work jacket with reflective stripes. The worker is wearing blue pants and black boots, and is kneeling in a rocky tunnel environment, possibly performing maintenance or inspection. A date stamp '2026/08/11' is visible in the bottom right corner of the image.
34	GX-B1500/26-1-26033	2026. 4. 7	综合判定：合格	 A photograph of a worker in a red hard hat and grey uniform standing in a tunnel. The worker is positioned near a large piece of blue machinery, possibly a pump or generator. The tunnel walls are rocky, and there are green pipes and other equipment visible in the background. A date stamp '2026/08/11' is visible in the bottom right corner of the image.

35	GX-B1500/26-1-26034	2026. 4. 7	综合判定：合格	
36	GX-B1500/26-1-26035	2026. 4. 7	综合判定：合格	

37	GX-B1310/21-1-26130	2026. 4. 7	符合标准要求	
38	GX-B1598/24-1-26006	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为3.22%，小于5%为正常	

39	GX-B1598/24-1-26007	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为3.13%，小于5%为正常		 <p>2026/02/13</p>
40	GX-B1598/24-1-26008	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为2.24%，小于5%为正常		 <p>2026/02/13</p>

41	GX-B1598/24-1-26009	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为2.34%，小于5%为正常		
42	GX-B1598/24-1-26010	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为3.54%，小于5%为正常		

43	GX-B1598/24-1-26011	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为3.39%，小于5%为正常		
44	GX-B1598/24-1-26012	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为3.37%，小于5%为正常		

45	GX-B1598/24-1-26013	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为3.22%，小于5%为正常		 <p>2026/02/13</p>
46	GX-B1598/24-1-26014	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为2.22%，小于5%为正常		 <p>2026/02/13</p>

47	GX-B1598/24-1-26015	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为2.19%，小于5%为正常	 <p>2026/02/13</p>
48	GX-B1598/24-1-26082	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为2.25%，小于5%为正常	 <p>2026/2/13</p>

49	GX-B1598/24-1-26083	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为2.15%，小于5%为正常		
50	GX-B1598/24-1-26084	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为1.81%，小于5%为正常		

51	GX-B1598/24-1-26085	2026. 4. 7	实测钢丝绳有效截面积损失百分比最大为1.85%，小于5%为正常	 A worker wearing a red safety suit and a red helmet is using a handheld tool to inspect a steel cable. The worker is positioned on a metal platform or staircase. The background shows industrial equipment and a yellow safety railing. A yellow timestamp '2026/2/13' is visible in the bottom right corner of the image.
52	GX-B1598/24-1-26090	2026. 4. 8	实测钢丝绳有效截面积损失百分比最大为0.76%，小于5%为正常	 Two workers in safety gear are inspecting a large steel cable in an industrial facility. One worker is wearing a red helmet and a grey safety suit, while the other is wearing a blue safety suit. They are standing on a green-painted floor. The background shows industrial equipment and a large green wheel. A yellow timestamp '2026/4/4' is visible in the bottom right corner of the image.



53	GX-B1598/24-1-26091	2026. 4. 8	实测钢丝绳有效截面积损失百分比最大为0.78%，小于5%为正常	 <p>2026/4/4</p>
54	GX-B1598/24-1-26086	2026. 4. 8	实测钢丝绳有效截面积损失百分比最大为0.74%，小于5%为正常	 <p>2026.3.24</p>

55	GX-B1598/24-1-26087	2026. 4. 8	实测钢丝绳有效截面积损失百分比最大为0.70%，小于5%为正常	 <p>2026.3.24</p>
56	GX-B1598/24-1-26088	2026. 4. 8	实测钢丝绳有效截面积损失百分比最大为0.78%，小于5%为正常	 <p>2026.4.2</p>



57	GX-B1598/24-1-26089	2026. 4. 8	实测钢丝绳有效截面积损失百分比最大为0.89%，小于5%为正常	
58	GX-B1313/26-1-26036~26037	2026. 4. 8	本次共检电力变压器2台，2台电力变压器所检项目合格	



59	GX-B1451/26-1-26196~26208	2026. 4. 8	本次共检高压开关柜 13台, 13台高压开关柜 所检项目合格	
60	GX-B1451/26-1-26209~26215	2026. 4. 8	本次共检高压开关柜7 台, 7台高压开关柜所 检项目合格	



61	GX-B1451/26-1-26230~26233	2026. 4. 8	本次共检高压开关柜4台, 4台高压开关柜所检项目合格	 <p>2026/03/13</p>
62	GX-B1309/26-1-26013	2026. 4. 8	所检项目合格	 <p>2026/03/04</p>

63	GX-B1500/26-1-26057	2026. 4. 8	综合判定：合格		
64	GX-B1500/26-1-26058	2026. 4. 8	综合判定：合格		

65	GX-B1451/26-1-26234~26240	2026. 4. 9	本次共检高压开关柜7台, 7台高压开关柜所检项目合格	
66	GX-B1329/26-1-26074~26081	2026. 4. 9	本次共检氧化锌避雷器8组, 8组所检项目合格	

67	GX-B1303/26-1-26012	2026. 4. 10	所检项目合格	
68	GX-B1307/26-1-26013	2026. 4. 9	综合判定：合格	

69	GX-B1307/26-1-26014	2026. 4. 10	综合判定：合格	
70	GX-B1307/26-1-26015	2026. 4. 10	综合判定：合格	



71	GX-B1307/26-1-26016	2026. 4. 10	综合判定：合格	
72	GX-B1307/26-1-26017	2026. 4. 10	综合判定：合格	

73	GX-B1307/26-1-26018	2026. 4. 10	综合判定：合格	
74	GX-B1309/26-1-26010	2026. 4. 10	所检项目合格	



75	GX-B1500/26-1-26047	2026. 4. 10	综合判定：合格	
76	GX-B1500/26-1-26048	2026. 4. 10	综合判定：合格	



77	GX-B1500/26-1-26049	2026. 4. 10	综合判定：合格		
78	GX-B1309/26-1-26015	2026. 4. 10	所检项目合格		



79	GX-B1500/26-1-26065	2026. 4. 10	综合判定：合格	
80	GX-B1500/26-1-26066	2026. 4. 10	综合判定：合格	



81	GX-B1500/26-1-26067	2026. 4. 10	综合判定：合格	
82	GX-B1500/26-1-26068	2026. 4. 10	综合判定：合格	



83	GX-B1309/26-1-26016	2026. 4. 10	所检项目合格	
84	GX-B1500/26-1-26069	2026. 4. 10	综合判定：合格	



85	GX-B1500/26-1-26070	2026. 4. 10	综合判定：合格	
86	GX-B1500/26-1-26071	2026. 4. 10	综合判定：合格	

87	GX-B1309/26-1-26012	2026. 4. 10	所检项目合格	
88	GX-B1500/26-1-26053	2026. 4. 10	综合判定：合格	

89	GX-B1500/26-1-26054	2026. 4. 10	综合判定：合格			
90	GX-B1500/26-1-26055	2026. 4. 10	综合判定：合格			

91	GX-B1500/26-1-26056	2026. 4. 10	综合判定：合格	
92	GX-B1309/26-1-26014	2026. 4. 10	所检项目合格	



93	GX-B1500/26-1-26061	2026. 4. 10	综合判定：合格		
94	GX-B1500/26-1-26062	2026. 4. 10	综合判定：合格		

95	GX-B1500/26-1-26063	2026. 4. 10	综合判定：合格		
96	GX-B1500/26-1-26064	2026. 4. 10	综合判定：合格		

97	GX-B1313/26-1-26111~26112	2026. 4. 10	本次共检电力变压器2台，2台电力变压器所检项目合格			
98	GX-B1451/26-1-26241~26245	2026. 4. 10	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格			


99	GX-B1313/26-1-26072~26075	2026. 4. 10	本次共检电力变压器4台，4台电力变压器所检项目合格		
100	GX-B1313/26-1-26076~26080	2026. 4. 10	本次共检电力变压器5台，5台电力变压器所检项目合格		

101	GX-B1313/26-1-26081~26083	2026. 4. 10	本次共检电力变压器3台，3台电力变压器所检项目合格		 <p>2026.3.24</p>	
102	GX-B1313/26-1-26084~26087	2026. 4. 10	本次共检电力变压器4台，4台电力变压器所检项目合格		 <p>2026.3.24</p>	

103	GX-B1380/26-1-26017	2026. 4. 10	所检项目合格	
104	GX-B1380/26-1-26018	2026. 4. 10	所检项目合格	

105	GX-B1380/26-1-26019	2026. 4. 10	所检项目合格			
106	GX-B1380/26-1-26020	2026. 4. 10	所检项目合格			

107	GX-B1380/26-1-26021	2026. 4. 10	所检项目合格			
108	GX-B1380/26-1-26022	2026. 4. 10	所检项目合格			

109	GX-B1380/26-1-26023	2026. 4. 10	所检项目合格	
110	GX-B1304/26-1-26008	2026. 4. 10	综合判定：合格	