


序号	报告编号	发布日期	结论	影像资料
53	GX-B1310/21-2-26151	2026/4/1	符合标准要求。	
54	GX-B1310/21-2-26152	2026/4/1	符合标准要求。	

55	GX-B1310/21-2-26153	2026/4/1	符合标准要求。	 <p>03月 02 2026.03.02 星期一 福建省龙岩市上杭县才溪镇</p>
56	GX-B1428/21-2-26154	2026/4/1	符合标准要求。	 <p>03月 10 2026.03.10 星期二 福建省龙岩市上杭县才溪镇</p>

57	GX-B1598/24-2-26139	2026. 4. 3	实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。	 <p>2026/03/21</p>
58	GX-B1598/24-2-26140	2026. 4. 3	实测钢丝绳有效截面积损失百分比最大为1.29%，小于5%为正常。	 <p>2026/03/21</p>

59	GX-B1598/24-2-26141	2026. 4. 3	实测钢丝绳有效截面积损失百分比最大为1.13%，小于5%为正常。	 A photograph showing two workers in red hard hats and dark work clothes inspecting a large steel cable. One worker is standing and looking at the cable, while the other is kneeling and working on it. The background shows an industrial interior with a metal railing and a wall with some signs. A timestamp '2026/03/21' is visible in the bottom right corner of the photo.
60	GX-B1598/24-2-26142	2026. 4. 3	实测钢丝绳有效截面积损失百分比最大为1.33%，小于5%为正常。	 A close-up photograph of workers inspecting a steel cable. One worker in a red hard hat is in the foreground, looking towards the camera. Another worker is visible in the background, also wearing a red hard hat and working on the cable. The setting is an industrial interior with a metal railing. A timestamp '2026/03/21' is visible in the bottom right corner of the photo.

61	GX-B1310/21-2-26151	2026. 4. 1	符合标准要求。	
62	GX-B1310/21-2-26152	2026. 4. 1	符合标准要求。	

63	GX-B1310/21-2-26153	2026. 4. 1	符合标准要求。	 <p>03月 02 2026.03.02 星期一 福建省龙岩市上杭县才溪镇</p>
64	GX-B1428/21-2-26154	2026. 4. 1	无缺陷迹痕显示。	 <p>03月 10 2026.03.10 星期二 福建省龙岩市上杭县才溪镇</p>

65	GX-B1382/26-2-26007	2026. 4. 7	综合判定：合格。	
66	GX-B1309/26-2-26021	2026. 4. 5	所检项目合格。	



67	GX-B1500/26-2-26086	2026. 4. 5	综合判定：合格。	
68	GX-B1500/26-2-26087	2026. 4. 5	综合判定：合格。	

69	GX-B1500/26-2-26088	2026. 4. 5	综合判定：合格。		
70	GX-B1500/26-2-26089	2026. 4. 5	综合判定：合格。		

71	GX-B1309/26-2-26019	2026. 4. 5	所检项目合格。		 <p>2026/03/25</p>
72	GX-B1500/26-2-26074	2026. 4. 5	综合判定：合格。		 <p>2026/03/25</p>


73	GX-B1500/26-2-26075	2026. 4. 5	综合判定：合格。	
74	GX-B1500/26-2-26076	2026. 4. 5	综合判定：合格。	

75	GX-B1500/26-2-26077	2026. 4. 5	综合判定：合格。	
76	GX-B1309/26-2-26020	2026. 4. 5	所检项目合格。	

77	GX-B1500/26-2-26078	2026. 4. 5	综合判定：合格。	
78	GX-B1500/26-2-26079	2026. 4. 5	综合判定：合格。	

79	GX-B1500/26-2-26080	2026. 4. 5	综合判定：合格。	
80	GX-B1500/26-2-26081	2026. 4. 5	综合判定：合格。	

81	GX-B1500/26-2-26082	2026. 4. 5	综合判定：合格。		
82	GX-B1309/26-2-26018	2026. 4. 5	所检项目合格。		

83	GX-B1500/26-2-26067	2026. 4. 5	综合判定：合格。	
84	GX-B1500/26-2-26068	2026. 4. 5	综合判定：合格。	

85	GX-B1500/26-2-26069	2026. 4. 5	综合判定：合格。			
86	GX-B1500/26-2-26070	2026. 4. 5	综合判定：合格。			

87	GX-B1500/26-2-26071	2026. 4. 5	综合判定：合格。	
88	GX-B1500/26-2-26072	2026. 4. 5	综合判定：合格。	

89	GX-B1500/26-2-26073	2026. 4. 5	综合判定：合格。	 <p>2026/03/16</p>
90	GX-B1328/26-2-26043	2026. 4. 7	本次共检绝缘手套40只，40只绝缘手套合格。	 <p>2026/02/23</p>



91	GX-B1328/26-2-26044	2026. 4. 7	本次共检绝缘靴 38只，38只绝缘靴合格。 。	 <p>2026/02/23</p>
92	GX-B1328/26-2-26045	2026. 4. 7	本次共检验电器 15支，15支验电器合格。 。	 <p>2026/02/23</p>

93	GX-B1328/26-2-26046	2026. 4. 7	本次共检携带式接地和接地短路装置15组，15组携带式接地和接地短路装置合格。	 <p>2026/02/28</p>
94	GX-B1328/26-2-26047	2026. 4. 7	本次共检绝缘杆1组，1组绝缘杆合格。	 <p>2026/02/28</p>


95	GX-B1328/26-2-26055	2026. 4. 7	本次共检绝缘手套14只，14只绝缘手套合格。	 <p>2026/3/16</p>
96	GX-B1328/26-2-26056	2026. 4. 7	本次共检绝缘靴12只，12只绝缘靴合格。	 <p>2026/3/16</p>

97	GX-B1328/26-2-26057	2026. 4. 7	本次共检验电器2支， 2支验电器合格。	
98	GX-B1328/26-2-26058	2026. 4. 7	本次共检便携式接 地和接地短路装置 2组，2组便携式接地 和接地短路装置合格 。	

99	GX-B1328/26-2-26059	2026. 4. 7	本次共检绝缘杆2组， 2组绝缘杆合格。	 <p>2026/3/16</p>
100	GX-B1539/22-2-26009	2026. 4. 10	除上述问题外，其余 所检项目合格。	 <p>03月 11 2026. 03. 11 星期三 福建省龙岩市上杭县旧县镇汀江</p>

101	GX-B1539/22-2-26010	2026. 4. 10	除上述问题外，其余所检项目合格。	
102	GX-B1539/22-2-26011	2026. 4. 10	除上述问题外，其余所检项目合格。	

103	GX-B1539/22-2-26012	2026. 4. 10	除上述问题外，其余所检项目合格。	 <p>03月 11 2026-03-11 星期三 福建省龙岩市上杭县旧县镇汀江</p>
104	GX-B1495/26-2-26001~26002	2026. 4. 8	本次共检防爆型高压配电装置2台，2台所检项目合格。	 <p>2026/02/09</p>

105	GX-B1332/26-2-26001~26009	2026. 4. 10	本次共检电力电容器9台，9台所检项目合格。 。	
-----	---------------------------	-------------	----------------------------	---