

序号	报告编号	发布日期	结论	影像资料
27	GX-B1321/26-7-26156~26159	2026. 4. 9	本次共检电力电缆 4条，4条电力电缆所 检项目合格。	
28	GX-B1321/26-7-26160~26164	2026. 4. 9	本次共检电力电缆 5条，5条电力电缆所 检项目合格。	

29	GX-B1321/26-7-26165~26166	2026. 4. 9	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	
30	GX-B1321/26-7-26167~26172	2026. 4. 9	本次共检电力电缆 6条，6条电力电缆所 检项目合格。	

31	GX-B1321/26-7-26173~26181	2026. 4. 9	本次共检电力电缆 9条，9条电力电缆所 检项目合格。			
32	GX-B1321/26-7-26182~26186	2026. 4. 9	本次共检电力电缆 5条，5条电力电缆所 检项目合格。			

33	GX-B1321/26-7-26187~26199	2026. 4. 9	本次共检电力电缆13条，13条电力电缆所检项目合格。	
34	GX-B1321/26-7-26127~26133	2026. 4. 9	本次共检电力电缆7条，7条电力电缆所检项目合格。	

35	GX-B1321/26-7-26134~26139	2026. 4. 9	本次共检电力电缆 4条，4条电力电缆所 检项目合格。			
36	GX-B1321/26-7-26140~26153	2026. 4. 9	本次共检电力电缆14 条，14条电力电缆所 检项目合格。			

37	GX-B1321/26-7-26154~26155	2026. 4. 9	本次共检电力电缆 2条，2条电力电缆所 检项目合格。			
38	GX-B1323/26-7-26015~26017	2026. 4. 9	所检项目合格。			

39	GX-B1495/26-7-26599~26611	2026. 4. 9	本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。			
40	GX-B1495/26-7-26612~26620	2026. 4. 9	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。			

41	GX-B1495/26-7-26621~26628	2026. 4. 9	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
42	GX-B1495/26-7-26629~26636	2026. 4. 9	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	

43	GX-B1495/26-7-26637~26642	2026. 4. 9	本次共检高压开关柜6台，6台高压开关柜所检项目合格。	 A photograph showing a worker in a blue hard hat and white jacket inspecting a high-voltage switchgear cabinet in a control room. The worker is holding a clipboard and looking at the equipment. The date stamp '2026.3.16' is visible in the bottom right corner of the image.
44	GX-B1312/26-7-26202~26203	2026. 4. 9	本次共检电力变压器2台，2台电力变压器所检项目合格。	 A photograph showing a high-voltage transformer in a control room. A red warning sign with a lightning bolt symbol and the text '高压危险' (High Voltage Danger) is visible. The date stamp '2026.3.17' is visible in the bottom right corner of the image.

45	GX-B1312/26-7-26188~26189	2026. 4. 9	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2026/3/17</p>
46	GX-B1312/26-7-26190~26195	2026. 4. 9	本次共检电力变压器6台，6台电力变压器所检项目合格。	 <p>2026/3/18</p>

47	GX-B1323/26-7-26018~26023	2026. 4. 9	所检项目合格。	
48	GX-B1312/26-7-26134~26135	2026. 4. 9	本次共检电力变压器2台，2台电力变压器所检项目合格。	

49	GX-B1312/26-7-26136~26138	2026. 4. 9	本次共检电力变压器3台，3台电力变压器所检项目合格。		
50	GX-B1312/26-7-26139~26141	2026. 4. 9	本次共检电力变压器3台，3台电力变压器所检项目合格。		

51	GX-B1312/26-7-26142~26144	2026. 4. 9	本次共检电力变压器3台，3台电力变压器所检项目合格。	
52	GX-B1312/26-7-26145~26146	2026. 4. 9	本次共检电力变压器2台，2台电力变压器所检项目合格。	

53	GX-B1312/26-7-26147~26148	2026. 4. 9	本次共检电力变压器2台，2台电力变压器所检项目合格。			
54	GX-B1328/26-7-26008	2026. 4. 9	本次共检绝缘手套52只，52只绝缘手套合格。			

55	GX-B1328/26-7-26009	2026. 4. 9	本次共检绝缘靴 52只，52只绝缘靴合格。 。	
56	GX-B1328/26-7-26010	2026. 4. 9	本次共检验电器 30只，30只验电器合格。 。	


57	GX-B1328/26-7-26011	2026. 4. 9	本次共检便携式接地和接地短路装置24套，24套便携式接地和接地短路装置合格。	
58	GX-B1495/26-7-26493~26502	2026. 4. 10	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	

59	GX-B1495/26-7-26503~26511	2026. 4. 10	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。			
60	GX-B1495/26-7-26512~26525	2026. 4. 10	本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。			

61	GX-B1495/26-7-26526~26530	2026. 4. 10	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。			
62	GX-B1547/26-7-26001~26006	2026. 4. 10	本次共检继电保护装置6台，6台所检项目合格。			

63	GX-B1318/26-7-26001~26005	2026. 4. 10	本次共检高压交流断路器5台，5台高压交流断路器所检项目合格。	
64	GX-B1332/26-7-26001~26018	2026. 4. 10	本次共检电容器18台，18台所检项目合格。	

65	GX-B1495/26-7-26643~26658	2026. 4. 10	本次共检高压防爆开关16台，16台高压防爆开关所检项目合格。	 A worker in a red uniform and helmet is inspecting a high-voltage switch cabinet. The worker is holding a device, possibly a testing instrument. The cabinet is open, revealing internal components. A date stamp '2026.3.17' is visible in the bottom right corner of the photo.
66	GX-B1329/26-7-26021~26038	2026. 4. 10	本次共检氧化锌避雷器18组，18组氧化锌避雷器所检项目合格。	 A worker in a grey uniform and red helmet is testing a zinc oxide arrester. The worker is using a testing instrument with red and black leads connected to the arrester. A date stamp '2026/3/26' is visible in the bottom right corner of the photo.

67	GX-B1329/26-7-26039~26050	2026. 4. 10	本次共检氧化锌避雷器12组，12组氧化锌避雷器所检项目合格。	 A photograph showing a worker in a red uniform and helmet kneeling on a green floor, testing a zinc oxide arrester. The worker is using a red test lead connected to a black device. A date stamp '2026/3/27' is visible in the bottom right corner of the photo. <p data-bbox="1765 592 1854 608">2026/3/27</p>
----	---------------------------	-------------	--------------------------------	--