

序号	报告编号	发布日期	结论	影像资料
1 3 3	GX-B1363/25-A-26125	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 3 4	GX-B1507/26-A-26003	2026/4/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 3 5	GX-B1507/26-A-26002	2026/4/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 3 6	GX-B1367/26-A-26027	2026/4/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 3 7	GX-B1367/26-A-26026	2026/4/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 3 8	GX-B1508/26-A-26001	2026/4/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 3 9	GX-B1363/25-A-26126	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 0	GX-B1363/25-A-26128	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 1	GX-B1363/25-A-26124	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 2	GX-B1364/26-A-26252	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 3	GX-B1364/26-A-26251	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 4	GX-B1364/26-A-26250	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 5	GX-B1364/26-A-26249	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 6	GX-B1364/26-A-26248	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 7	GX-B1364/26-A-26247	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 8	GX-B1364/26-A-26244	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 4 9	GX-B1364/26-A-26243	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 0	GX-B1364/26-A-26242	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 1	GX-B1364/26-A-26241	2026/4/8	所检项目合格。	 <p>The photograph shows two individuals in grey work uniforms. The person in the foreground is seen from the back, wearing a uniform with the logo '中检公信' (China Inspection and Certification) and the letters 'CIC'. The person in the background is facing left. They are standing in front of a dark piece of equipment. On the wall behind them is a yellow triangular warning sign with the Chinese characters '高温' (High Temperature) and a symbol of three wavy lines. A date stamp '2026.03.31' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
1 5 2	GX-B1364/26-A-26240	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 3	GX-B1364/26-A-26239	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 4	GX-B1364/26-A-26238	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 5	GX-B1364/26-A-26237	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 6	GX-B1364/26-A-26236	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 7	GX-B1364/26-A-26235	2026/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 8	GX-B1364/26-A-26301	2026/4/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 5 9	GX-B1366/25-A-26033	2026/4/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
1 6 0	GX-B1365/25-A-26027	2026/4/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
1 6 1	GX-B1366/25-A-26036	2026/4/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
1 6 2	GX-B1364/26-A-26270	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 6 3	GX-B1364/26-A-26269	2026/4/9	所检项目合格。	 <p>The photograph shows two individuals in grey work uniforms. The person on the right is seen from the back, with a logo on their jacket that reads 'CIC 中检公信'. They are standing in front of a piece of equipment with a yellow warning sign that says '注意高温' (Caution High Temperature). A timestamp '2026.04.03' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
1 6 4	GX-B1364/26-A-26268	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 6 5	GX-B1364/26-A-26267	2026/4/9	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
1 6 6	GX-B1364/26-A-26258	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 6 7	GX-B1364/26-A-26257	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 6 8	GX-B1364/26-A-26254	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 6 9	GX-B1364/26-A-26255	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 0	GX-B1364/26-A-26256	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 1	GX-B1364/26-A-26253	2026/4/9	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 2	GX-B1364/26-A-26259	2026/4/9	成束电线电缆燃烧试验不合格，其他所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 3	GX-B1364/26-A-26260	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 4	GX-B1364/26-A-26261	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 5	GX-B1364/26-A-26262	2026/4/9	成束电线电缆燃烧试验不合格，其他所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 6	GX-B1364/26-A-26263	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 7	GX-B1364/26-A-26264	2026/4/9	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
1 7 8	GX-B1364/26-A-26265	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 7 9	GX-B1364/26-A-26266	2026/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
180	GX-B1364/26-A-26276	2026/4/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 1	GX-B1364/26-A-26277	2026/4/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 2	GX-B1364/26-A-26278	2026/4/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 3	GX-B1364/26-A-26279	2026/4/14	所检项目合格。	 <p>The photograph shows two men in white work uniforms inspecting a piece of industrial equipment. The man on the right has '中检公' (China Inspection Company) printed on his back. The equipment has a control panel with a screen and several buttons. A yellow warning sign is visible above the panel. A timestamp '2026.04.08' is in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
1 8 4	GX-B1538/26-A-26047	2026/4/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 5	GX-B1538/26-A-26041	2026/4/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 6	GX-B1538/26-A-26042	2026/4/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 7	GX-B1367/26-A-26028	2026/4/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 8	GX-B1367/26-A-26029	2026/4/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 8 9	GX-B1363/25-A-26129	2026/4/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 0	GX-B1363/25-A-26130	2026/4/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
1 9 1	GX-B1363/25-A-26131	2026/4/15	所检项目合格。	