



序号	报告编号	发布日期	结论	影像资料
111	GX-B1313/26-1-26111~26112	2026. 4. 10	本次共检电力变压器2台，2台电力变压器所检项目合格	
112	GX-B1451/26-1-26241~26245	2026. 4. 10	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格	



113	GX-B1313/26-1-26072~26075	2026. 4. 10	本次共检电力变压器4台，4台电力变压器所检项目合格		 <p>2026.3.23</p>
114	GX-B1313/26-1-26076~26080	2026. 4. 10	本次共检电力变压器5台，5台电力变压器所检项目合格		 <p>2026.3.23</p>

115	GX-B1313/26-1-26081~26083	2026. 4. 10	本次共检电力变压器3台，3台电力变压器所检项目合格		 <p>2026.3.24</p>	
116	GX-B1313/26-1-26084~26087	2026. 4. 10	本次共检电力变压器4台，4台电力变压器所检项目合格		 <p>2026.3.24</p>	

117	GX-B1380/26-1-26017	2026. 4. 10	所检项目合格	
118	GX-B1380/26-1-26018	2026. 4. 10	所检项目合格	

119	GX-B1380/26-1-26019	2026. 4. 10	所检项目合格	
120	GX-B1380/26-1-26020	2026. 4. 10	所检项目合格	

121	GX-B1380/26-1-26021	2026. 4. 10	所检项目合格		
122	GX-B1380/26-1-26022	2026. 4. 10	所检项目合格		

123	GX-B1380/26-1-26023	2026. 4. 10	所检项目合格	
124	GX-B1304/26-1-26008	2026. 4. 10	综合判定：合格	

125	GX-B1310/21-1-26131	2026. 4. 10	符合标准要求	 <p>2026/04/06</p>
126	GX-B1310/21-1-26125	2026. 4. 8	符合标准要求	 <p>2026/3/29</p>



127	GX-B1310/21-1-26126	2026. 4. 8	符合标准要求	 A worker wearing a red hard hat and safety glasses is sitting on a large, dark-colored industrial wheel. The worker is holding a blue object in their hand. The background shows a clear sky and some industrial structures. A yellow timestamp '2026/3/29' is visible in the bottom right corner of the photo.
128	GX-B1310/21-1-26127	2026. 4. 8	符合标准要求	 A worker wearing a red hard hat and safety glasses is standing next to a large, rusted metal barrel. The worker is holding a tool or object near the barrel. The background shows a yellow building and some industrial equipment. A yellow timestamp '2026/3/29' is visible in the bottom right corner of the photo.

129	GX-B1310/21-1-26128	2026. 4. 8	符合标准要求	 A worker wearing a red hard hat, safety glasses, and a brown work jacket is kneeling in a workshop. He is working on a piece of equipment that is partially covered with a blue plastic bag. A large metal hook or tool is visible on the floor next to him. A yellow date stamp '2026/3/29' is in the bottom right corner of the photo.
130	GX-B1310/21-1-26129	2026. 4. 8	符合标准要求	 A worker wearing a red hard hat, safety glasses, and a brown work jacket is standing in a workshop. He is holding a small device in his hands. The workshop floor is cluttered with various tools and equipment. A yellow date stamp '2026/3/29' is in the bottom right corner of the photo.

131	GX-B1322/26-1-26217~26222	2026. 4. 13	本次共检验电力电缆6条，6条所检项目合格	
132	GX-B1328/25-1-26063	2026. 4. 13	本次共检绝缘手套40只，40只绝缘手套合格	

133	GX-B1328/25-1-26064	2026. 4. 13	本次共检绝缘靴 30只，30只绝缘靴合格	
134	GX-B1305/26-1-26010	2026. 4. 13	综合判定：合格	

135	GX-B1305/26-1-26011	2026. 4. 13	综合判定：合格	
136	GX-B1305/26-1-26012	2026. 4. 13	综合判定：合格	



137	GX-B1310/21-1-26132	2026. 4. 7	符合标准要求	 <p>2026/3/31</p>
138	GX-B1310/21-1-26133	2026. 4. 7	符合标准要求	 <p>2026/3/31</p>



139	GX-B1310/21-1-26134	2026. 4. 7	符合标准要求	
140	GX-B1310/21-1-26148	2026. 4. 7	符合标准要求	



141	GX-B1310/21-1-26124	2026. 4. 14	符合标准要求	 <p>2026.03.01</p>
142	GX-B1309/26-1-26011	2026. 4. 14	所检项目合格	 <p>2026/03/13</p>

143	GX-B1500/26-1-26050	2026. 4. 14	综合判定：合格	
144	GX-B1500/26-1-26051	2026. 4. 14	综合判定：合格	

145	GX-B1500/26-1-26052	2026. 4. 14	综合判定：合格	
146	GX-B1303/26-1-26013	2026. 4. 17	所检项目合格	

147	GX-B1307/26-1-26019	2026. 4. 17	综合判定：合格	
148	GX-B1307/26-1-26020	2026. 4. 17	综合判定：合格	

149	GX-B1307/26-1-26021	2026. 4. 17	综合判定：合格	
150	GX-B1307/26-1-26022	2026. 4. 17	综合判定：合格	

151	GX-B1307/26-1-26023	2026. 4. 17	综合判定：合格	 <p>2026/03/20</p>
152	GX-B1307/26-1-26024	2026. 4. 17	综合判定：合格	 <p>2026/03/20</p>

153	GX-B1307/26-1-26025	2026. 4. 17	综合判定：合格	 <p>2026/03/22</p>
154	GX-B1307/26-1-26026	2026. 4. 17	综合判定：合格	 <p>2026/03/22</p>

155	GX-B1307/26-1-26027	2026. 4. 17	综合判定：合格	 <p>2026/03/22</p>
156	GX-B1303/26-1-26014	2026. 4. 17	所检项目合格	 <p>2026/03/21</p>