

序号	报告编号	发布日期	结论	影像资料
57	GX-B1329/26-5-26280~26294	2026. 4. 22	本次共检氧化锌避雷器15组，15组氧化锌避雷器所检项目合格。	 A photograph showing two workers in dark jackets and safety helmets (one black, one red) inspecting a piece of electrical equipment. A yellow timestamp '2026/4/22' is visible in the bottom right corner of the image.
58	GX-B1312/26-5-26126	2026. 4. 22	所检项目合格。	 A photograph showing a worker in a dark jacket and a red safety helmet kneeling and working on a piece of electrical equipment. The equipment has several large red cylindrical components. A yellow timestamp '2026/3/6' is visible in the bottom right corner of the image.

59	GX-B1321/26-5-26245~26251	2026. 4. 22	本次共检电力电缆 7条，7条电力电缆所检 项目合格。	 <p>2026/3/6</p>
60	GX-B1310/21-5-26122	2026. 4. 17	符合标准要求。	 <p>2026/3/14</p>

61	GX-B1310/21-5-26123	2026. 4. 17	符合标准要求。	
62	GX-B1310/21-5-26124	2026. 4. 17	符合标准要求。	

63	GX-B1310/21-5-26125	2026. 4. 17	符合标准要求。	 <p>2026/3/14 2025.10.13 13:19</p>
64	GX-B1310/21-5-26126	2026. 4. 17	符合标准要求。	 <p>2026/3/14 2025.10.13 13:19</p>

65	GX-B1310/21-5-26127	2026. 4. 17	符合标准要求。	
66	GX-B1310/21-5-26128	2026. 4. 17	符合标准要求。	

67	GX-B1310/21-5-26129	2026. 4. 17	符合标准要求。	
68	GX-B1310/21-5-26130	2026. 4. 17	符合标准要求。	

69	GX-B1310/21-5-26131	2026. 4. 17	符合标准要求。	
70	GX-B1495/25-5-26276~26296	2026. 4. 22	本次共检防爆型高压配电装置21台，21台防爆型高压配电装置所检项目合格。	

71	GX-B1304/26-5-26008	2026/4/29	综合判定:合格。	 <p>A photograph showing a worker in a red hard hat and dark jacket operating a green industrial machine. The worker is holding a document and looking at the machine. The date stamp '2026/03/19' is visible in the bottom right corner of the image.</p>
72	GX-B1304/26-5-26008	2026/4/29	综合判定:合格。	 <p>A photograph showing a worker in a red safety suit and red hard hat operating a green industrial machine. The worker is standing next to the machine, which has a large circular component. The date stamp '2026/03/20' is visible in the bottom right corner of the image.</p>