

序号	报告编号	发布日期	结论	影像资料
54	GX-B1310/21-Y-26047	2026. 4. 21	符合标准要求。	
55	GX-B1310/21-Y-26048	2026. 4. 21	符合标准要求。	

56	GX-B1310/21-Y-26049	2026. 4. 21	符合标准要求。	
57	GX-B1427/21-Y-26050	2026. 4. 21	符合标准要求。	

58	GX-B1310/21-Y-26054	2026. 4. 21	符合标准要求。	 <p>2026.3.10</p>
59	GX-B1310/21-Y-26055	2026. 4. 21	符合标准要求。	 <p>2026.3.10</p>

60	GX-B1310/21-Y-26056	2026. 4. 21	符合标准要求。	 <p>2026.3.10</p>
61	GX-B1382/26-Y-26004	2026. 4. 22	综合判定：合格。	 <p>2026.3.9</p>

62	GX-B1305/26-Y-26004	2026. 4. 20	综合判定：合格。	 <p>2026.3.10</p>
63	GX-B1451/26-Y-26057~26065	2026. 4. 22	本次共检高压开关柜9台, 9台高压开关柜所检项目合格。	 <p>2026.3.18</p>

64	GX-B1328/26-Y-26040	2026. 4. 22	本次共检携带型短路接地装置2组，2组携带型短路接地装置合格。	
65	GX-B1451/26-Y-26022~26024	2026. 4. 22	本次共检高压开关柜3台, 3台高压开关柜所检项目合格。	

66	GX-B1451/26-Y-26025~26027	2026. 4. 22	本次共检高压开关柜3台, 3台高压开关柜所检项目合格。	 <p>托里县招金北疆矿业有限公司 2026/3/7</p>
67	GX-B1451/26-Y-26028~26033	2026. 4. 22	本次共检高压开关柜6台, 6台高压开关柜所检项目合格。	 <p>托里县招金北疆矿业有限公司 2026/3/7</p>

68	GX-B1451/26-Y-26034~26040	2026. 4. 22	本次共检高压开关柜7台, 7台高压开关柜所检项目合格。	
69	GX-B1451/26-Y-26041~26047	2026. 4. 22	本次共检高压开关柜7台, 7台高压开关柜所检项目合格。	

70	GX-B1451/26-Y-26048~26049	2026. 4. 22	本次共检高压开关柜2台, 2台高压开关柜所检项目合格。	 <p>托里县招金北疆矿业有限公司 2026/3/8</p>
71	GX-B1451/26-Y-26050~26051	2026. 4. 22	本次共检高压开关柜2台, 2台高压开关柜所检项目合格。	 <p>托里县招金北疆矿业有限公司 2026/3/18</p>



72	GX-B1380/26-Y-26006	2026. 4. 22	所检项目合格。	
73	GX-B1380/26-Y-26007	2026. 4. 22	所检项目合格。	

74	GX-B1621/26-Y-26004	2026. 4. 20	所检项目合格。	
75	GX-B1621/26-Y-26005	2026. 4. 20	所检项目合格。	


76	GX-B1621/26-Y-26006	2026. 4. 20	所检项目合格。	
77	GX-B1313/26-Y-26012~26018	2026. 4. 21	本次共检电力变压器7台，7台电力变压器所检项目合格。	

78	GX-B1313/26-Y-26019~26023	2026. 4. 21	本次共检电力变压器5台，5台电力变压器所检项目合格。	
79	GX-B1313/26-Y-26024	2026. 4. 21	所检项目合格。	



80	GX-B1313/21-Y-26025	2026. 4. 21	所检项目合格。	
81	GX-B1451/26-Y-26022~26024	2026. 4. 22	本次共检高压开关柜3台, 3台高压开关柜所检项目合格。	



82	GX-B1451/26-Y-26025~26027	2026. 4. 22	本次共检高压开关柜3台, 3台高压开关柜所检项目合格。	
83	GX-B1451/26-Y-26028~26033	2026. 4. 22	本次共检高压开关柜6台, 6台高压开关柜所检项目合格。	



84	GX-B1451/26-Y-26034~26040	2026. 4. 22	本次共检高压开关柜7台, 7台高压开关柜所检项目合格。	
85	GX-B1451/26-Y-26041~26047	2026. 4. 22	本次共检高压开关柜7台, 7台高压开关柜所检项目合格。	

86	GX-B1451/26-Y-26048~26049	2026. 4. 22	本次共检高压开关柜2台, 2台高压开关柜所检项目合格。	 <p>托里县招金北疆矿业有限公司 2026/3/8</p>
87	GX-B1451/26-Y-26050~26051	2026. 4. 22	本次共检高压开关柜2台, 2台高压开关柜所检项目合格。	 <p>托里县招金北疆矿业有限公司 2026/3/8</p>



88	GX-B1305/26-Y-26006	2026. 4. 22	综合判定：合格。	 A worker in a white uniform and red helmet is operating a large industrial machine in a dark environment. The worker is wearing a safety harness and is looking at a device in their hands. The machine has a large red wheel and a blue component. The date 2026.09 is visible in the bottom right corner of the image.
89	GX-B1598/24-Y-26001	2026. 4. 21	实测钢丝绳有效截面积损失百分比最大为1.18%，小于5%为正常。	 A worker in a white uniform and red helmet is standing next to a large industrial machine. The worker is wearing a safety harness and is holding a device in their hands. The machine has a large red wheel and a blue component. The date 2026年4月18日 is visible in the bottom right corner of the image.

90	GX-B1598/24-Y-26002	2026. 4. 21	实测钢丝绳有效截面积损失百分比最大为0.88%，小于5%为正常。	
91	GX-B1598/24-Y-26003	2026. 4. 21	实测钢丝绳有效截面积损失百分比最大为1.06%，小于5%为正常。	

92	GX-B1598/24-Y-26004	2026. 4. 21	实测钢丝绳有效截面积损失百分比最大为0.92%，小于5%为正常。	
93	GX-B1598/24-Y-26005	2026. 4. 21	实测钢丝绳有效截面积损失百分比最大为0.99%，小于5%为正常。	

94	GX-B1598/24-Y-26006	2026. 4. 21	实测钢丝绳有效截面积损失百分比最大为1.28%，小于5%为正常。	 A photograph showing a close-up of a steel wire rope being inspected. The rope is dark and appears to be part of a larger mechanical system. A yellow timestamp '2026/3/12' is visible in the bottom right corner of the image.
95	GX-B1598/24-Y-26007	2026. 4. 21	实测钢丝绳有效截面积损失百分比最大为1.03%，小于5%为正常。	 A photograph showing a close-up of a steel wire rope being inspected. An orange arrow points to a specific area on the rope. A yellow timestamp '2026/3/12' is visible in the bottom right corner of the image.



96	GX-B1305/26-Y-26005	2026. 4. 22	综合判定：合格	 A photograph showing a worker in a red hard hat and grey uniform standing next to a computer workstation in an underground setting. The workstation includes a monitor, keyboard, and mouse. The worker appears to be operating the equipment. A yellow timestamp '2026/3/10' is visible in the bottom right corner of the image.
97	GX-B1313/26-Y-26033	2026. 4. 24	所检项目合格。	 A photograph showing a worker in a red hard hat and grey uniform operating a piece of industrial machinery. The worker is holding a document and looking at the equipment. The machinery is red and has various cables and hoses attached. A yellow timestamp '2026/3/10' is visible in the bottom right corner of the image.

98	GX-B1308/26-Y-26004	2026. 4. 21	综合判定：合格。	
99	GX-B1382/26-Y-26002	2026. 4. 21	合格。	

100	GX-B1382/26-Y-26003	2026. 4. 21	合格。	
101	GX-B1328/26-Y-26014	2026. 4. 21	本次共检绝缘手套 76只, 76只绝缘手套合 格。	

102	GX-B1328/26-Y-26015	2026. 4. 21	本次共检绝缘靴70只， 70只绝缘靴合格。	
103	GX-B1303/26-Y-26004	2026. 4. 27	综合判定：合格 。	

104	GX-B1308/26-Y-26005	2026. 4. 27	综合判定：合格。	 <p>内蒙古神威矿业集团有限公司 2026年4月23日</p>
105	GX-B1499/26-Y-26012	2026. 4. 27	所检项目合格。	 <p>内蒙古神威矿业集团有限公司 2026年4月23日</p>

106	GX-B1499/26-Y-26013	2026. 4. 27	所检项目合格。	
107	GX-B1499/26-Y-26014	2026. 4. 27	所检项目合格。	

108	GX-B1303/26-Y-26003	2026. 4. 27	综合判定：合格。 。	
109	GX-B1304/26-Y-26002	2026. 4. 28	综合判定：合格。	

110	GX-B1310/21-Y-26036	2026. 4. 27	符合标准要求。	
111	GX-B1310/21-Y-26037	2026. 4. 27	符合标准要求。	

112	GX-B1310/21-Y-26038	2026. 4. 27	符合标准要求。	 A worker wearing a green protective suit with a hood, a red helmet, and safety glasses is operating a piece of machinery. The worker is also wearing a safety harness. The date '2026.3.7' is visible in the bottom right corner of the photo.
113	GX-B1427/21-Y-26039	2026. 4. 27	符合标准要求。	 A worker wearing a green protective suit with a hood, a safety harness, and safety glasses is operating a piece of machinery. The date '2026.3.7' is visible in the bottom right corner of the photo.


114	GX-B1310/21-Y-26040	2026. 4. 27	符合标准要求。	
115	GX-B1310/21-Y-26041	2026. 4. 27	符合标准要求。	

116	GX-B1310/21-Y-26042	2026. 4. 27	符合标准要求。	 A photograph showing a worker in a red hard hat and blue work clothes operating a tool in a workshop. The worker is focused on the task. A date stamp '2026.3.11' is visible in the bottom right corner of the image.
117	GX-B1427/21-Y-26043	2026. 4. 27	符合标准要求。	 A photograph showing a worker in a red hard hat and blue work clothes operating a tool in a workshop. The worker is focused on the task. A date stamp '2026.3.11' is visible in the bottom right corner of the image.

118	GX-B1310/21-Y-26044	2026. 4. 27	符合标准要求。	
119	GX-B1310/21-Y-26045	2026. 4. 27	符合标准要求。	

120	GX-B1310/21-Y-26046	2026. 4. 27	符合标准要求。	
121	GX-B1310/21-Y-26051	2026. 4. 27	符合标准要求。	

122	GX-B1310/21-Y-26052	2026. 4. 27	符合标准要求。	 <p>2026.3.8</p>
123	GX-B1310/21-Y-26053	2026. 4. 27	符合标准要求。	 <p>2026.3.8</p>

124	GX-B1304/26-Y-26003	2026. 4. 29	综合判定：合格。	
125	GX-B1621/26-Y-26006	2026. 4. 21	所检项目合格。	

126	GX-B1305/26-Y-26007	2026. 4. 30	综合判定：合格	
127	GX-B1305/26-Y-26008	2026. 4. 30	综合判定：合格	

128	GX-B1322/26-Y-26029~26032	2026. 4. 30	本次共检验电力电缆4条，4条电力电缆所检项目合格。	
129	GX-B1322/26-Y-26033~26039	2026. 4. 30	本次共检验电力电缆7条，7条电力电缆所检项目合格。	

130	GX-B1322/26-Y-26040~26045	2026. 4. 30	本次共检验电力电缆6条，6条电力电缆所检项目合格。	
131	GX-B1451/26-Y-26052~26056	2026. 4. 30	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	

132	GX-B1451/26-Y-26080~26083	2026. 4. 30	本次共检高压开关设备4台,4台高压开关设备所检项目合格。	
133	GX-B1451/26-Y-26066~26079	2026. 4. 30	本次共检高压开关柜14台,14台高压开关柜所检项目合格。	

134	GX-B1303/26-Y-26005	2026. 4. 30	综合判定：合格。	
-----	---------------------	-------------	----------	---